


EcoCAT ID: 14185-38

333.95616
T323
1996
Map 38
c.1

MESILINKA RIVER

Fish Habitat and Stream Inventory

SCALE 1:20 000



SYMBOL EXPLANATION

T.R.I.M. TOPOGRAPHY:

Loose Surface - All Weather Road
Loose Surface - Winter Road
Buildings
Slide Area
Treeed Swamp
Marsh
Wooded Area
GLACIAL FEATURES:
Esker
Glacier
Contour, Index
Contour, Intermediate
Indefinite
Moraine
ELEVATION:
Index Contour
Intermediate Contour
Contour, Index
Contour, Intermediate
Depression

HYDROGRAPHY:

Water Level
Stream
Intermittent Stream
Intermittent Lake
River
Island (to scale)
Sand or Gravel Bar
Flow Direction Arrow

STREAM INVENTORY:

Back Channel
Crossing - Road or Culvert
Bank Failure
Barrier
Beaver Dam
Slide Channel
Bedrock - Confined
Island
Bedrock - Outcrop
Wetlands
Wetlands - Right Bank
Wetlands - Left Bank
Falls or Chutes (m)
Large Organic Debris Class 1
Large Organic Debris Class 2
Tributary - Right Bank
Tributary - Left Bank
Crossing
Crossing - Ford
Crossing - Bridge
Logging - Upstream Extant
Logging - Downstream Extant
Pool - Class 1
Pool - Class 2
Boulder Garden
Riffle
Braided Stream
Reach Break

WATERSHED IDENTIFIER:

VIDEO REFERENCE:

230-0259-654-453
Date: 09/09/96
Time of occurrence: 17:31
Filename-Tape #: 90000C-12
90000C-12

WETTED WIDTH (m):

WW2

STREAM DEPTH (m):

WD.1-2

SUBSTRATE:

SUB: cobble/gravel

GRADIENT - HIGH:

1 GRADE

- LOW:

1 GRADE

CONTOUR INTERVAL: 20 METRES
Elevation in Metres above Mean Sea Level

SOURCE:

BASE: TR STR SYM: INV
LOC: VDC LK SYM: N/A
HAB: VID
FISH: N/A
DATE INV: 1996/09/08 INV MGMT: MELP

BASE MAP: 94C.033

DATE: 03/31/98

GEODETIC

COMPILATION: RTR

DATUM: NAD 83

SURVEYED BY:

Province of British Columbia
Ministry of Environment, Lands and Parks

TERRA PRO
GPS SURVEYS LTD
3411 15th Avenue, S.E. P.O. Box 1001
V2N 1A1

Survey information collected through aerial reconnaissance; locations established with GPS positioning.

3D Differentiated Correction GPS accuracies do not apply to uncorrected features.

INDEX LOCATION

UTM ZONE 10

C043
94C.033
C023

