


ECOCAT ID: 14185-41

# MESILINKA RIVER

## Fish Habitat and Stream Inventory

SCALE 1:20 000



### SYMBOL EXPLANATION

T.R.I.M. TOPOGRAPHY:	STREAM INVENTORY:
Loose Surface - All Weather Road	Back Channel
Loose Surface - Winter Road	Crossing - Road or Culvert
Buildings	Bank Failure
Slide Area	Barrier
Treed Swamp	Beaver Dam
Marsh	Side Channel
Wooded Area	Bedrock - Confined
GLACIAL FEATURES:	Island
Esker	Bedrock - Outcrop
Glacier	Wetlands
Contour, Index	Wetlands - Right Bank
Contour, Intermediate	Wetlands - Left Bank
Contour, Indefinite	Falls or Chutes (m)
Moraine	Large Organic Debris Class 1
ELEVATION:	Large Organic Debris Class 2
Index Contour	Tributary - Right Bank
Intermediate Contour	Tributary - Left Bank
Contour, Index	Crossing
Contour, Intermediate	Crossing - Ford
Depression	Crossing - Bridge
HYDROGRAPHY:	Logging - Upstream
Water Level	Logging - Downstream
Lake	Pool - Class 1
Stream	Pool - Class 2
Intermittent Stream	Boulder Garden
Intermittent Lake	Rifle
River	Braided Stream
Island (to scale)	Reach Break
Sand or Gravel Bar	
Flow Direction Arrow	

### WATERSHED IDENTIFIER:

### VIDEO REFERENCE:

WETTED WIDTH (m):  
STREAM DEPTH (m):  
SUBSTRATE:  
GRADIENT - HIGH:  
- LOW:

230-6259-554-463  
Date: 1998/09/08  
Time of occurrence: 12:00  
Filename: Tape 8  
WV2  
WD 1-2  
SUB: cobble/gravel  
1 GRADE  
1 GRADE

CONTOUR INTERVAL 20 METRES  
Elevation in Metres above Mean Sea Level

### SOURCE:

BASE: TR	STR SYM: INV
LOC: VDC	LK SYM: N/A
HAB: VID	
FISH: N/A	
DATE INV: 1998/09/08	INV MGMT: MELP

BASE MAP: 94C.036  
DATUM: NAD 83

DATE: 03/31/98  
COMPILED BY: BJS

SURVEYED BY:



Ministry of Environment, Lands and Parks

Survey information collected through aerial reconnaissance; locations established with GPS positioning. 3D Differential Correction (GPS accuracies do not apply to uncorrected features)

INDEX LOCATION UTM ZONE 10

