



125° 36' 00" 55° 42' 00" 55° 36' 00" 125° 24' 00"

ECOCAT ID 14185-9

SILVER LAKE

Fish Habitat and Stream Inventory

SCALE 1:20 000

SYMBOL EXPLANATION

T.R.I.M. TOPOGRAPHY:	STREAM INVENTORY:
Roads	GPS Flight Line
Buildings	Back Channel Left Right
Slide Area	Culvert
Treed Swamp	Slumping Bank Start
Marsh	Slumping Bank End
Wooded Area	Slumping Bank Left
	Slumping Bank Right
	Barrier, Probable
	Beaver Dam
	Side Channel
	Side Channel Start
	Side Channel End
	Bedrock - Confined
	Bedrock - Confined Start
	Bedrock - Confined End
	Island Vegetated
	Bedrock - Outcrops
	Wetlands
	Wetlands - Right Bank
	Wetlands - Left Bank
	Falls Class 1
	Falls Class 2
	Cascades
	Chutes
	Tributary - Left Bank
	Tributary - Right Bank
	Crossing - Bridge
	Crossing - Ford
	Pool - Class 1
	Pool - Class 2
	Pool - Class 3
	Boulder Garden
	Gravel Bar
	Riffle
	Riffle Start
	Riffle End
	Branded Stream
	Reach Break
	Logging
	Upstream Extent
	Downstream Extent
	Left Bank Right Bank

As an attempt to reduce clutter, Large Organic Debris features (X) (O) (S) were left off the maps. These features still remain in the digital file and database.

WATERBODY IDENTIFIER:

VIDEO REFERENCE:

AREA OF DRAINAGE:

ROAD PRESENT (not in TRIM):

ROAD LEFT BANK, RIGHT BANK:

KILOMETER MARKER:

CONTOUR INTERVAL 20 METRES
Elevation in Metres above Mean Sea Level

SOURCE:

BASE: TR	STR SYM: INV
LOC: VDC	LK SYM: N/A
HAB: VID	
FISH: N/A	
DATE INV: Summer '97	INV MGNT: OTH

BASE MAP: 093N.063 DATE: 02/06/98

GEODETTIC DATUM: NAD 83 COMPILATION: RTR SURVEYED BY:



Survey information collected through aerial reconnaissance, locations established with GPS positioning. 3D Differential Correction GPS accuracies do not apply to uncorrected features.

INDEX LOCATION UTM ZONE 10

NO73

93N.063

NO53

North Arrow