

Appendix B

Field Assessment Results and Photographs

Lambly Creek Watershed Stream Crossing Hazard Rating (SCHR) Summary																										
Sites Surveyed				Running Surface				Ditch														Anthropogenic Source Presence (1) Absent (0)			Photos	
Xing ID	Structure				Left Side		Right Side			Right Front		Right Back		Left Front		Left Back		Road Score	Ditch Score	Combined Score	** Risk	Industrial Cattle Recreation				
	Type	Size	Erodability	Road use	Erosion Potential	Delivery Potential	Erosion Potential	Delivery Potential	Ditch Substrate	Erosion Potential	Delivery Potential															
1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
2	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
3	4	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	1	1	0	P9090100 - P9090110	
4	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
5	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
6	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
7	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
8	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
9	5	400	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	0	1	0		
10	5	500	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				P9090111 - P9090112	
11	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low					
12	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low					
13	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				IMGP2224P1 - IMGP2225P2	
14	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				IMGP2226P3	
15	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				IMGP2227P4	
16	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
17	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
18	5	1300	0.9	1	0.6	0.98	0.6	0.9	0.9	0	0.8	0.6	0.8	0	0.8	0.6	0.8	1.1	1.0	0.3	Low	1	0	0	IMGP2242P19 - IMGP223P20	
19	5	600	0.9	1	0.6	0.9	0.6	0.9	0.9	0.6	0.8	0	0.8	0.6	0.8	0.6	0.8	1.0	1.4	0.4	Low	0	1	0	IMGP2239P16 - IMGP2241P18	
20	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low					
21	5	500	0.95	0.92	0.6	0.85	0.7	0.9	0.9	0	0.9	0	0.85	0	0.9	0.6	0.9	1.1	0.5	0.3	Low	1	1	0	P9080212 - P9080229	
22	3	1.4 x 3	0.85	0.92	0	1	0	1	0.8	0	1	0	1	0	1	0	1	0.0	0.0	0.0	Very Low	0	0	0	IMGP2247P24 - IMGP2257P34	
23	7	-	0.8	0.9	0	1	0	1	0.8	0	1	0	1	0	1	0	1	0.0	0.0	0.0	Very Low	0	1	0	IMGP2246P23	
24	7	-	0.8	0.9	0	1	0	1	0.8	0	1	0	1	0	1	0	1	0.0	0.0	0.0	Very Low	0	1	0	IMGP2244P21 - IMGP2245P22	
25	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	0	0	0	IMGP2228P5	
26	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	0	0	0		
27	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
28	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
29	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
30	8		0.9	1	0.7	0.8	0.6	0.8	0.9	0.6	0.8	0.6	0.8	0	0.8	0.6	0.8	1.0	1.4	0.4	Low	0	1	0	IMGP2236P13 - IMGP2238P15	
31	5	1500	0.9	1	0.6	0.9	0.6	0.9	0.9	0.6	0.8	0.6	0.8	0.6	0.8	0.6	0.8	1.0	1.9	0.5	Low to Moderate	1	0	0	IMGP2234P11 - IMGP2235P12	
32	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
33	5	1000	0.95	1	0.7	0.9	0.6	0.9	0.9	0	0.85	0	0.85	0	0.85	0	0.85	1.1	0.0	0.2	Very Low	1	1	1	P9090066 - P9090076	
34	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low					
35	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low					
36	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low					
37	7	-	0.85	0.9	0	1	0.6	1	0.9	0	0.85	0	0.85	0	0.85	0	0.85	0.5	0.0	0.1	Very Low	1	1	0	P9080199 - P9080211	
38	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low					
39	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				IMGP2229P6	
40	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low					
41	5	900	0.85	0.93	0.6	0.8	0.6	0.8	0.9	0	0.8	0	0.8	0	0.8	0	0.8	0.9	0.0	0.1	Very Low	0	1	0	IMGP2230P7 - IMGP2233P10	

Lambly Creek Watershed Stream Crossing Hazard Rating (SCHR) Summary Cont'd.																										
Sites Surveyed				Running Surface				Ditch														Anthropogenic Source Presence (1) Absent (0)			Photos	
Xing ID	Structure				Left Side		Right Side			Right Front		Right Back		Left Front		Left Back		Road Score	Ditch Score	Combined Score	** Risk	Industrial	Cattle	Recreation		
	Type	Size	Erodability	Road use	Erosion Potential	Delivery Potential	Erosion Potential	Delivery Potential	Ditch Substrate	Erosion Potential	Delivery Potential					Very Low	1	1	0							
42	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
43	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
44	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
45	7	0.85	0.85	0	0.9	0	0.9	0.9	0	0.85	0	0.85	0	0.85	0	0.85	0.0	0.0	Very Low	1	1	0	P9080179 - P9080186			
46	5	400	0.9	0.95	0.6	0	0.6	1	0.9	0.7	0.9	0.8	1	0.6	0.9	0.6	0	0.5	1.9	0.4	Low	1	1	0	P9080148 - P9080160	
47	5	800	0.9	0.9	0.6	0.9	0.6	0.9	0.9	0	0.85	0.6	0.9	0	0.85	0.6	0.9	1.0	1.1	0.3	Low	1	1	0	P9080246 - P9080258	
48	5	500	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	Very Low	0	1	0	P9080230 - P9080237			
49	5	500	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	Very Low	0	1	0	P9080238 - P9080245			
50	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
51	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
52	5	500	0.9	0.95	0.6	1	0.6	1	0.9	0	0.85	0.6	0.9	0	0.85	0	0.9	1.1	0.5	0.3	Low	1	1	0	P9080134 - P9080147	
53	5	800	0.9	0.95	0.7	1	0.6	1	0.9	0.6	0.9	0	0.85	0.6	0.9	0	0.85	1.2	1.0	0.4	Low	1	1	0	P9080161 - P9080178	
54	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
55	5	900	0.9	1	0.6	0	0.6	0.9	0.9	0	0.85	0.6	0.9	0	0.9	0.6	0	0.5	0.5	0.2	Very Low	1	0	0	P9090127 - P9090144	
56	5	500	0.9	1	0.6	0.9	0.6	0.9	0.95	0.7	0.9	0.6	0.9	0.7	0.9	0	0.85	1.0	1.8	0.5	Low to Moderate	1	0	0	P9090145 - P9090154	
57	4	-	0.9	0.8	0.6	0.8	0.6	0.8	0.9	0.6	0	0.6	0	0.6	0	0.6	0	0.8	0.0	0.1	Very Low	-	-	-		
58	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low						
59	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
60	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
61	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
62	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
63	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
64	5	600	0.9	0.8	0.6	0.8	0.6	0.8	0.9	0.6	0	0.6	0	0.6	0	0.6	0	0.8	0.0	0.1	Very Low					
65	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
66	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
67	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
68	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
69	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
70	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
71	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
72	7	-	0.9	0.8	0.6	0.8	0.6	0.8	0.9	0.6	0	0.6	0	0.6	0	0.6	0	0.8	0.0	0.1	Very Low	-	-	-		
73	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
74	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
75	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
76	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
77	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
78	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
79	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
80	4	-	0.85	0.8	0.6	0.8	0.6	0.8	0.9	0.6	0	0.6	0	0.6	0	0.6	0	0.8	0.0	0.1	Very Low	-	-	-		
81	5	400	0.9	0.95	0.6	0.8	0.6	0.8	0.9	0	0.8	0	0.8	0	0.8</td											

Lambly Creek Watershed Stream Crossing Hazard Rating (SCHR) Summary Cont'd.																									
Sites Surveyed				Running Surface				Ditch														Anthropogenic Source Presence (1) Absent (0)			Photos
Xing ID	Structure				Left Side		Right Side			Right Front		Right Back		Left Front		Left Back		Road Score	Ditch Score	Combined Score	** Risk	Industrial	Cattle	Recreation	
	Type	Size	Erodability	Road use	Erosion Potential	Delivery Potential	Erosion Potential	Delivery Potential	Ditch Substrate	Erosion Potential	Delivery Potential					IMGP2238P15 - IMGP2239P16									
83	7	-	0.85	0.95	0.6	0.8	0.6	0.8	0.9	0	0.8	0	0.8	0	0.8	0	0.8	0.9	0.0	0.1	Very Low	-	-	-	-
84	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
85	5	800/600	0.9	0.95	0.6	0.8	0.6	0.8	0.9	0	0.8	0	0.8	0	0.8	0	0.8	0.9	0.0	0.1	Very Low	0	0	0	IMGP2238P15 - IMGP2239P16
86	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
87	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
88	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
89	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
90	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
91	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
92	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
93	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
94	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
95	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
96	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
97	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
98	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
99	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
100	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
101	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
102	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
103	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
104	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
105	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
106	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
107	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	-	-	-	-
108	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	-	-	-	-
109	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	-	-	-	-
110	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
111	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
112	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	-	-	-	-
113	5	1200	0.92	0.92	0.6	0.9	0.7	0.9	0.9	0.6	0.9	0.7	0.9	0.6	0.9	0.7	0.9	1.1	2.3	0.6	Low to Moderate	1	1	0	P9080259 - P9080276
114	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
115	5	1200	0.9	0.92	0.6	0.85	0.6	0.85	0.9	0	0.85	0	0.9	0	0.85	0	0.9	0.9	0.0	0.2	Very Low	1	1	0	P9080278 - P9080286
116	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	-	-	-	IMGP2240P17
117	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	-	-	-	-
118	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
119	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	0	0	0	IMGP2241P18 - IMGP2242P19
120	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	-	-	-	-
121	5	600	0.9	0.93	0.6	0.85	0.6	0.9	0.85	0.6	0.85	0	0.85	0.6	0.85	0.6	0.85	1.0	1.5	0.4	Low	0	1	0	IMGP2233P10 - IMGP2234P11
122	5	400	0.9	0.93	0.6	0.85	0.6	0.9	0.85	0.6	0.85	0.6	0.85	0	0.85	1.0	1.5	0.4	Low	0	1	0	IMGP2279P8 - IMGP2280P9		
123	5	600	0.9	0.93	0.6	0.85	0.6	0.9	0.85	0.6	0.85	0.6	0.85	0	0.85	0.6	0.85	1.0	1.5	0.4					

Lambly Creek Watershed Stream Crossing Hazard Rating (SCHR) Summary Cont'd.																									
Sites Surveyed				Running Surface				Ditch														Anthropogenic Source Presence (1) Absent (0)			Photos
Xing ID	Structure				Left Side		Right Side			Right Front		Right Back		Left Front		Left Back		Road Score	Ditch Score	Combined Score	** Risk	Industrial	Cattle	Recreation	
	Type	Size	Erodability	Road use	Erosion Potential	Delivery Potential	Erosion Potential	Delivery Potential	Ditch Substrate	Erosion Potential	Delivery Potential					Low to Moderate	1	1	0						
124	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
125	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
126	5	1000	0.9	1	0.6	0.9	0.8	1	0.9	0.7	1	0.7	0.85	0.8	0.9	0.6	0	1.3	1.9	0.5	Low to Moderate	1	1	0	P9080102 - P9080116
127	5	600	0.9	1	0.6	0	0.7	1	0.9	0	0.85	0.6	1	0	0	0.6	0	0.6	0.6	0.2	Low	1	1	0	P9080082 - P9080101
128	5	900	0.9	1	0.6	0.9	0.6	0.9	0.9	0.6	1	0.6	1	0.6	0.85	0.6	0	1.0	1.7	0.4	Low to Moderate	1	1	0	P9080065 - P9080081
129	5	400	0.9	1	0.6	0	0.8	1	0.9	0.6	0.85	0.7	1	0.6	0	0.6	0	0.7	1.2	0.3	Low	1	1	0	P9080047 - P9080064
130	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				
131	5	1200	0.9	0.93	0.6	0.8	0.6	0.8	0.9	0	0.9	0	0.9	0	0.9	0.9	0.0	0.9	0.0	0.1	Very Low				IMGP2253P30 - IMGP2254P31
132	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				
133	5	400	0.9	0.93	0.6	0.9	0.6	0.9	0.85	0.6	0.8	0.6	0.9	0.6	0.8	0	0.9	1.0	1.4	0.4	Low	0	1	0	IMGP2255P32 - IMGP2257P34
134	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
135	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				
136	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				IMGP2243P20
137	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				
138	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				
139	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
140	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
141	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
142	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
143	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
144	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
145	7		0.9	0.85	0.7	1	0.6	1	0.85	0	0.85	0	0.9	0	0.85	0	0.9	1.2	0.0	0.2	Very Low	1	0	0	P9090155 - P9090162
146	5	1000	0.9	0.9	0.6	0.85	0.6	0.85	0.9	0	0.85	0	0.9	0	0.85	0	0.9	0.9	0.0	0.2	Very Low	1	1	0	P9090163 - P9090171
147	5	900	0.9	0.85	0.6	1	0.6	1	0.85	0	0.85	0	0.85	0	0.85	0	0.85	1.1	0.0	0.2	Very Low	1	1	0	P9090172 - P9090180
148	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				
149	5	400	0.9	0.93	0.6	0.8	0.6	0.8	0.85	0.6	0.8	0.6	0.8	0.6	0.8	0	0.8	0.9	1.4	0.4	Low	0	0	0	
150	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				
151	5	400	0.9	0.93	0.6	0.9	0.6	0.9	0.85	0.6	0.85	0.6	0.8	0	0.8	0.6	0.8	1.0	1.4	0.4	Low	0	1	0	IMGP2248P25 - IMGP2249P26
152	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				IMGP2246P23 - IMGP2247P24
153	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
154	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
155	5	800	0.9	0.9	0.6	0.9	0.6	0.9	0.85	0.6	0.8	0.6	0.8	0.6	0.8	1.0	1.8	0.5	Low to Moderate	1	1	1	-		
156	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				
157	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				IMGP2261P38
158																									
159	5	1200	0.9	0.93	0.6	0.9	0.6	0.9	0.9	0.7	0.9	0.7	0.9	0.6	0.8	0.6	0.8	1.0	2.2	0.5	Low to Moderate	0	1	0	
160	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				IMGP2260P37
161	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	

Lambly Creek Watershed Stream Crossing Hazard Rating (SCHR) Summary Cont'd.																									
Sites Surveyed				Running Surface				Ditch														Anthropogenic Source Presence (1) Absent (0)			Photos
Xing ID	Structure				Left Side		Right Side			Right Front		Right Back		Left Front		Left Back		Road Score	Ditch Score	Combined Score	** Risk	Industrial	Cattle	Recreation	
	Type	Size	Erodability	Road use	Erosion Potential	Delivery Potential	Erosion Potential	Delivery Potential	Ditch Substrate	Erosion Potential	Delivery Potential					Low	Very Low	Low	Very Low						
162	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
163	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
164	5	1200	0.9	0.95	0.6	0.9	0.7	0.9	0.9	0.6	0.9	0	0.85	0	0.9	0	0	1.1	0.5	0.3	Low	1	1	0	P9030531 - P9030546
165	5	600	0.9	0.95	0.6	0.9	0.6	0.9	0.9	0	0.85	0	0.9	0	0.85	0	0.9	1.0	0.0	0.2	Very Low	1	1	0	P9030547 - P9030556
166	5	800	0.9	0.95	0.6	0.85	0.6	0.85	0.9	0	0.85	0	0.9	0	0.85	0	0.9	0.9	0.0	0.2	Very Low	1	1	0	P9030619 and P9030621/22
167	5	?	0.9	0.92	0.6	0.85	0.6	0.85	0.9	0	0.85	0.7	1	0	0.85	0.6	1	0.9	1.3	0.4	Low	1	0	0	P9030620
168	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
169	5	500	0.9	0.95	0.6	0.85	0.6	0.85	0.9	0	0.85	0	0.85	0	0.85	0	0.85	0.9	0.0	0.2	Very Low	1	1	0	P9030610 - P9030616
170	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
171	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
172	5	400	0.9	0.95	0.6	0.85	0.6	0.85	0.9	0	0.9	0	0.9	0	0.85	0.8	1	0.9	0.8	0.3	Low	1	0	0	P9030603 - P9030607
173	5	400	0.9	0.95	0.6	0.85	0.6	0.85	0.9	0	0.85	0	0.9	0	0.85	0	0.9	0.9	0.0	0.2	Very Low	1	1	0	P9030596 - P9030601
174	5	800	0.9	0.95	0.6	0.9	0.6	0.9	0.9	0	0.85	0.6	0.9	0	0.85	0	0.9	1.0	0.5	0.3	Low	1	1	0	P9030588 - P9030594
175	5	800	0.9	0.95	0.6	1	0.6	0.9	0.9	0	0.85	0.6	0.85	0.6	0.85	0.6	0.9	1.1	1.6	0.4	Low to Moderate	1	1	0	P9030579 - P9030586
176	5	800	0.9	0.95	0.6	0.9	0.6	0.85	0.9	0	0.85	0	0.85	0	0.85	0	0.85	1.0	0.0	0.2	Very Low	1	1	0	P9030574 - P9030578
177	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				
178	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
179	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
180	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
181	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
182	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
183	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
184	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
185	5	300	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	1	1	0	
186	5	600	0.85	0.9	0.6	0.8	0.6	0.8	0.85	0	0.8	0.6	0.8	0.6	0.8	0.6	0.8	0.8	1.4	0.4	Low	0	0	0	IMGP2258P35 - IMGP2258P36
187	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low			-	
188	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low			-	
189	4		0.9	0.85	0	0.85	0	0.85	0.9	0	0.85	0	0.85	0	0.85	0	0.85	0.0	0.0	0.0	Very Low	1	0	0	P9030495 - P9030504
190	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
191	4		0.9	0.85	0	0.85	0	0.85	0.9	0	0.85	0	0.85	0	0.85	0	0.85	0.0	0.0	0.0	Very Low	1	0	0	P903484 - P903494
192	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	-	-	-	
193	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
194	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
195	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
196	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
197	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
198	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
199	5	1200	0.9	0.92	0.7	0.9	0.7	0	0.9	0	0.9	0	0.9	0	0.9	0	0.9	0.6	0.0	0.1	Very Low	1	1	0	P9030512 - P9030530
20																									

Lambly Creek Watershed Stream Crossing Hazard Rating (SCHR) Summary Cont'd.																									
Sites Surveyed				Running Surface				Ditch														Anthropogenic Source Presence (1) Absent (0)			Photos
Xing ID	Structure				Left Side		Right Side			Right Front		Right Back		Left Front		Left Back		Road Score	Ditch Score	Combined Score	** Risk	Industrial	Cattle	Recreation	
	Type	Size	Erodability	Road use	Erosion Potential	Delivery Potential	Erosion Potential	Delivery Potential	Ditch Substrate	Erosion Potential	Delivery Potential					Low to Moderate	1	1	0						
203	5	600	0.9	0.95	0.7	0.85	0.7	0.85	0.9	0	0.9	0.6	0.9	0	0.9	0.6	0.9	1.1	1.1	0.4	Low	1	1	0	P9030505 - P9030507
204	5	400	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	1	1	0	P9030403 - P9030405
205	5	1100	0.9	0.95	0.6	0.8	0.6	0.8	0.85	0.6	0.8	0.6	0.8	0.6	0.8	0.6	0.8	0.9	1.8	0.5	Low to Moderate	1	1	0	IMGP2266P43 - IMGP2268P45
206	5	600	0.85	0.95	0.6	0.8	0.6	0.8	0.85	0.6	0.8	0.6	0.8	0	0.8	0.6	0.8	0.9	1.4	0.4	Low	0	1	0	IMGP2269P46 - IMGP2270P47
207	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
208	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
209	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
210	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
211	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
212	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
213	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
214	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
215	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
216	7	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	-	-	-	-
217	7	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	-	-	-	-
218	5	1500	0.9	0.95	0.6	0.9	0.6	0.85	0.9	0.6	0.85	0.7	1	0	0.85	0	0	1.0	1.2	0.4	Low	1	1	0	P9030463 - P9030482
219	5	1500/1200	0.9	0.95	0.6	0.9	0.6	0.9	0.9	0.7	0.9	0.6	0.85	0.6	0.9	0.7	1	1.0	2.3	0.6	Low to Moderate	1	1	0	P9030376- P9030394
220	5/CPP	400/600	0.9	0.98	0.6	0.8	0.6	0.8	0.85	0	0.8	0	0.8	0	0.8	0	0.8	0.9	0.0	0.2	Very Low	0	0	0	IMGP2224P1 - IMGP2225P2
221	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
222	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
223	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
224	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
225	5	800	0.9	1	0.6	0.85	0.6	0.85	0.9	0	0.85	0.6	0.85	0	0.85	0.6	0.9	1.0	1.1	0.3	Low	1	1	0	P9050098 - P9050111
226																									
227	5	900	0.9	1	0.6	0.9	0.6	0.9	0.9	0	0.8	0.7	0.9	0	0.85	0.7	0.9	1.0	1.3	0.4	Low	1	1	0	P9050087 - P9050097
228	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	-	-	-	-
229	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	-	-	-	-
230	5	2400	0.9	1	0.6	0	0.6	1	0.9	0.8	1	0.7	0.9	0.6	0	0.6	0	0.5	1.4	0.3	Low	1	1	0	P9080001 - P9080038
231	5	400	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	-	-	-	P9080039 - P9080046
232	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
233	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
234	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
235	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
236	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
237	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
238	7	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	-	-	-	-
239	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low	-	-	-	-
240	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
241	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
242	7		0.9	0.92	0.6	1	0.6</td																		

Lambly Creek Watershed Stream Crossing Hazard Rating (SCHR) Summary Cont'd.

Lambly Creek Watershed Stream Crossing Hazard Rating (SCHR) Summary Cont'd.																											
Sites Surveyed				Running Surface				Ditch												Anthropogenic Source Presence (1) Absent (0)			Photos				
Xing ID	Structure				Left Side		Right Side			Right Front		Right Back		Left Front		Left Back		Road Score	Ditch Score	Combined Score	** Risk	Industrial	Cattle	Recreation			
	Type	Size	Erodability	Road use	Erosion Potential	Delivery Potential	Erosion Potential	Delivery Potential	Ditch Substrate	Erosion Potential	Delivery Potential					Very Low	Low	Very Low									
283	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
284	2		0.9	0.92	0.6	0.9	0.6	0.9	0.9	0	0.85	0	0.85	0	0.85	0	0.85	1.0	0.0	0.2	Very Low	1	0	0	P9090194 - P9090204		
285	5	900	0.85	0.9	0	0.85	0	0.85	0.9	0	0.85	0	0.85	0	0.85	0	0.85	0.0	0.0	0.0	Very Low	1	1	0	P9090205 - P9090211		
286	5	-	0.9	1	0.6	0.85	0.6	0.85	0.9	0	0.85	0.6	0.85	0	0.85	0.6	0.85	1.0	1.0	0.3	Low	1	1	0	-		
287	7		0.85	0.9	0.6	0.9	0.6	0.9	0.9	0	0.85	0	0.85	0	0.85	0	0.85	1.0	0.0	0.2	Very Low	1	1	1	P9090212 - P909029		
288	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low			-	-		
289	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
290	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
291	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
292	7		0.9	0.92	0.6	1	0.6	1	0.9	0	0.85	0	0	0	0.85	0	0.9	1.1	0.0	0.2	Very Low	1	0	1	P9050129 - P9050136		
293	7	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low			-	-		
294	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
295	5	400	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				P9050111 - P9050112		
296	5	1600	0.9	1	0.6	0	0.6	0.85	0.9	0.6	0.9	0.6	0.9	0.6	0.9	0	0	0.6	0	0.5	1.0	0.2	Low	1	0	0	P9050113 - P9050128
297	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
298	7		0.9	0.9	0	1	0	1	0.9	0	0.82	0	0.85	0	0.5	0	0.85	0.0	0.0	0.0	Very Low	1	1	1	P9090222 - P9090226		
299	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
300	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
301	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
302	5	400	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				P9090220 - P9090221		
303	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
304	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
305	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low				-			
306	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
307	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
308	5	600	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low			-	-		
309	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0.0	0.0	0.0	Very Low			-	-		
310	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
311	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
312	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
313	5	??	0.9	1	0.7	0.85	0.7	0.85	0.9	0.7	0.9	0.7	0	0.6	0.8	0.7	0.8	1.1	1.6	0.5	Low to Moderate	1	1	1	-		
314	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	Very Low	-	-	-	-		
315	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	Very Low	-	-	-	-		
316	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	Very Low	-	-	-	-		
317	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	Very Low	-	-	-	-		
318	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	Very Low	-	-	-	-		
319	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	Very Low	-	-	-	-		
320	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	Very Low	-	-	-	-		
321	5	900	0.85	1	0.6	0.9	0.6	0.9	0.85	0.6	0.9	0	0.9	0.6	0.9	0	0.9	1.0	1.0	0.3	Low	1	0	0	P9030411 - P9030426		
322	5	800	0.9	0.95	0.6	0.9	0.6	0.9	0.9	0	0.85	0	0.85	0	0.85	0	0.85	1.0	0.0	0.2	Very Low	1	1	1	P9030557 - P9030561		
323	8	-	0.85	0.8	0.																						

Sites Surveyed				Running Surface				Ditch												Anthropogenic Source Presence (1) Absent (0)			Photos		
Xing ID	Structure			Left Side		Right Side			Right Front		Right Back		Left Front		Left Back		Road Score	Ditch Score	Combined Score	** Risk				Photos	
	Type	Size	Erodability	Road use	Erosion Potential	Delivery Potential	Erosion Potential	Delivery Potential	Ditch Substrate	Erosion Potential	Delivery Potential	Erosion Potential	Delivery Potential	Erosion Potential	Delivery Potential	Industrial	Cattle	Recreation							
324	7	-	0.85	0.85	0	0.85	0	0.85	0.9	0.7	1	0	0.85	0.7	1	0	0.85	0.0	1.3	0.2	Low	0	1	0	P9080187 - P9080198
325	5	900 (600)	0.9	1	0.6	0	0.6	0.9	0.9	0.7	0.9	0.6	0	0	0.9	0.6	0.9	0.5	1.1	0.3	Low	1	0	0	P90901113 - P9090125

** Risk interpreted relative to sediment delivery to a stream, real, occurring at time of site visit, or potential

0.0 to 0.2	-	Very Low Risk
0.21 to 0.4	-	Low Risk
0.41 to 0.6	-	Low to Moderate Risk
0.61 to 0.79	-	Moderate Risk
0.8 to 0.9	-	High Risk
0.91 +	-	Vey High Risk



Photo 1 – Cattle trampling at Site 267



Photo 2 – Recreational crossing u/s site 313



Photo 3 – Road run-off near Site 313



Photo 4 – Road fill erosion near Site 252



Photo 5 – Road run-off near Site 230



Photo 6 – dust layer at Site 230



Photo 7 – Cattle at Site B4 Tributary



Photo 8 – Rec/Cattle activity at Bighorn



Photo 9 – Log culvert at Site 203



Photo 10 – Diversion ditch to Tadpole



Photo 11 – Ditch to Tadpole, Site 166



Photo 12 – North Fork Creek, Site 19



Photo 13 – Tadpole cattle/rec use



Photo 14 – Diversion ditch at Tadpole



Photo 15 – Deactivation at Site 287



Photo 16 – Traffic dust from p/u truck



Photo 17 – Sumps at Site 313



Photo 18 – Steep fill/erosion on Bear Main