

# **APPENDIX B**

## **PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF THE ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
1	Effects of Wolverine Mine Project on Guide/Outfitting Territory 721P998 Licence of Occupation 813324 dated 27 June 2001.	Guide/Outfitter	Ongoing discussions with both the guide outfitter and Dale Drown (General Manager of Guide Outfitter Association of BC) since February 2004. Mr. Drown is acting as the guide outfitters representative. WWC received a formal claim from Mr. Drown and is in the process of negotiating a settlement. A counter offer and refinement to this offer were made by WCC on November 12 and 24 respectively. WCC anticipates a settlement by December 15, 2004.	Negotiation on-going	MWLAP
2	Effects of coal dust on wildlife.	Guide/Outfitter	Wildlife Working Group has researched this issue - University of Saskatoon, Professor of Veterinary Medicine and independent consultant Veterinarian opinion says likely not an issue.	Response satisfactory. Issue addressed. Details at permitting	MWLAP
3	Loss of caribou habitat in the EB pit area.	Guide/Outfitter	Further data needed. Low use of EB pit area by caribou. WCC will participate in ongoing studies, with 8 year available for management planning prior to EB development.	On-going commitment to caribou studies and adaptive management approach acceptable for certificate level decision.	MWLAP, MoF
4	Effects of noise (blasting/drilling) on wildlife.	Guide/Outfitter	Short term effect. Wildlife is expected to habituate to daily blasting.	Response satisfactory. Issue addressed.	MWLAP
5	Effect of Wolverine Mine Project on Terry Ranch wetland and waterfowl.	Guide/Outfitter	Wetlands on the east side of the BC Rail railway line should remain undisturbed and will be monitored for any changes largely resulting from groundwater flow. Plans outlined in Additional Information Report.	Response satisfactory. Issue addressed. Monitoring details at permitting.	MWLAP
6	Siting of power line along Wolverine FSR	BC Hydro	BC Hydro to construct 25 kV power line along Wolverine FSR and along Perry Creek Road to Explosives Storage	Response satisfactory.	MoF

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
	and portion of Perry Creek Road.		site.	Issue addressed. Details at permitting.	
7	Loss of timber from power line right of way in TFL 48 <i>Originally raised: Additional Information Report Item - Table 10.7-1. Potential to reduce loss by revegetating with trees.</i>	MoF; Canfor for in public meeting	Loss is likely temporary. Power line will likely be removed at closure. Canfor set the minimum clearance from the Wolverine FSR to ensure sufficient room for snow removal and potential for future upgrading of the road. Canfor requested consideration & reforestation practices to reduce lost productivity.	Response satisfactory. Issue addressed. Details at permitting.	MoF
8	Loss of timber from mine site in TFL 48. <i>Originally raised: Additional Information Report Item - Table 10.7-1 of Additional Information Report</i>	MoF	Reclamation objectives will include creating a post mine landscape with similar forest capabilities as existed pre mine - with the exception of pit areas where this will not be possible.	Response satisfactory. Issue addressed. Details at permitting.	MEM
9	Snow removal. <i>Originally raised: Additional Information Report Item - Table 10.7-1 of Additional Information Report</i>	MoF	Issue has been addressed through power line alignment / design and ensuring adequate row width.	Details at permitting.	MoF
10	Joint use of Perry Creek Road.	MoF	WCC has agreed to pay the cost of the Perry Creek Road realignment and to maintain public/industrial use access during the road realignment, mining and reclamation phases of the project.	Response satisfactory. Issue addressed. Details at permitting.	MoF, MEM
11	Joint use of Wolverine FSR.	MoF	WCC has signed Road Use Agreement with Canfor.	Response satisfactory. Issue addressed.	MoF

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
12	Traffic management.	MoF	WCC has committed to traffic management planning for both roads. Standard radio-controlled FSR procedures will remain in effect on the Wolverine FSR.	Response satisfactory. Issue addressed. Plan to be developed prior to construction.	MoF
13	Relocation of section of Wolverine FSR. <i>Originally raised: Additional Information Report Item - Table 10.7-6 of Additional Information Report</i>	MoF	Canfor has indicated agreement in principle to realignment of Wolverine FSR provided the realigned road provides year round access.	Response satisfactory. Issue addressed. Permitting Issue	MoF
14	Relocation of section of Wolverine FSR. <i>Originally raised: Additional Information Report Item - Table 10.7-6 of Additional Information Report</i>	BC Rail/CN Rail	BC Rail/CN Rail has indicated agreement in principle to realignment of Wolverine FSR.	Response satisfactory. Issue addressed. Final plans to be approved and right of ways defined. Details at permitting.	LWBC, MoF
15	Service road along railway. <i>Originally raised: Additional Information Report Item - Table 10.7-6 of Additional Information Report</i>	BC Rail/CN Rail	Incorporated into design of realignment. Preliminary design underway.	Final plans to be approved and right of ways defined at permitting.	LWBC
16	Turnaround located in Plantsite area. <i>Originally raised: Additional Information Report Item - Table 10.7-6 of Additional Information Report</i>	BC Rail/CN Rail	BC Rail have agreed to removal of turnaround.	Response satisfactory. Issue addressed. Details at permitting.	LWBC

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
17	Sale of surplus rail right of way lands to WCC.	BC Rail/CN Rail	Agreement was given in principle. Negotiations are in progress. Letter sent to BCR Properties Ltd. on 15 September 2004.	Negotiations on-going. Details at permitting.	LWBC
18	Rail load out structure clearance and modification of main track alignment. <i>Originally raised: Additional Information Report Item - Table 10.7-6 of Additional Information Report</i>	BC Rail/CN Rail	BC Rail agreed to modifications.	Response satisfactory. Issue addressed. Details at permitting.	LWBC/MoF
19	Adequacy of space beside railway tracks for infrastructure. <i>Originally raised: Additional Information Report Item - Table 10.7-6 of Additional Information Report</i>	BC Rail/CN Rail	WCC has accommodated this in design for the Wolverine FSR relocation and facilities located in proximity to the railway.	Response satisfactory. Issue addressed. Details at permitting.	LWBC, MoF
20	Safety and overlapping tenures. <i>Originally raised: Additional Information Report Item - Table 10.7-6 of Additional Information Report</i>	BC Rail/CN Rail	BC Rail have agreed in principle to the road realignment, but want to review the final design drawings. WCC has agreed. BC Rail have agreed to the power line alignment and design.	Response satisfactory. Issue addressed. Details at permitting.	LWBC, MoF
21	Overlapping interest and possible joint use of area.	BP Energy	Anticipate a statement of non-objection.	No EAO follow up needed.	MEM
22	Uninterrupted access - need for continuous public and forestry operations traffic access on Perry Creek Road. <i>Originally raised:</i>	Canfor	Perry Creek Road will remain open for public traffic and other industrial traffic during and after mining. Access will be maintained during road realignment.	Response satisfactory. Issue addressed. Details at permitting.	MEM/MoF

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
	<i>Additional Information Report Item - Table 10.7-2 of Additional Information Report</i>				
23	Traffic management - loaded logging trucks to be given right-of-way. <i>Originally raised: Additional Information Report Item - Table 10.7-2 of Additional Information Report</i>	Canfor	Loaded logging trucks will have right-of-way as per standard radio-controlled FSR operating procedures. No change from current procedures. WCC has committed to traffic management planning for both Perry Creek Road and Wolverine Forest Service Road. Standard radio-controlled FSR procedures will remain in effect on the Wolverine FSR.	Response satisfactory. Issue addressed. Details at permitting.	MOF
24	Primary road user designation - Canfor wants to remain primary road user. <i>Originally raised: Additional Information Report Item - Table 10.7-2 of Additional Information Report</i>	Canfor	WCC has agreed. WCC has signed Road Use Agreement with Canfor.	No EAO follow up needed.	MoF
25	Safety at road intersections <i>Originally raised: Additional Information Report Item - Table 10.7-2 of Additional Information Report</i>	Canfor	Crossings no longer an issue with the currently proposed alignment. There is one intersection, and it will be controlled.	Response satisfactory. Issue addressed. No EAO follow up needed.	MoF
26	Wolverine Forest Service Road realignment - grades and other standards maintained. <i>Originally raised: Additional Information Report Item - Table 10.7-2 of Additional</i>	Canfor	WCC agrees - matter resolved. Canfor has indicated agreement in principle to realignment of Wolverine FSR provided the realigned road provides year round access.	Response satisfactory. Issue addressed. Details at permitting.	MoF

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
	<i>Information Report</i>				
27	Canfor access - access to east side of Wolverine River for forestry operations. <i>Originally raised: Additional Information Report Item - Table 10.7-2 of Additional Information Report</i>	Canfor	Plan for Canfor to relocate a section of the road and the bridge to an upstream area resolves issue.	Response satisfactory. Issue addressed. Details at permitting.	MOF
28	Perry Creek Bridge safety (load restrictions) - bridge upgrading required to accommodate heavy traffic. <i>Originally raised: Additional Information Report Item - Table 10.7-2 of Additional Information Report</i>	Canfor	Bridge upgraded by Canfor since issue was raised; issue resolved.	Response satisfactory. Issue addressed. Details at permitting.	MOF
29	Potential loss of productive forest areas within Canfor's TFL - TFL 48. <i>Originally raised: Additional Information Report Item - Table 10.7-2 of Additional Information Report</i>	Canfor	Reclamation objectives will include creating a post-mine landscape with similar forest capabilities as existed pre-mine - with the exception of pit areas, where this will not be possible.	Response satisfactory. Issue addressed. Details in Additional Information Report confirmed at permitting.	MOF, MEM
30	Mine site timber salvage rights. <i>Originally raised: Additional Information Report Item - Table 10.7-2 of Additional Information Report</i>	Canfor	WCC has agreed. In terms of completing the salvage, the likely arrangement is that WCC will manage a 3rd party contractor. Continuing discussions required with Canfor.	Response satisfactory. Issue addressed.	MOF

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
31	Joint use of Perry Creek Road.	Canfor	WCC has agreed to pay the cost of the Perry Creek Road realignment and to maintain access during the road realignment, mining and reclamation phases of the project.	Response satisfactory. Issue addressed. No EAO follow up needed.	N/A
32	Joint use of Wolverine FSR.	Canfor	WCC has signed Road Use Agreement with Canfor.	Response satisfactory. Issue addressed.	MoF
33	Disturbance to wildlife.	Dale Drown on behalf of guide outfitter	Short term effects. Many species expected to habituate.	Response satisfactory. Issue addressed.	MWLAP
34	Increased traffic effects on wildlife (road kills, hunting, dust).	Dale Drown on behalf of guide outfitter	WCC will require strict adherence to posted speed limits from its workers, who will also be instructed that wildlife has the right of way (unless unsafe). WCC will implement a no hunting policy for employees traveling to or from the mine, and prohibit hunting on the mine property. WCC does not have authority to manage hunting outside its property (regional responsibility). No firearm provision for workers at minesite.	Response satisfactory. Issue addressed. Details to follow in Wildlife Management Plan.	MWLAP
35	Overlapping interest and possible joint use of area.	Elk Valley Coal	Elk Valley Coal issued a statement of non objection.	Response satisfactory. Issue addressed.	LWBC, MEM
36	Overlapping interest and possible joint use of area.	Encana	WCC sent Encana a map showing Wolverine Project tied to NTS survey. Encana issued a statement of non objection.	Response satisfactory. Issue addressed.	
37	Effect of Wolverine Mine Project on Trapping Territory 721T006 .	Licensed Trapper	WCC is discussing impact with licensed trapper and will review claim for compensation. Settlement anticipated December 30, 2004. Trapper has requested employment opportunity. WCC has paid the trapper for removal of beavers, with on-going work anticipated.	Negotiations on-going.	MWLAP
38	Species impacts. <i>Originally raised: Additional Information</i>	Licensed Trapper	Impacts are local, and effects limited to individual animals. No effects at population level.	Response satisfactory. Issue	

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
	<i>Report Item - Table 10.7-10 of Additional Information Report</i>			addressed.	
39	Beavers - beaver dams in the vicinity of the railway and load out. <i>Originally raised: Additional Information Report Item - Table 10.7-10 of Additional Information Report</i>	Licensed Trapper	WCC has contracted the trapper, to remove beaver from this area. Wildlife Act permit in place to allow removal of beaver dam.	Response satisfactory. Issue addressed.	MWLAP
40	Employment. <i>Originally raised: Additional Information Report Item - Table 10.7-10 of Additional Information Report</i>	Licensed Trapper	WCC will provide trapper with advance information on contracting and employment opportunities.	On-going.	N/A
41	Overlapping interest and possible joint use of area.	Husky Oil Operations	WCC has requested feedback or a statement of non objection. No response to date. Anticipate a statement of non objection.	No known issue. No follow up needed.	N/A
42	Honour the legacy of stewardship of the valley. <i>Originally raised: Additional Information Report Item - Table 10.7-8 of Additional Information Report</i>	John Terry Estate	WCC will use "best practices" in terms of environmental stewardship and site reclamation.	No outstanding issue. No follow up needed.	MWLAP
43	Grave site. <i>Originally raised: Additional Information Report Item - Table 10.7-8 of Additional Information Report</i>	John Terry Estate	The gravesite, which is near the Wolverine River and the buildings is not directly affected by the Wolverine Project, and will be protected. This commitment has been made to John Terry Estate.	No follow up needed.	MSRM
44	Ownership of the land and future of the	John Terry Estate	Principles of agreement concluded on a lease/purchase arrangement. Ranch is currently owned by John Terry	Final agreement	LWBC

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
	Terry Ranch. <i>Originally raised: Additional Information Report Item - Table 10.7-8 of Additional Information Report</i>		Estate. WCC has agreed to purchase a corner of the ranch (33 ha) which is required for mine infrastructure. WCC has also agreed to sell this land back to the family following reclamation of this area. A lease agreement for the remainder of the property is pending. A permanent right of way for the FSR will be established on the Northern Corner.	pending.	
45	Ranch residency. <i>Originally raised: Additional Information Report Item - Table 10.7-8 of Additional Information Report</i>	John Terry Estate	Owners of ranch have committed to a non-residency agreement, as needed to meet MWLAP standards in full. Full residency at the ranch will be possible again following mine closure. The John Terry Estate will be compensated for loss of habitation potential during the life of the mine - negotiations have concluded. Legal agreements are being finalized.	Awaiting agreement.	EAO, MWLAP
46	Long term liabilities <i>Originally raised: Additional Information Report Item - Table 10.7-8 of Additional Information Report</i>	John Terry Estate	WCC has developed management plans to address concerns that mine development could result in site contamination. Contingencies and monitoring plans are also defined. Aquatic Resource Monitoring plans have been reviewed with MWLAP.	Response satisfactory. Issue addressed. Details of the monitoring plans at permitting (e.g.. Groundwater)	MWLAP
47	Human health. <i>Originally raised: Additional Information Report Item - Table 10.7-8 of Additional Information Report</i>	John Terry Estate	WCC is addressing concerns that mine development will result in a negative impact on human health due to degradation in air quality. See above(#44) with regard to arrangements for non residency of ranch property.	Awaiting agreement and details at permitting.	MWLAP, Workers Health and Safety Branch, MEM
48	Health of vegetation. <i>Originally raised: Additional Information Report Item - Table 10.7-8 of Additional Information Report</i>	John Terry Estate	Impacts have been assessed and significant impacts are not expected. WCC will monitor vegetation metals on the mine site, as well as vegetation selenium levels in wetlands adjacent to the railroad track. Baseline for these items has been completed.	Response satisfactory. Issue addressed. Details of vegetation monitoring plans at permitting.	MEM

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
49	Livestock and wildlife health. <i>Originally raised: Additional Information Report Item - Table 10.7-8 of Additional Information Report</i>	John Terry Estate	Impacts have been assessed and significant impacts are not expected.	Response satisfactory. Issue addressed.	MWLAP
50	Effects on wetland and birds. <i>Originally raised: Additional Information Report Item - Table 10.7-8 of Additional Information Report</i>	John Terry Estate	Mitigation, monitoring and contingency plans will protect waterfowl using the wetland. Monitoring Programs have been agreed with MWLAP.	Response satisfactory. Issue addressed.	MWLAP
51	Impacts to wildlife, especially to waterfowl. <i>Originally raised: Additional Information Report Item - Table 10.7-8 of Additional Information Report</i>	John Terry Estate	Mitigation, monitoring and contingency plans will protect waterfowl using the wetland. Monitoring plans for the wetlands on and adjacent to the ranch have been developed and reviewed with MWLAP.	Response satisfactory. Issue addressed. Details at permitting.	MWLAP
52	Grazing tenure. <i>Originally raised: Additional Information Report Item - Table 10.7-8 of Additional Information Report</i>	John Terry Estate	Allowable animal units months were reduced within the Grazing Tenure because of the low level of use. Last reported use levels were still well below the allowable level. Should be possible to move livestock (horses) to other parts of the Grazing Tenure.	Awaiting agreement.	MoF
53	Long term goals of ranch owners. <i>Originally raised: Additional Information Report Item - Table 10.7-8 of Additional Information Report</i>	John Terry Estate	Impact on property to be compensated for and documented in agreement.	Final agreement pending.	N/A
54	Aesthetics / viewscape. <i>Originally raised:</i>	John Terry Estate	Impact on property will be compensated as per principles of Agreement.	Response satisfactory. Issue	MEM

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
	<i>Additional Information Report Item - Table 10.7-8 of Additional Information Report</i>			addressed. Reclamation details at permitting.	
55	Wolverine FSR and the power line. <i>Originally raised: Additional Information Report Item - Table 10.7-8 of Additional Information Report</i>	John Terry Estate	Agreement in principle to locating power line rights of FSR and way permanently on Northwest Corner to be provided for on property transfer to WCC.	Response satisfactory. Issue addressed. Details at permitting.	MoF
56	Water management pipeline. <i>Originally raised: Additional Information Report Item - Table 10.7-8 of Additional Information Report</i>	John Terry Estate	Agreement in principle to locating pipeline and water management structures on property.	Response satisfactory. Issue addressed.	MWLAP, LWBC
57	Livestock wintering - Grazing Tenure RAN072880. <i>Originally raised: Additional Information Report Item - Table 10.7-9 of Additional Information Report</i>	John Terry Estate	Owners are dealing with MOF directly on this issue.	Details at permitting.	MoF
58	Fencing. <i>Originally raised: Additional Information Report Item - Table 10.7-9 of Additional Information Report</i>	John Terry Estate	Terry Ranch executors have indicated that all of the required fencing is already in place (to keep livestock off the FSR and the railway), and that it will be the Ranch's responsibility to maintain it.	Response satisfactory. Issue addressed.	N/A
59	Coal dust on plants. <i>Originally raised: Additional Information Report Item - Table 10.7-9 of Additional Information Report</i>	John Terry Estate	Not expected to be a significant concern based on studies of other sites. Discussed at Wildlife Working Group Meeting.	Response satisfactory. Issue addressed.	MWLAP

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
60	Removal of land from Grazing Tenure. <i>Originally raised: Additional Information Report Item - Table 10.7-9 of Additional Information Report</i>	John Terry Estate	Depending on the existing forage values within the disturbance areas it may be possible to modify utilization patterns on the area without significant effect. Range enhancement measures in other parts of the tenure area are another possibility. Under discussion with the executors of the John Terry Estate. Not of concern at present utilization levels.	No EAO follow up needed. Details at permitting.	MoF
61	Coal Bed Methane (CBM) Test Well (A-10-G/93PG). <i>Originally raised: Additional Information Report Item - Table 10.7-4 of Additional Information Report</i>	Koch	Signed agreement between Koch and WCC dated December 2003. Test well will be abandoned by June 30, 2005 or 60 days following notice by Chief Inspector of Mines.	Response satisfactory. Issue addressed.	MEM/OGC
62	Safety. <i>Originally raised: Additional Information Report Item - Table 10.7-4 of Additional Information Report</i>	Koch	Signed agreement with Koch addresses issues of safety. Operational details to be worked out by Koch and WCC when construction begins.	Response satisfactory. Issue addressed.	MEM/OGC
63	Safety/Damage of Well. <i>Originally raised: Additional Information Report Item - Table 10.7-4 of Additional Information Report</i>	Koch	Agreement provides that Koch can elect to either provide protection for the well and/or well site facilities and equipment, or abandon the well.	Response satisfactory. Issue addressed.	MEM/OGC
64	Joint use of Perry Creek Road. <i>Originally raised: Additional Information Report Item - Table 10.7-4 of Additional Information Report</i>	Koch	WCC has agreed to pay the cost of the Perry Creek Road realignment and to maintain access during the road realignment, mining and reclamation phases of the project.	Response satisfactory. Issue addressed.	MEM/OGC
65	Joint use of Wolverine FSR.	Koch	WCC has signed Road Use Agreement with Canfor. Canfor is expected to take the lead in the traffic management time.	Response satisfactory. Issue	MEM/OGC/MoF

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
				addressed.	
66	Traffic management. <i>Originally raised: Additional Information Report Item - Table 10.7-4 of Additional Information Report</i>	Koch	WCC has committed to traffic management planning for both roads. Standard radio-controlled FSR procedures will remain in effect on the Wolverine FSR. WCC will notify and will consult with Koch prior to construction	Response satisfactory. Issue addressed.	MEM/OGC/MoF
67	Emergency planning/response zones.	Koch	To be addressed at operational level by WCC as part of Emergency Response. Safety training required for WCC.	Response satisfactory. Issue addressed.	MEM/OGC/MoF
68	Well abandonment and reclamation. <i>Originally raised: Additional Information Report Item - Table 10.7-4 of Additional Information Report</i>	Koch	Koch is required to complete prior to June 30, 2005 and for costs of all clean-up and reclamation pertaining to the well and well-site.	Response satisfactory. Issue addressed. Details at permitting.	MEM/OGC
69	Potential for new Petroleum and Natural Gas/Coal Bed Methane infrastructure on mine site. <i>Originally raised: Additional Information Report Item - Table 10.7-4 of Additional Information Report</i>	Koch	Koch's development plan in the area has not been established at this time. Koch has no specific plans at this time. No identified conflict.	No follow up needed.	MEM/OGC
70	Ongoing operational issues. <i>Originally raised: Additional Information Report Item - Table 10.7-4 of Additional Information Report</i>	Koch	Need for standard on-going operational cooperation between the two companies during period of joint use. Provided for in Letter of Agreement between Koch and WCC.	Response satisfactory. Issue addressed. No agency follow up needed.	MEM/OGC
71	Effects of coal dust on Terry Ranch cattle	Mary Ann Eyben - John Terry	WCC has researched this issue - University of Saskatoon veterinarian opinion says likely not an issue. Independent	Response satisfactory.	MWLAP

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
	and horses.	Estate	consultant indicated no evidence of this as a concern. Coal industry in eastern BC concurs.	Issue addressed.	
72	Effects of noise (blasting/drilling) on wildlife.	Mary Ann Eyben - John Terry Estate	Short term effect. Wildlife is expected to habituate to daily blasting.	Response satisfactory. Issue addressed.	MWLAP
73	Overlapping interest and possible joint use of area.	Scott Land & Lease aka Saskatoon Assets aka Canadian Coastal Resources	WCC has requested feedback or a statement of non objection. No response to date. Indicating no concerns.	No EAO follow up needed.	MEM/OGC
74	Overlapping interest and possible joint use of area.	Sekani/Den-Mara	WCC has requested feedback or a statement of non objection. No response to date, indicating any concerns.	No EAO follow up needed.	MEM/OGC
75	Proposed Bullmoose IV Well (C-2-F/93P3) and access road <i>Originally raised: Additional Information Report Item - Table 10.7-5 of Additional Information Report</i>	Formerly Shell, rights transferred to Talisman	Draft agreement between Shell and WCC sent to Shell. Shell has recently informed WCC that interest in proposed well area has been taken over by Talisman. Talisman confirmed that the right was used to drill a well at A-16-F/93P3 which is outside and east of WCC's coal licences in the area. Shell has issued a statement of non objection to the Wolverine Project.	No EAO follow up needed.	MEM/OGC
76	Water management in joint area - Shell's access road is within the catchment area for the clean water diversion for the Perry Creek Mine. <i>Originally raised: Additional Information Report Item - Table 10.7-5 of Additional Information Report</i>	Shell	Shell has recently informed WCC that interest in proposed well area has been taken over by Talisman. See #75.	No EAO follow up needed.	MEM/OGC
77	Bullmoose II Well, located north of Perry	Shell	Shell sent WCC a letter saying they have no plans to proceed with the well.	No EAO follow up needed.	MEM/OGC

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
	Creek, near the Wolverine FSR. <i>Originally raised: Additional Information Report Item - Table 10.7-5 of Additional Information Report</i>				
78	Joint use of Perry Creek Road. <i>Originally raised: Additional Information Report Item - Table 10.7-5 of Additional Information Report</i>	Shell	WCC has committed to pay the cost of the Perry Creek Road realignment and to maintain access during the road realignment, mining and reclamation phases of the project.	Response satisfactory. Issue addressed. No EAO follow up needed.	MEM/OGC
79	Traffic management <i>Originally raised: Additional Information Report Item - Table 10.7-4 of Additional Information Report</i>	Shell	WCC has committed to traffic management planning for both roads. Standard radio-controlled FSR procedures will remain in effect on the Wolverine FSR. To be on a project basis as needed.	Response satisfactory. Issue addressed.	MEM/OGC
80	Uninterrupted access - Joint use of Perry Creek Road and need for continuous access. <i>Originally raised: Additional Information Report Item - Table 10.7-3 of Additional Information Report</i>	Talisman	Perry Creek Road will remain open for public traffic and other industrial traffic during and after mining. Access will be maintained during road realignment, mining and reclamation phases of the project.	Response satisfactory. Issue addressed.	MoF/MEM
81	Cost of Perry Creek Road re-alignment. <i>Originally raised: Additional Information Report Item - Table 10.7-3 of Additional Information Report</i>	Talisman	WCC has agreed to pay the entire cost of the Perry Creek Road realignment.	Response satisfactory. Issue addressed.	MOF/MEM
82	Traffic management.	Talisman	WCC has committed to traffic management planning for	Response	MOF/MEM

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
	<i>Originally raised: Additional Information Report Item - Table 10.7-3 of Additional Information Report</i>		both Perry Creek road and Wolverine Forest Service Road. Standard radio-controlled FSR procedures will remain in effect on the Wolverine FSR.	satisfactory. Issue addressed.	
83	Land tenure - conversion of WCC Coal Licenses to Leases for the purpose of developing the EB Pit and related facilities. <i>Originally raised: Additional Information Report Item - Table 10.7-3 of Additional Information Report</i>	Talisman	Talisman has signed an agreement that they do not object to this conversion.	Response satisfactory. Issue addressed. Details at permitting.	MEM
84	Land tenure - conversion of WCC Coal Licenses to Leases for the purpose of developing the Perry Creek Pit and related facilities. <i>Originally raised: Additional Information Report Item - Table 10.7-3 of Additional Information Report</i>	Talisman	Letter of agreement stating Non-objection by Talisman for conversion of Coal Licenses to Leases for future Perry Creek underground mining, which is the only area of overlapping tenure between Talisman and the Perry Creek Mine.	Response satisfactory. Issue addressed. Details at permitting.	MEM
85	Joint use of Wolverine FSR.	Talisman	WCC has signed Road Use Agreement with Canfor. Canfor will lead in addressing road use issues.	Response satisfactory. Issue addressed.	MOF
86	Proposed Bullmoose IV Well (C-2-F/93P3) and access road.	Talisman	WCC has confirmed Talisman's jurisdiction and plans for this well. Talisman have transferred their right and have drilled a well at A-16-F/93P3 which is outside and east of WCC's coal licences.	No EAO follow up needed.	MEM/OGC

**APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT**

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
87	Pipeline crossings in the EB area. <i>Originally raised: Additional Information Report Item - Table 10.7-3 of Additional Information Report</i>	Talisman	Agreement on design and construction of new crossing, and maintenance of all crossings, has been reached between the two companies.	Response satisfactory. Issue addressed.	MEM/OGC
88	Emergency planning/response zones.	Talisman	Provided for in Agreements signed with Talisman. Safety training related to sour gas signed with Talisman.	No EAO follow up needed. Details at permitting.	MEM/OGC
89	New PNG infrastructure on mine site. <i>Originally raised: Additional Information Report Item - Table 10.7-3 of Additional Information Report</i>	Talisman	Talisman has signed an agreement with WCC to not construct any new PNG facilities within the EB Open Pit until EB mine closure.	No EAO follow up needed.	MEM/OGC
90	On-going operational issues. <i>Originally raised: Additional Information Report Item - Table 10.7-3 of Additional Information Report</i>	Talisman	Need for on-going operational cooperation between the two companies, as per commitments in signed agreements.	No EAO follow up needed.	MEM/OGC
91	Access issues.	TR Ridge Riders	No response to WCC's additional information package. WCC has committed to maintain existing public roads during mining.	Response satisfactory. Issue addressed.	MoF/MEM
92	Overlapping PNG interest and possible joint use of area.	Western Land Services	WCC has requested feedback or a statement of non objection. No response to date. No objection expected.	No EAO follow up needed.	MEM/OGC
93	Overlapping PNG interest and possible joint use of area.	WJ Quinn Consulting	WCC has requested feedback or a statement of non objection. No response to date. Anticipate no objections.	No EAO follow up needed.	
94	Access to Mt. Spieker and Mr.	Wolverine Nordic & Mountain	Nordic & Mountain Society wrote to WCC with questions about access. Response letter dated September 21,	No follow up needed.	N/A

## APPENDIX B – PUBLIC ISSUES TRACKING SUMMARY – REVIEW OF ADDITIONAL INFORMATION REPORT AND ADDENDUM REPORT

# ID	Issues Raised	Submitted by	Proponent Response	Review Status	Responsible Agency
	Reesor/Access up Perry Creek Road.	Society	2004, committed to maintaining access.		
95	Improvement of Highway 52.	Bill Cooksby	Improvement to highways in the area due to the project are not needed. Existing Highways have excess capacity to handle projected traffic. No highway coal haul needed.	No EAO follow up needed.	N/A
96	Potential Impact on Tourism.	Stacey Leunesse	WCC has developed extensive programs to protect and restore environmental values. Potential for mine tours to be of interest to tourists during operations.	No EAO follow up needed. Details at Permitting.	MEM/MWLAP
97	Local employment and contracting.	Various public meetings	WCC has committed to local hiring for mine construction and operations.	No EAO follow up needed.	
98	On-going operational issues. <i>Originally raised: Additional Information Report Item - Table 10.7-3 of Additional Information Report</i>	Talisman	Need for on-going operational cooperation between the two companies, as per commitments in signed agreements.	No EAO follow up needed.	MEM/OGC

### Abbreviations

BP Energy	
Canfor	Canadian Forest Products Ltd.
EAO	Environmental Assessment Office
Encana	Encana Corporation
FSR	Forest Service Road
Koch	Koch Petroleum Canada Ltd.
LWBC	Land and Water British Columbia Inc.
MEM	Ministry of Energy and Mines
MoF	Ministry of Forests
MWLAP	Ministry of Water, Land and Air Protection
N/A	Not Applicable
OGC	Oil and Gas Commission
PNG	Petroleum and Natural Gas
Shell	Shell Canada Ltd.
Talisman	Talisman Energy Canada Inc.
TFL	Tree Farm License
WCC/Proponent	Western Canadian Coal Corp.