




High water marks located on farm at XS 11 on the left bank of the Slocan River.



H.W.M. B1

On the foundation of the farmhouse.


Elev. 477.827



H.W.M. B2

On left bank of river at XS 11.

Elev. 477.037



H.W.M. A


Located below the centre of the suspension foot bridge at XS 55.

Centre bridge deck
Elev. 477.0

H.W.M. is 4.7 FT below the deck
Elev. 475.58

NOTE:

This information is considered historical as it represents channel conditions and configuration at the time of the survey only. User must accept responsibility of ensuring that the accuracy and completeness of provided data is suitable for the needs of the project or study. It is provided "as is" without warranty of any kind, whether express or implied. Under no circumstances will the Government of British Columbia be liable to any person or business entity for any direct, indirect, special, incidental, consequential, or other damages based on any use of this information.




H.W.M. C

Located on the left bank of slocan river at Meadow Lark Alpine Dairy farm, DS of XS 38.

H.W.M. is on the concrete base of the barbeque
Elev. ~~508.91~~ 506.09

Page (15)
88/10/13



H.W.M. D

Located on the left bank of the slocan river at the old Appledale (now destroyed) bridge between X-sects 44 & 45.

Top of guard post
Elev. 521.641

H.W.M. is 5.4 ft below the top of the guard post
Elev. 520.00