

water levels

PROJECT 76RPP4
NORTH THOMPSON RIVER
SEPT. 20/21 1976
CLEARWATER

XS1	F101	-7.05 =	1316.97 RB	-7.23 =	1316.79 LB
XS2	F2	-26.32 =	1318.26 RB	-26.57 =	1318.01 LB
XS3	F3	-10.12 =	1320.13 RB	-9.93 =	1320.31 LB
XS4	F4	-3.04 =	1322.14 RB	-3.67 =	1321.51 LB
XS5	F5	-9.72 =	1322.99 RB	-9.99 =	1322.72 LB
XS6	F106	-11.97 =	1324.34 RB	-12.73 =	1323.58 LB
XS7	F107	-6.31 =	1325.44 RB	-7.04 =	1324.71 LB
XS8	F108	-3.92 =	1326.19 RB	-4.11 =	1326.00 LB
XS9	F109	-11.23 =	1326.63 RB	-11.38 =	1326.48 LB
XS10	F110	-5.82 =	1330.17 RB	-5.88 =	1330.11 LB

WL for bridge X55A

5	0	1322.85
Bridge	360	1323.27
6	958	1323.96

NOTE:

This information is considered historical as it represents channel conditions and configuration at the time of the survey only. User must accept responsibility of ensuring that the accuracy and completeness of provided data is suitable for the needs of the project or study. It is provided "as is" without warranty of any kind, whether express or implied. Under no circumstances will the Government of British Columbia be liable to any person or business entity for any direct, indirect, special, incidental, consequential, or other damages based on any use of this information.