


ECOCAT ID: 14185-25

OSILINKA RIVER

Fish Habitat and Stream Inventory

SCALE 1:20 000



SYMBOL EXPLANATION

T.R.I.M. TOPOGRAPHY:	STREAM INVENTORY:
Loose Surface - All Weather Road	Back Channel
Loose Surface - Winter Road	Crossing - Road or Culvert
Buildings	Bank Failure
Slide Area	Barrier
Treed Swamp	Beaver Dam
Marsh	Side Channel
Wooded Area	Bedrock - Confined
GLACIAL FEATURES:	Island
Esker	Bedrock - Outcrop
Glacier	Wetlands
Contour, Index	Wetlands - Right Bank
Contour, Intermediate	Wetlands - Left Bank
Contour, Indefinite	Falls or Chutes (m)
Moraine	Large Organic Debris Class 1
ELEVATION:	Large Organic Debris Class 2
Index Contour	Tributary - Right Bank
Intermediate Contour	Tributary - Left Bank
Contour, Index	Crossing
Depression	Crossing - Ford
Contour, Intermediate	Crossing - Bridge
Depression	Logging - Upstream
HYDROGRAPHY:	Logging - Downstream
Water Level	Pool - Class 1
Lake	Pool - Class 2
Stream	Boulder Garden
Intermittent Stream	Riffle
Intermittent Lake	River
Island (to scale)	Braided Stream
Sand or Gravel Bar	Reach Break
Flow Direction Arrow	

WATERSHED IDENTIFIER:

VIDEO REFERENCE:

WETTED WIDTH (m):

STREAM DEPTH (m):

SUBSTRATE:

GRADIENT - HIGH:

- LOW:

CONTOUR INTERVAL 20 METRES
Elevation in Metres above Mean Sea Level

SOURCE:

BASE: TR	STR SYM: INV
LOC: VDC	LK SYM: N/A
HAB: VID	
FISH: N/A	
DATE INV: 1998/09/08	INV MGMT: MELP

BASE MAP: 94C.016

DATE: 03/31/98

GEODETIC

COMPILATION: TGS

DATUM: NAD 83

SURVEYED BY:

Province of British Columbia


TERRA PRO
GPS SURVEYS LTD
Survey Services, Inc. 1998-1999
100-1111 14th Ave. W. P.O. Box 1000
V6H 2T6

Ministry of Environment, Lands and Parks

INDEX LOCATION

UTM ZONE: 10

C026
94C.016
C006



B.C. ENVIRONMENT
LIBRARY
PRINCE GEORGE