



GITANYOW FISHERIES AUTHORITY

Southern Kitwanga Watershed Fish Passage - Culvert Inspection and Water Quality Effectiveness Evaluation Project 2007

500 0 500 1000 1500 2000 2500 3000 3500 4000 Meters

Legend Roads 1:20k TRM Map Sheets Road Annotation Streams TRM Lakes and Two Sided Streams		2007 FPCI Barrier Classifications Blower Suctioned Non-Fish-Barrier Full-barrier No fish barrier No rank Partial barrier Undetermined		2007 WQEE Sediment Risk - Surveyed Sites - Site ID 350	
2007 FPCI Barrier Classifications Blower Suctioned Non-Fish-Barrier Full-barrier No fish barrier No rank Partial barrier Undetermined		2007 WQEE Sediment Risk Rating Extreme High Low Moderate Nil No rank		Surveyed Sites Bridge Culvert Deactivated Log corridor Mapping error No access No culvert	