Province of British Columbia Ministry of the Environment Water Investigations Branch

A REVIEW OF GROUNDWATER

CONDITIONS ON GABRIOLA ISLAND

W. S. Hodge Technician Groundwater Section Hydrology Division

Victoria, B.C. August 1978

TABLE OF CONTENTS

	\underline{P}	ge				
	TABLE OF CONTENTS	ii				
	LIST OF FIGURES i	ii				
	LIST OF TABLESi	ii				
1.	INTRODUCTION	1				
2.	LOCATION, AREAL EXTENT AND CLIMATE					
3.	TOPOGRAPHY AND DRAINAGE					
4.	SURFICIAL DEPOSITS 4					
5.	BEDROCK GEOLOGY 4					
6.	BEDROCK STRATIGRAPHY	4				
	6.1 Gabriola Formation	5 5 5 5				
7.	WATERSHED REGIONS	6				
× . •	7.1 Sands Region 7.2 Lock Bay Region 7.3 Descanso Bay Region 7.4 Gabriola Region 7.5 Silva Bay Region 7.6 North Degnen Bay Region 7.7 West Degnen Bay Region 7.8 False Narrows Regions 7.9 Hoggan Lake Region 7.10 Northumberland Channel Region 7.11 South Descanso Bay Region	8 11 13 15 17 18 19 20 22 23 24				
8.	GROUNDWATER QUALITY	25				
9.	OBSERVATION WELLS 9.1 Observation Well 72-1 9.2 Observation Well 72-2 9.3 Observation Well 72-3 9.4 Observation Well 72-4 9.5 Observation Well 72-5	26 27 28 28 29 30				
10.	CONCLUSIONS	30				
11.	RECOMMENDATIONS 32					
12.	REFERENCES					

LIST OF FIGURES

•			· · · · · · · · · · · · · · · · · · ·	age
Figure	1	-	Watershed region map	35
Figure	2	_	Legal location map	36
Figure	3	-	Bedrock and structural geology map	37
Figure	4	•	Map showing well yields greater than 10 gpm	38
Figure	5	-	Map showing chlorides exceeding 100 Mg/L	39
Figure	6	-	Map showing chlorides exceeding 100 Mg/L	40
Figure	7	-	Water quality comparison in observation wells	41
Figure	8	-	T.D.S depth relationship in bedrock wells	42
Figure	9	-	Observation well locations	43
Figure	10	-	Lithology of observation wells	44
Figure	11	-	Hydrographs prepared from observation well records	45
Figure	12	-	Demand-storage percentages	46
			LIST OF TABLES	
Table 1	l -		abriola Island well inventory - hydrogeological ata	47
Table 2	2 -	•	uantitative estimates of present groundwater use	95

A REVIEW OF GROUNDWATER

CONDITIONS ON GABRIOLA ISLAND

1. INTRODUCTION

The Groundwater Section of the Water Investigations Branch, Ministry of the Environment, has been involved in groundwater studies on Gabriola Island since the summer of 1971. This involvement has included the retaining of Robinson, Roberts, and Brown Ltd., a groundwater consulting firm of Vancouver, to conduct a drilling program during the summer of 1972, for the purpose of obtaining information on the groundwater geology and hydrology of Gabriola Island. The results and subsequent conclusions on the hydrogeology of the Island, derived from this drilling program, have been referred to in part throughout this text.

Additional investigations, including some "door-to-door surveys" to obtain local groundwater information, have been conducted by the Groundwater staff during 1973 and 1974. From 1975 to present, investigations have been limited to the collection of water level data and maintenance of two water level recorders installed on wells constructed during the 1972 drilling program, occasional water well sampling, well location work by summer staff and collection of drill log data on a continuing once per year basis.

The objectives of this presentation are as follows:

- (1) to compile and summarize all hydrogeological and hydrochemical data obtained to date for presentation into a format for future reference;
- (2) to examine all groundwater information available and make quantitative estimates on groundwater usage versus groundwater in storage for each groundwater region; and
- (3) review and discuss water quality and delineate problem areas.

A total of 850 records of wells drilled up to October 1977 have been reviewed. Of this total, 746 well records have been summarized and tabulated (Table 1). The remaining 106 records are of wells drilled during 1977 and these have not yet been accurately located in the field. Site descriptions given by drillers have, however, allowed the writer to roughly plot a large percentage of these wells on maps, thereby obtaining a reasonable idea where and at what rate groundwater development is taking place.

A map has been prepared showing Gabriola Island divided into 11 watershed regions (Figure 1). A detailed discussion on the hydrogeology of each region has been included in this report. A location map showing legal sections, and local place names has been prepared (Figure 2). A map has been prepared showing the basic characteristics of the bedrock geology of Gabriola Island (Figure 3). Maps have also been prepared showing well yields exceeding 10 gallons per minute as rated by the local drillers (Figure 4). Rating of the well yield is generally done by conducting a bail test on the well. Bailing time or number of bails removed is recorded in relation to total drawdown of water level. This method gives the driller a rough idea of the productive yield of each well. Maps showing wells sampled with chloride values exceeding

100 mg/L have been prepared (Figures 5, 6). A Schoeller plot has been prepared comparing the water quality in two observation wells (Figure 7). A plot of total dissolved solids versus total depth of well has been prepared to see if a depth-T.D.S. relationship exists (Figure 8). Maps have been prepared showing the location and lithology of the five observation wells (active and non-active) on Gabriola Island (Figures 9, 10), as well as water level plots for observation wells 72-1 and 72-4 (Figure 11). These observation wells have been discussed in detail in this report. Estimated groundwater usage versus available groundwater in storage has been calculated (Table 2) with relationships shown diagrammatically in Figure 12.

2. LOCATION, AREAL EXTENT AND CLIMATE

Gabriola Island is approximately 13,000 acres in size and is located east of Nanaimo. It is reached by a 20-minute scheduled ferry ride from Nanaimo and has a permanent population of around 1,150 people (Oswald, 1978). Visitors and part-time residents can increase this number to three times the permanent population during the summer months.

The island is characterized by a cool maritime climate with relatively warm, wet winters and cool, dry summers. The average annual precipitation over the last ten years has been determined as 34 inches (B.C. Ministry of Agriculture, 1977).

3. TOPOGRAPHY AND DRAINAGE

As the soil cover of Gabriola Island averages less than 6 feet, the topography generally reflects the underlying bedrock structure. The land surface is generally higher along the southwest coastal region and slopes in

a northeasterly direction. The highest elevation on Gabriola Island is slightly above 550 feet.

4. SURFICIAL DEPOSITS

The average depth of overburden on Gabriola Island is generally less than 6 feet. Surficial deposits of significant thickness or extent are practically nonexistent on Gabriola Island. The Island is generally free of glacial debris, except in some valleys where meltwater sediments have been deposited. Coarse gravel and boulder deposits reaching thicknesses up to 85 feet have been deposited near the southeast coast of the Island, west of Degnen Bay. Surficial deposits of any significant thickness appear limited to this specific area. A few shallow, moderately producing domestic wells have been completed in this material. Well log data has shown these gravel deposits to be generally dry and well-drained.

5. BEDROCK GEOLOGY

Gabriola Island is comprised of sedimentary rocks belonging to the Upper Cretaceous Nanaimo Group (Muller and Jeletzky, 1970). Erosion during and following the Pleistocene, coupled with constant weathering, have formed the present topography. The principal bedrock types of Gabriola Island are interbedded sandstones and interbedded shales and conglemerates.

6. BEDROCK STRATIGRAPHY

Four stratigraphic rock formations outcrop on Gabriola Island (Figure 3).

Additional, more detailed stratigraphic discussions have been made by Muller and Jeletzky (1970). According to Muller and Jetelzky (1970), three of these

formations are predominantly interbedded sandstones and two are predominantly interbedded shales. These formations and their predominant lithology are listed below:

Formation	Predominant Lithology
Gabriola	sandstone
Spray	shale
Geoffrey	sandstone
Northumberland	shale .

A very brief description on the lithology of each formation from Muller and Jeletzky (1970) is as follows:

6.1 Gabriola Formation

The Gabriola Formation is predominantly sandstone with some conglomerate lenses occurring locally. The lack of extensive conglomerate is a distinctive feature of this formation.

6.2 Spray Formation

The lower part of the Spray Formation consists largely of siltstoneshale sequences with thinly graded beds. Shale is more predominant in the upper part and individual shale beds are several feet thick, separated by thin bottom layers of siltstone.

6.3 Geoffrey Formation

The Geoffrey Formation is mainly composed of sandstone and coarse conglomerates. Cross bedding and shale breccias are exhibited in this formation and cavernous to honeycomb weathering features can be seen along the coastline.

6.4 Northumberland Formation

The upper part of the Northumberland Formation is comprised mainly of shales while the lower beds of the Northumberland are replaced by sandstone

and coarse conglomerate. This information can be seen exposed northeast of Northumberland Channel on the south coast of Gabriola Island. At False Narrows, between Mudge and Gabriola Islands shales are estimated to reach a thickness of 1,000 feet (Muller and Jeletsky, 1970).

7. WATERSHED REGIONS

Gabriola Island has been divided for convenience into 11 watershed regions (Figure 1). Boundaries between these regions generally represent the topographic divides between natural drainage basins. Watersheds were drawn from maps of 1" = 1,320' with contour intervals of 25 feet. They were subsequently reduced to the scale shown in Figure 1.

Maps showing preliminary groundwater regions have previously been prepared (Brown and Erdman, 1975) and are based principally on the results and subsequent conclusions derived during the 1972 drilling program by Robinson, Roberts and Brown. Although several groundwater regions have previously been defined by topography, bedrock lithology and fault and fracture systems on the Island, a more simplified division, a watershed region based primarily on topography, has been adopted for this report.

The largest watershed region is the Gabriola region (Figure 1) covering approximately 3,149 acres.

An estimate of the annual groundwater use in each region (Table 2) was made based on the number of wells in each region, utilizing a demand figure of 500 gallons per day for each well over a period of 100 days of little or no recharge. These figures were then compared to the probable groundwater available in storage for use on an annual basis over the same 100-day no recharge period. Under natural recharge conditions this quantity of water would be replenished annually from precipitation during the winter months. Potential recharge from precipitation (Foweraker, 1974) was calculated for Mayne Island on the basis of 1 inch per year. However, Foweraker found that his calculations exceeded by $2\frac{1}{2}$ times the estimated storage available for groundwater within the

fractured bedrock media. This led him to believe that on an annual basis storage and permeability and not precipitation, appear as the more immediate limiting factors controlling groundwater availability on the Islands, particularly during the dry summer and fall periods.

Recharge to the groundwater regime from septic field disposal systems has not been accounted for in the recharge calculations of this report. Natural groundwater recharge generally takes place in topographically higher areas of the watersheds. Since most residential development is concentrated along coastal areas near the discharge end of the groundwater flow systems, groundwater recharge from septic fields is not considered to be a significant contribution regionally. Much of the septic effluent in coastal areas might be expected to discharge (seepage) into the sea, or be lost through evaporation and transpiration.

Storage coefficients of artesian bedrock aquifers may range from 1×10^{-5} to 1×10^{-3} (W.C. Walton, 1970). As reliable pump test data is lacking in most regions, difficulties arise in predicting changes in storage in relation to, and location of fault zones and density of bedrock fracturing. In view of this, a bulk storage coefficient of 1×10^{-4} (.01%) has been used in computing groundwater storage on Gabriola Island. This figure has previously been used for all computations of groundwater storage on Mayne Island (Foweraker, 1974). Application of this figure may not be feasible locally where detailed groundwater studies in a specific area have proven otherwise.

The method of estimating the demand-storage percentage of each region (Figure 12) was adapted from Foweraker (1974), but differs in that groundwater use is based on the number of wells rather than the number of residents using groundwater. Since one well may service more than one residence and not all wells may be used, the estimated demand-storage percentage figures may be somewhat high. Figures above 75% may therefore be considered critical. Following is an example of the calculations used in determination of the demand-storage percentage for the South Descanso Bay region.

Example:

- (1) Area of region x total thickness of rock to bottom of potable water-bearing zone
- = Total volume of rock
 (acre-feet)

(339.20 acres) x (assume 200 feet)

- = (67,840 acre-feet)
- (2) Total volume of rock x storage coefficient
- Total potable groundwater
 in storage (acre-feet)

(67,840 acre-feet) x (0.0001)

- = (6.78 acre-feet)
- (3) No. of wells x daily use x period of little in region per well or no recharge from precipitation
- = Estimated groundwater usage
- (49 wells) x (500 gals./day) x (100 days)
- = (2,400,000 gallons)

(4) Estimated groundwater usage Total potable groundwater in storage in U.S. gallons

Demand-storage percentage

 $\frac{2,400,000}{6.78 \times 43,560 \times 7.481} \times 100$

= 108.6%

The demand-storage figures should be used with reservation as they are based on a simplified model which may be amended when more groundwater data becomes available. The figures do, however, identify problem areas where groundwater use may be exceeding natural recharge.

Following is a detailed discussion on the hydrogeological and hydrochemical information obtained within each watershed region.

7.1 Sands Region

Area - 864.2 acres

No. of drilled wells in region

- 154

No. of dug wells and utilized springs in region - 21

The Sands Region is a highly developed, popular area with many wells located on lots varying in size between 0.5 and 1 acre along coastal areas.

The average depth of overburden overlying bedrock in this region is approximately 6 feet, while the average well depth and yield has been determined as 131 feet and less than 5 gallons per minute respectively.

The majority of drill logs on record in this region show layered sandstone and shale sequences. The principal water-bearing formation appears to be
the contact zone between these sequences, with the shale layering being the
major water-bearing material. Clay layering of varying thickness between bedrock zones is shown in numerous drill logs; however, this material is probably
in reality a softer shale. Clay fault gauge may occur in some cases; however,
thickness here would not be expected to be significant.

Well depths range from shallow dug wells (8 to 35 feet deep) to drilled depths of 418 feet.

Two good quality wells with high yield potential are reported in Section 21 and Section 22 (Figure 2). Both report excellent yields of between 25 and 30 gallons per minute, are relatively shallow, and are located considerably far inland. Greater yields have been reported from deeper wells in this region; however, hydrogen sulphide odour is apparent in these deeper wells.

Although the peninsula between Taylor and Pilot Bay (Figure 2) may be receiving some freshwater recharge from areas inland, water sampling has shown the potable groundwater in storage is intruded by sea water. The peninsula is a low-lying basin area and limited in catchment area, severely restricting potable groundwater recharge.

The probability of obtaining a good quality groundwater on the peninsula is very unlikely. Although some moderately yielding wells of 5 to less than 10 gallons per minute are located on the peninsula, Hach (field chemical) analyses have shown this area to be subject to sea water encroachment. Chloride values greater than 2,000 ppm (parts per million) have been recorded in some wells along the coastal fringe (Figure 6). All drilled wells on record located on the peninsula are completed below sea level. All wells sampled on the peninsula have shown evidence of sea water encroachment, and further groundwater development is not recommended.

The majority of wells located along Berry Point Road between Pilot Bay and Orlebar Point (Figure 2) report yields of less than 2 gallons per minute, although one recently drilled flowing artesian well (drilled July 1977) sited nearby a line of springs south of Clark Bay within the boundaries of Section 22 (Figure 2), has reported an excellent yield of 25 gpm (actual flow is not known) from 140 feet below ground level. Wells under artesian pressure in this area have recorded chloride values as high as 1,233 mg/L and T.D.S. values over 1,900 mg/L. This fact coupled with the spring activity may indicate the presence of a major fractured zone in the area.

From present knowledge, wells located inland and at higher elevations have shown water quality to be of a benign type. Chemical analysis has shown water quality to be a soft, moderately mineralized, type groundwater.

In summary, sea water encroachment is evident on both the peninsula between Taylor and Pilot Bay, and along the total coastline fringe bordering this groundwater region. It can be seen (Figure 6) that although saline water is restricted to wells completed below sea level around coastal areas,

salinity values do not necessarily increase with increasing depth. Salinity values would, however, be expected to increase with length and time of pumping and volume of water pumped. Sea water intrusion is evident in some wells inland from Taylor Bay, where rock fracturing may be directly linked with the ocean. Quality of well water in topographically higher areas inland should be of a benign type due to recharge from precipitation in these areas.

Demand-storage percentages have been calculated in Table 2 and shown diagrammatically in Figure 12. This figure shows groundwater usage to be over 150 percent. At present it would be unrealistic to assume a constant demand of 500 gallons per day is required of every well; however, if only one-half of the 175 wells recorded in this region were utilized at this rate, a demand-storage figure over 75 percent would still indicate a definite problem area.

7.2 Lock Bay Region

Area - 2,188.9 acres

No. of drilled wells in region

- 197

No. of dug wells and springs utilized in region - 3

The average depth of overburden overlying bedreck is 10.5 feet and the average depth of drilled well determined as 75.5 feet. Well depths range from shallow dug wells to drilled depths of 325 feet.

Approximately 25 percent of this region is subdivided for present or future development. Most development exists along North Road inland at higher elevations and along coastal areas west of Lock Bay.

A good majority of wells drilled and recorded in this region are located west of Lock Bay (Figure 2) at elevations between 25 and 75 feet above sea level. The majority of these wells are less than 100 feet in depth and report excellent domestic yields greater than 10 gallons per minute (Figure 4).

The principal water-bearing formation along the coastal area west of Lock Bay is predominantly fractured and broken shale (Northumberland Shales). The fractured and broken nature of these shales and topography surrounding this area are favourable, resulting in numerous productive wells. Many wells in this area are situated on lots less than one-half acre in size and are located very close to the coastline. Wells in this area are closely spaced and mining or sea water intrusion could subsequently occur, particularly in the dry summer months when water demand is at its greatest. This particular area, west of Lock Bay, along the coast is being actively developed as approximately 20 new wells were constructed in this specific area in 1977.

The predominant water-bearing formation inland at higher elevations appears to be the contact zone between shale and sandstone sequences. The shale layering is probably broken and well-fractured and thus able to store and transmit groundwater in varying amounts. The sandstone appears to have no significant porosity or permeability and appears to be relatively massive.

Comparative yields inland to those along coastal regions are apparent.

Domestic yields in these areas range from moderate to excellent; however,

depths of wells inland are considerably greater in order to intercept groundwater movement through the fault and fracture zones.

Eight complete chemical analyses of groundwater quality are available showing water quality inland to be generally a soft, low to moderately

mineralized groundwater. Only two complete analyses are available from well water along coastal areas at lower elevation. Although no high chloride levels are apparent, mineralization is considerably greater. Sampling of selective wells along coastal areas at different times of the year may show evidence of sea water encroachment in these wells.

There is presently one <u>active</u> observation well (72-1) monitoring water levels within the boundaries of this region (Figure 9). Observation well 72-5, also within the boundaries of this region, was abandoned in August 1977. A detailed discussion on the construction and development of both wells and an attempt to analyse the hydrograph of Well 72-1 has been made and presented later in this report.

Demand-storage percentages have been calculated in Table 2 and shown diagrammatically in Figure 12. This figure shows groundwater use to be 70 percent of available groundwater in storage.

The low-lying coastal basin west of Lock Bay is very popular and has been and is continuing to be subjected to rapid growth.

7.3 Descanso Bay Region

Area - 1,420.9 acres

No. of drilled wells in region

~ 6ó

No. of dug wells and utilized springs in region - 5

The average depth of overburden overlying bedrock in this region is 5 feet, while well depths range from 8 feet to 537 feet (the deepest productive water well on record on Gabriola Island).

This region is at present not highly developed. The majority of wells are located inland on lots varying between 0.5 and 1 acre in size. The remaining wells are located along the coastline south of Taylor Bay and inland on larger parcels of land.

Well yields are reported as "poor" to as high as 40 U.S.gpm, while approximately 40 percent of the wells have been rated as capable of a potential of 10 gpm or greater. The majority of the wells rated 10 gpm and greater are located on a subdivision along the southern portion of the region. This subdivision is situated in a level valley area, about 300 feet above sea level and receives surface drainage from areas east and south of the subdivision.

In contrast, many wells located within S.E. Section 20 (Figure 2) are low to moderate yielding (less than 5 gpm).

Wells located south of Taylor Bay along the coastline have shown evidence of sea water encroachment with chloride values recorded as high as 550 parts per million.

Massive sandstone is the predominant bedrock type in this region (Gabriola Formation). The majority of drill logs show sandstone and thin shale layer sequences. Drill logs show both the sandstone and shale to be very capable of storing and transmitting groundwater. Conglomerate layering is evident in wells along the south coast and appears to be the principal water producer.

Four complete chemical analyses are on record from drilled wells in this region. This limited information shows groundwater from shallow wells, less than 100 feet in depth and completed at elevations above sea level, to be a soft, low mineralized groundwater.

A discussion on the details of well construction and analyses of the hydrograph plot for Observation Well 72-3 has been presented later in this report.

The demand-storage figure has been calculated at 37.8 percent for this region. This figure suggests there is no present danger of demand exceeding groundwater in storage.

In summary, excellent domestic yields can be expected throughout the southern portion of this region. Many potential well yields exceeding 10 gpm have been recorded near this area. Excellent possibilities for constructing a high productive well field definitely exist in this region. The majority of productive wells are between 50 and 150 feet in depth at an elevation of between 250 and 300 feet above sea level. Water quality does appear to deteriorate with well depth, Groundwater does not appear to be restricted to the shale interbedding as in some regions and the sandstone appears to be capable of storing and transmitting groundwater to provide excellent productive yields from shallow depths.

7.4 Gabriola Region

Area - 3,148.9 acres

No. of drilled wells in region

No. of dug wells and utilized springs in region - 1

The average depth of overburden overlying bedrock is 7.5 feet with well depths ranging between 12 and 275 feet.

Very little development has occurred in this region. Most wells are located on large tracts of land and are widely scattered.

The principal water-bearing material appears to be the contact zone between sandstone and shale sequences; however, many moderately productive wells have been reported to be drilled in the sandstone.

Well yields range between 0.6 U.S.gpm to 75 U.S.gpm (observation well 72-2 - the highest safe productive potential yield on record on Gabriola Island).

The few field chemical tests and complete analyses available show groundwater to be soft, low in mineralization in shallow wells inland, and soft, moderately high in mineralization from deeper wells at lower elevation. Water quality appears to deteriorate slightly with increased well depth.

Discussions on the details of well construction and development for observation wells 72-2 and 72-4 have been presented later in this report.

An attempt to analyse the hydrograph plot (Figure 11) has also been made for observation well 72-4.

A calculated demand-storage figure of <u>5.8 percent</u> (assuming saturated depth of 200 feet) indicates there is no present danger of groundwater with-drawal exceeding groundwater in storage.

In summary, a definite potential for drilling and developing good quality, high yielding production wells exists within this region.

7.5 Silva Bay Region

Area - 563.0 acres

No. of drilled wells in region

No. of dug wells and utilized springs in region - 3

Most development in this region is centered around Silva Bay, north of Whitney Road on lots between 0.5 and 1 acre in size.

48

The average depth of overburden overlying bedrock is 3 feet with well depths ranging between 9 feet and 200 feet. Many excellent potential yields have been reported from wells less than 100 feet in depth.

Well yields range between 0.25 gallon per minute and 26 gallons per minute, with the majority of yields reported as 5 gallons per minute or less near coastal areas.

The principal water-bearing formation is sandstone (Gabriola Formation).

Drill logs do not show the presence of fracture zones and it can only be assumed they are present where moderate to high yield potential wells are encountered. A few drill logs show shale layering between sandstone with this contact zone being the major producing zone.

A significant number of field chemical analyses have been performed on wells in the Silva Bay area. These analyses have shown definite evidence of sea water encroachment where chloride values as high as 1,050 ppm have been recorded from shallow drilled wells (Figure 5).

The majority of wells in the Silva Bay region are completed below sea level.

Chemical analysis has shown water quality inland to be basically soft, moderately mineralized groundwater with no evidence of sea water intrusion at present.

A demand-storage figure of 68.1 percent suggests serious consideration should be given to monitoring future groundwater development in the area surrounding Silva Bay. Sea water encroachment is already a problem along coastal areas. There is potential for construction of moderate to high yielding wells inland in this region. Well depths between 100 and 150 feet should result in yielding good quality groundwater.

7.6 North Degnen Bay Region

Area - 553.2 acres

No. of drilled wells in region - 30

No. of dug wells and utilized springs in region - 2

Most development in this region is centered around Degnen Bay,

The average depth of overburden overlying bedrock is 3 feet with well depths ranging from 8 feet to 202 feet. Most drilled wells around Degnen Bay are completed below sea level. Very few water quality analyses are presently available for this region. One well located in the east Degnen Bay area has, however, a reported chloride value of "greater than" 1,000 ppm, which may suggest the possibility of sea water encroachment in some wells along the coastline.

Excellent domestic yields have been reported along the Degnen Bay coastline; however, water quality may not be acceptable because of high chloride levels recorded in some wells in this area. Some moderately yielding wells completed near the coastline at elevations

below sea level have shown evidence of possible sea water intrusion. Many wells sampled reported chloride values exceeding 100 mg/L.

A demand-storage figure of 44.4 percent indicates no immediate danger of groundwater withdrawal exceeding natural recharge. Careful planning should be given to future groundwater development along coastal regions where sea water contamination could become a serious problem as is apparent in other more developed coastal areas.

7.7 West Degnen Bay Region

Area - 422.5 acres

No. of drilled wells in region

- 16

No. of dug wells and utilized springs in region - 3

Almost all groundwater development in this region surrounds the Degnen Bay coastline.

The average depth of overburden is 12 feet with surficial deposits (blue clay) as thick as 40 feet recorded near the west bay area. A few dug wells in this area are completed in creek beds and report good domestic yields.

Well depths range between 4 feet and 231 feet with yields ranging between 0.5 gpm and 25 gpm.

The principal water-bearing formation appears to be the contact zone between shale and sandstone sequences. Some thick formations of water-bearing shale can be seen inland from the Degnen Bay coastline (Spray shales).

Water quality analyses taken on wells west of Degnen Bay near the coastline have shown evidence of sea water encroachment (Figure 5).

The demand-storage figure of 34.5 percent indicates no immediate danger of groundwater withdrawal exceeding natural recharge. Once again, the dangers of future groundwater development on small coastal lots should be of concern where overpumping the bedrock fractures may eventually deteriorate water quality, especially during the dry summer months.

7.8 False Narrows Region

Area - 1,414.2 acres

No. of drilled wells in region

- 165

No. of dug wells and utilized springs in region - 13

The False Narrows Region is extensive, covering the southeastern coast of Gabriola Island and is highly developed along coastal areas. Over 500 acres of this region are subdivided for present or future development. Much of this acreage is subdivided into lots 1 acre or less in size.

The average depth of overburden overlying bedrock is 10 feet with well depths ranging between 5 and 250 feet (this range does not include a coal exploration hole drilled during the 1930's to a depth of 2,200 feet).

The principal water-bearing formation appears to be fractured shale (Northumberland Formation). These shale beds appear to be have been subjected to shear stress caused by folding and are consequently highly fractured. Sandstone appears capable of producing moderate domestic yields in the eastern portion of the region around the mouth of Degnen Bay.

Thick formations of clay overlying shale are common along the coastline with some surficial deposits (boulders, coarse gravel) as thick as 85 feet recorded inland within the Garland subdivision. These deposits, however,

generally have little water-bearing potential. One well completed in coarse gravel is reported to yield 10 gpm. The majority of drilled wells in the Garland subdivision are completed in fractured shales and produce moderate domestic yields (5 gpm and less).

Considerable groundwater development is apparent along the coastline west of Degnen Bay. This is a high well density area with yields reported from "poor" to 20 gpm. The majority of wells are completed at elevations below sea level, and are located on lots less than 1 acre in size.

Excellent yields have been reported inland at higher elevations and the Percy Anchorage area (Figure 2) near the 2,200-foot coal exploration hole drilled in the 1930's. Four wells were drilled in late 1971 to a depth of 100 feet and all penetrate fractured water-bearing shale beds. This well field is located in a meadow area (elevation 25 feet above sea level).

Three of the four wells were pump tested. The fourth well was not considered worthwhile to test as the driller bailed this well dry at 12 gpm. Very little water quality data is available in this region. A few chemical analyses of groundwater are available from areas inland and along coastal areas near Percy Anchorage. These analyses have shown groundwater to be low in hardness, moderately to rather highly mineralized. The only sign of sea water encroachment is in a well adjacent to the Percy Anchorage coastline. The higher levels of chloride (200-480 ppm) suggest that this well is drawing water from a deeper zone than is used by the adjacent wells in the same shale formation.

Sea water intrusion is evident at the mouth of Degnen Bay along the western coastline fringe where chloride values from wells have been recorded

as high as 3,050 ppm and T.D.S. values as high as 8,000 ppm.

A demand-storage figure of 96.6 percent has been calculated. Once again, this figure may be relatively high assuming 500 gpd is required of every well recorded in the region. As stated previously, however, the relative value of this figure is considered to be valid and does serve to point out problem areas.

In summary, this region is highly developed, particularly along the coastline. Although little evidence of well interference and sea water encroachment is presently available, well density in this area suggests this could be a definite problem.

This region has proven potential for construction of a moderate to highly productive well field. Production wells should, however, be sited at higher elevations inland as far as is practical away from low-lying coastal areas.

7.9 Hoggan Lake Region

Area - 1,977,7 acres

No. of drilled wells in region

- 20

No. of dug wells and utilized springs in region - 2

Most development exists within the Wildwood Estates subdivisions in the northwestern portion of the region. The average depth of overburden overlying bedrock is 4.5 feet with wells ranging in depth between 60 and 245 feet. Reported well yields range from 10 gallons per hour to 50 gallons per minute.

Both the sandstone and shale appear capable of yielding moderate to high quantities of groundwater. Sandstone and shale layering is common in this region, and drill logs indicate the contact zone between shale and sandstone may be a major producing zone. Excellent yields have been reported within the Wildwood Estates property. Yields as high as 50 gpm from relatively shallow depth wells (130-140 feet) are on record. Drill logs show bedrock to be highly fractured with excellent water-bearing potential. Topography in the area is favourable, promoting surface and subsurface groundwater movement.

Chemical analyses shows groundwater in this area to be generally soft and moderately mineralized.

Very little groundwater data is presently available in other portions of this region.

Hoggan Lake was formed by the construction of a dam in the early 1900's that backed water into a previous wetland. The lake which is about 40 feet deep and covers approximately 59 acres may have potential as a major water supply for the southwest corner of Gabriola Island. It is, however, situated on privately owned property.

In summary, excellent potential for groundwater development exists in the northwestern portion of this region. No groundwater data is presently available at higher elevations surrounding the Wildwood Estates subdivisions.

7.10 Northumberland Channel Region

Area - 204.9 acres

No, of drilled wells in region

÷ 2

No. of dug wells and utilized springs in region - -

The Northumberland Channel Region covers a narrow strip of land along the southwestern coast of the Island. Some development exists along the western portion of the region; however, the eastern portion is bounded by steep cliffs with little potential for development. Almost no information is available on groundwater quantity or quality in this region.

7.11 South Descanso Bay Region

Area - 339.2 acres

No. of drilled wells in region

47

No. of dug wells and utilized springs in region - 2

The South Descanso Region has been heavily subdivided and is almost totally divided into lots one acre and less in size. The average depth of overburden overlying bedrock is 5.5 feet with well depths ranging between 12 feet and 300 feet.

Sandstone and shale sequences are common inland in this region while sandstone and conglomerate layering is common along coastal regions, particularly in the Descanso Bay area. Drill logs indicate the contact zone between these sequences is the major water-producing zone. Yields in this region are reported to range from "poor supply" to 32 gpm.

In the past, a well field was designed and constructed to provide domestic water to future residents in the South Descanso Region. This particular area is located in a low-lying meadow area but insufficient water was obtained to meet the requirements of the development of that time.

Numerous domestic wells have since been drilled on private lots to the east of the meadow area at higher elevations with varying results. Most wells

reporting good domestic yields are shallow, generally less than 100 feet in depth, while deeper wells have not shown significant increases in potential yields. Pumping levels of many of the wells inland are above sea level.

Wells located around Descanso Bay are subject to sea water intrusion. Most of these wells are completed below sea level and once the fresh water head is lowered through pumping, sea water may enter the water-bearing zone. Chloride values as high as 250 ppm have been recorded in the Descanso Bay area.

At present the number of wells on record as theoretically extracting 500 gallons per day has indicated groundwater withdrawals are exceeding groundwater in storage. A demand-storage percentage of 108.6 percent has been calculated for the region. This particular region has been substantially subdivided in the past and if domestic wells were constructed on each lot excessive groundwater withdrawals could present a real problem, particularly in the dry summer period when water levels are at or near their lowest. Some potentially high yielding wells have been constructed to the east of this subdivision.

8. GROUNDWATER QUALITY

Natural groundwater quality is emphasized in this report and pollution aspects apart from natural sources such as sea water, for example, have not been analyzed.

Approximately 75 complete chemical analyses of groundwater have been done on Gabriola Island, as well as numerous field (Hach) analyses.

These analyses have shown groundwater on Gabriola Island to be basically a good quality, soft, low to moderately mineralized water in areas of higher elevation, while higher mineralized groundwater is apparent at lower elevations. This is particularly evident along coastal regions where wells are subject to sea water encroachment. The majority of wells sampled for complete chemical analyses are less than 200 feet in depth.

A computer plot has shown a correlation coefficient of around 0.6 between Total Dissolved Solids and total depth of well (Figure 8). This figure would indicate a relationship between T.D.S. and depth does exist; however, this is not overly evident. A more apparent T.D.S.-depth relationship would probably be evident if similar depth wells were located in topographically similar areas.

9. OBSERVATION WELLS

At present there are three observation wells on Gabriola Island
(Figure 9) that are being actively monitored, either manually by an observer
or with automatic water level chart recorders.

Five test wells were originally drilled during the 1972 drilling program and four of the five wells have been monitored for at least part of the time during the period 1973-78. Observation well 72-2 has never been monitored due mainly because of a flowing artesian condition (water level + 10 feet above ground level at time of well completion), necessitating the capping of this well.

A brief discussion on the current status of the Gabriola Island observation wells has been presented below. Wherever length and consistency of record has permitted, an attempt has been made to try and correlate water

level fluctuation with periods of high and low precipitation and/or pumping in the area.

9.1 Observation Well 72-1

Description: Section 14, Well No. 3
Depth 325 feet
Site I.D. 1400064

This well is located in the Lock Bay region and was drilled in 1972 by the air rotary method. It was pump tested for 1,000 minutes.

Based upon the results of this pump test, the safe productive yield was rated at 10 U.S.gpm. It is located inland in N.E. section 14 at an elevation of 325 feet above sea level (Figure 9).

Interpretation of this water level hydrograph is difficult in that measurements are taken on a once per month basis and also water levels may be influenced from nearby pumping.

Peak water levels do, however, correspond to periods of high precipitation, although response is slow, with a time lag of about one month (Figure 11). This slow response to precipitation may indicate that the well is not responding to a local flow system, but rather to a deeper flow system. Water Quality shows a moderately mineralized calcium bicarbonate type groundwater deeper flow system; however, more extensive sampling would have to be done before this can be confirmed. The major water-bearing formation intercepted is 215 feet below ground level.

It is recommended that an automatic water level recorder be installed on this well, as past experience has shown that manual readings can be misleading taken on a once per month basis on a well suspected of being influenced from nearby pumping.

9.2 Observation Well 72-2

Description: Section 6, Well No. 5

Depth 275 feet Site I.D. 1400060

Observation well 72-2 is located in the eastern end of the Island along Peterson Road at an elevation of 120 feet above sea level (Figure 9). The well was drilled in 1972 by the air rotary method and pumped at a rate of 70 U.S.gpm for 1,400 minutes. Based upon available data, the well was rated at 75 U.S.gpm.

An artesian flowing condition (calculated head at time of well completion was 10 feet above ground level) necessitated capping of this well.

9.3 Observation Well 72-3

Description: Section 19, Well No. 7

Depth 250 feet Site I.D. 1400067

Observation well 72-3 is located in the Ministry of Highways yard off North Road at an elevation of 305 feet above sea level (Figure 9). The well was drilled in 1972 by the air rotary method and was pumped at 50 U.S.gpm for 1,500 minutes. The safe productive yield of this well was calculated at between 35 and 40 U.S.gpm.

The well is equipped with an automatic water level recorder and has been continually monitored since 1973.

Analyses of the water level data has shown that although annual seasonal fluctuation can readily be seen, water level is definitely being influenced from nearby pumping. The Gabriola school well, located approximately 600 feet east, is most probably the influencing well. Similar water levels in both

wells further supports this assumption. The water level data has also shown that there is no evidence of any overpumping of this aquifer at this time.

9.4 Observation Well 72-4

Description: Section 16, Well No. 1

Depth 275 feet Site I.D. 1400061

Observation well 72-4 is located near the middle of the Gabriola region along North Road at an elevation of 210 feet above sea level (Figure 9). The well was drilled in 1972 by the air rotary method and no pump test was conducted. At the time of drilling the well yield was estimated to be 3 U.S.gpm. Attempts to improve the yield by surging were not successful.

All available manual water level data collected to date has been presented in this report (Figure 11). An automatic water level recorder was installed on this well in August 1977.

The hydrograph (Figure 10) shows water level does correspond with precipitation; however, peak water levels lag behind peak periods of precipitation by about one month.

The water level has continued to rise in this well since initially drilled in 1972. The low point in the hydrograph record was reached at about 31.5 feet in October 1973. A definite pattern of rising water level can readily be seen with the low point in October 1977 recorded as 21.7 feet below ground level.

Both observation wells (72-2 and 72-4) have been sampled for complete chemical analysis. Although the water quality of well 72-2 shows a more alkaline, higher mineralized water than well 72-4, a Schoeller plot has shown both groundwaters to be of a similar type (Figure 7), and possibly within the

same flow system. The sample showing higher parameter values (seen in observation well 72-2) would be expected to be located in the lower end of the flow system. The topographic location and flowing artesian condition seen in 72-2 tends to support this assumption. The higher yield and flowing artesian condition and more rapid movement of the groundwater through the fracture system may account for the lower mineralized groundwater found in well 72-4.

9.5 Observation Well 72-5 (Figure 9)

Description: Section 22, Well No. 44
Depth 325 feet
Site I.D. 1400063

Observation well 72-5, also within the boundaries of this region, was abandoned in August 1977. The well was drilled in 1972 by the air rotary method and was pumped for 1,500 minutes. The safe productive yield was calculated at 20 U.S.gpm.

The well was equipped with an automatic water level recorder from June 1973 to August 1977.

10. CONCLUSIONS

(a) Groundwater inland on Gabriola Island is generally of a benign type, being a relatively soft, moderately mineralized type groundwater. Total Dissolved Solids in wells sampled inland is generally below 250 mg/L. Higher mineralized water is evident along coastal regions where T.D.S. values are as high as 5,800 mg/L. This particular sample was taken from a well located on the western coastline fringe of Degnen Bay. This highly mineralized water is usually associated with sea water intrusion. A combination of continuing development, lack of summer recharge and

nature of the local bedrock has contributed to deterioration of water quality in some areas. Areas where sea water encroachment is apparent are Silva Bay, Degnen Bay, east of Lock Bay, and particularly the Pilot-Taylor Bay area.

- (b) Approximately 10 to 15 percent of drilled wells on Gabriola Island have been reported by the well drillers to be capable of yielding over 10 gallons per minute.
- (c) Approximately 85 percent of groundwater utilized on Gabriola Island is from drilled wells with the principal aquifer reported as fractured shales and sandstones.
- (d) Bedrock wells range in depth from 5-foot dug wells to 537-foot drilled wells.
- (e) Well yields range from 1 gallon per hour to 75 U.S. gallons per minute.
- (f) A relationship showing increasing mineralization with increasing well depth appears to exist up to depths of around 200 feet (Figure 8).

 Further investigations may show a T.D.S. depth relationship is even more evident in deeper wells.
- (g) Successful well fields have been developed to supply water to subdivisions on the Island. Specific well sites have shown potential for greater groundwater development, while some areas have shown potential for developing higher capacity well yields. These areas are, however, limited and in some cases quite far from the more populated coastal regions.

(h) Demand-storage percentages have been calculated for each groundwater region. On the basis of 500 gpd per well, those regions considered to be at present critical are the Sands, False Narrows and South Descanso Bay regions. Those regions that are becoming critical as groundwater development continues are the Lock Bay and Silva Bay regions. The remaining regions appear to have adequate groundwater in storage to meet additional water demands.

11. RECOMMENDATIONS

- (1) Further groundwater development along the coastal areas of the Sands,
 Lock Bay, South Descanso Bay, False Narrows, Degnen Bays and Silva Bay
 regions should be carefully planned. Further deterioration of the
 groundwater resource may occur in these areas due to sea water encroachment or well interference problems.
- (2) Additional potential for development of the groundwater resource exists within the Hoggan Lake, Descanso Bay and Gabriola regions, and inland in the Lock Bay, Degnen Bays and Silva Bay regions.
- (3) Additional investigations are warranted to determine with more certainty the productivity of the fault and fracture systems on Gabriola Island, and the role of major fault zones on groundwater movement on the island.
- (4) Some additional programs which should be considered are:
 - (i) A water quality program should be initiated on Gabriola Island, particularly along coastal regions to obtain more up-to-date

information on groundwater quality. Very little information is presently available on water quality from wells drilled during the past few years.

- (ii) Well 72-2 should be monitored on a regular basis. The location and importance of this high yielding aquifer (the productive yield of this well was determined as 75 U.S.gpm) warrants monitoring of the shut-in pressure head at least once per month.

 (The artesian head at time of well construction was estimated to be 10 feet above ground.)
- (iii) A pump test should be conducted on observation well 72-4 (Weldwood of Canada) in the near future; water level in this well has continued to rise since initially drilled in 1972.

12. REFERENCES

- B.C. Ministry of Agriculture, Climate of B.C., Tables of Temperatures, Precipitation and Sunshine, 1968-1977.
- Brown, W. L. and Erdman, R. B. 1975. Habitat of Groundwater on Gabriola Island, B.C. Report prepared for Department of Lands, Forests and Water Resources, Groundwater Division, Water Investigations Branch, File 92-G-4.
- Brown, W. L. and Dakin, R. A. 1972. Regional Groundwater Study Gabriola

 Island and Nanoose Peninsula (Part A-Gabriola Island) for the Regional

 District of Nanaimo.

- Foweraker, J. C. 1974. Groundwater Investigations on Mayne Island.

 Report No. 1, Evaluation, Development and Management of the Groundwater

 Resource on Mayne Island. Groundwater Division, Water Investigations


 Branch, Department of Lands, Forests and Water Resources.
- Muller, J. E. and Jeletzky, J. A. 1970. Geology of the Upper Cretaceous


 Nanaimo Group, Vancouver Island and Gulf Islands, B.C. Geological


 Survey of Canada, Paper 69-25.
- Oswald, E. T. 1978. Gabriola Island and Neighbouring Islands; A Landscape
 Analysis. Environment Canada, Forestry Service.
- Walton, W. C. 1970. Groundwater Resource Evaluation. McGraw Hill Book Co.

U.S. Hodge.

W. S. Hodge
Technician
Groundwater Section
Hydrology Division
Water Investigations Branch
Ministry of the Environment









Geology Map.


WATER INVESTIGATIONS BRANCH

() I

... DWG. No. FIGURE ..







Dr. by W. Hodge

LEGEND



Chloride value 800

- Well depth

Wells with Known chloride values greater than 100 mg./L

to Chloride value of sampled well .


BRITISH COLUMBIA MINISTRY OF THE ENVIRONMENT ENVIRONMENTAL AND ENGINEERING SERVICES WATER INVESTIGATIONS BRANCH


TO ACCOMPANY REPORT ON Gabriola Island -Map showing chlorides exceeding 100 Mg./L. SCALE: VERT. As shown HOR AS Shown

Aug. 1978

DATE


. DWG. No. Figure FILE No.





DR. by W. Hodge

LEGEND



Wells with known chlorides values greater than 100 mg/l wirde size is proportionate to chloride value of sampled well.

SCALE: VERT. As shown

DATE


HOR As shown


AUG. 1978


DWG. No. Figure 6.


BRITISH COLUMBIA MINISTRY OF THE ENVIRONMENT ENVIRONMENTAL AND ENGINEERING SERVICES WATER INVESTIGATIONS BRANCH


TO ACCOMPANY REPORT ON Gabriola Island -Map showing chlorides














											Control of the Contro
WATERS 'ED	SECTION	WELL No.	WELL DUG	DEPTH DRILL	5.W.L.	DEPTH TO * W.B.Z.	WELL HEAD ELEVATION	1	DESCRIPTION OF MATERIAL	REPORTED YIELD	REMARKS
Sonds	21	/		204		14-5'	25'	2 ′	Sandstone - Shaley	10 9ph	
0	21	2	•	170'	4'	17 5 164	20'	10'	Sandstone	2.19pm	layered sandstone ishele - Hach chem.
	21	3		171	o'	151 : 165	20'	4'8"	Sandstone: shale	1 9pm	" "
	21	4		172'	4	166'	2/	bedrock ESLATE	Shale	129ph	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
	21	5		185'	60'	175'	£ 2/	2'	shale	20 gph	" "
	21	6		60'	z'	23'. .'35'	35'	7'	Sandstone	20 gpm	
	21	7		75'	28'	70'	30'	13'	Shale	2/4 gpm	HACH CHEM DONE.
	21	.8		.40'	19'	24'	30′	≈8'?	shake .	1.5 gpm	,, ,,
	21	9 .		78'	35'	66'	31 '	²20' ?	shale	.5 gpm	salty water -
	21	10	•	247	30	101	37'	7'	Sandstone	1 9pm	water undinkable - coal gas smell.
	21 .	11	30'	. `	15'	. 7	31	-	bedrock?	2.	no log reports good.
	21	12	20'		16'	?	28′	?		_	good quality water
	.21	13		175	-}-	175	19'	15	Sondstone ; shale	1 4 gpm	NACH CHEM. DONE - Layered Sendstone 1 de
	21	14	24'		20'	?	43'	?	side	_	has gonedry
	2./	15		60'		. 7	20'	7'4"	Sandstone: Stale		VKY HOLE
•	2./	16.	23'	·	20'	?	38		?		POCK SUPPLY
	21	17'	36'		22	?	44'	o ?	BEXOCK.		POOK SUPPLY - HACH CHEM. DONE
**.							e Toma agree on Toma agree and agree or an				* Water bearing Town - 1862 7.

WELL DEPTH DEPTH DESCRIPTION CASING REPORTED WELL 5.W.L. WELL HEAD REMARKS WATERSHED SECTION LENGTH OF MATERIAL YIELD ELEVATION No. DUG DRILL W.B.Z. 16' Sandstone 118 15' 5' udb 1 Water Sally Sands 116 18 21 19 22 ' 0 ? Sandstone bedrock Oserface 60 9ph 21 132 49 9': 21 20 33 ' Sandstone 9 0.4 97171 75 4. 40' Sandstone w/ Layers shale poor quali 21 21 35' Sandstone 173 19900 *9*0' Hach done-poor quality 100' 10' 30 ' sholey sandstone 20 gph 21 . 22 ? 6'6" sondstone 92' 8' 50' 30 gph 21 23 63! 25' 15' 24 Sandstone : shale 129pm 21 160 Sulphur smell pumping level @ 10 gpm = 25' 20' ? 180 Shale-sondstone 21 25 159pm water quite sulphury - some gas excellent details on log. Hack done 118' 25' shale -sandstone 5gpm 26 21 30' -12' 24 shale & sondstone 4 9000 27 90 21 poor quality - HACH DONE *3*0' 10 21 Sandstone 500 gpd 28 270 200 8' well gone dry - iron 34 9pm 175 160 21 29 *3*o' Sandstone 6' 270' 20' 14' 21 20 gpt Sandstone 30 270' Sandstone willowers 170.745 21 3/ 30' Well apparently not being wied 252 35 10900 25' Zgpm 45 0 Sandstone 21 *3*z Sandstone , shale 8' DRY HOLE - copped 60' 264 21 33 25' 70' 21 9/2 sondstone , shale 8Z 20' 34 * Water bearing Zone - W.B.Z.

WATERSHED SecrieN Well Well Depth Siml Depth Well Head Casino Description Repaired No. 200 Daill Well State State					<u></u>	07.07.17						
21 36 40' 3' 25' 60' 8' Shele sendstone 59pm 21 37 130' 40' 120' 30' 8' Shele sendstone 129th MACH YOUR 21 38 80' 15' 80' 25' 5' Sandstone 39pm 21 39 105' 36' 84'96' 25' 6' Sandstone shele 2'29pm 21 40 58' 20' 50'\$ 30' 6' Sandstone shele 49pm 21 41 80' 7 45'80 50' 8' Shele sandstone 129pm 21 42 2 4 100' 15' 6'55' 125' 4' Shele sandstone 5'kgpm 21 44 100' 15' 6'55' 125' 4' Shele sandstone 5'kgpm 21 45 54' 2' 25'50 60' 7' Sandstone 15hele 79pm 21 46 300' 5' 170' 50' 6' Sandstone 123pm 21 48 110' 15' 100' 20' 6' Sandstone 10'129pm 21 48 110' 15' 100' 20' 6' Sandstone 15hele 15pph 21 49 60' 5' 12160' 30' 8' Sandstone 15hele 5'kgpm 21 50' 26' 6' Sandstone 15hele 15pph 21 50' 26' 6' Sandstone 15hele 5'kgpm	WATERSHED	SECTION				5.W.L.	70 x		1 .	1		REMARKS
21 36 40' 3' 25' 60' 8' Shele sendstone 59pm 21 37 130' 40' 120' 30' 8' Shele sendstone 129th MACH DOWS 21 38 80' 15' 80' 25' 5' Sandstone 39pm 21 39 105' 36' 94'96' 25' 6' Sandstone shele 2'29pm 21 40 58' 20' 50'.5. 30' 6' Sandstone shele 4'9pm 21 41 80' 7 45'.80 50' 8' Shele sandstone 1'29pm 21 42 21 43. 21 44 100' 15' 6.5. 125' 4' Shele sandstone 5'kgem 21 45 54' 2' 25 150 60' 7' Sandstone shele 79pm 21 46 300' 5' 170' 50' 6' Sandstone 2.3 9ph 21 48 110' 15' 100' 20' 6' Sandstone 10'129pm 21 48 110' 15' 100' 20' 6' Sandstone 15'kele 15'gpm 21 49 60' 5' 12160' 30' 8' Sandstone 15'kele 15'gpm 21 50' 26 Sandstone 15'kele 15'gpm 21 50' 26' Sandstone 15'kele 15'gpm 21 50' 26' Sandstone 15'kele 15'gpm 21 50' 26' Sandstone 15'kele 5'kgpm	Sands	21	<i>35</i>		60'	8'		25	.?	Shale sandstone	6 9pm	NOT IN USE
21 38 80' 15' 80' 25' 5' Sandstone 39pm 21 39 105' 36' 94;96' 25' 6' Sandstone; shale 2'29pm 21 40 58' 20' 50:5, 30' 6' Sandstone; shale 49pm 21 41 80' ? 45:80 50' 8' Shale; sandstone 1/2 9pm 21 42 21 43. 21 44 100' 15' 60; 125' 4' Shale; sandstone 5'29pm 21 45 54' 2' 25 150' 60' 7' Sandstone 15hale 79pm 21 46 30' 5' 170' 50' 6' Sandstone 2:3 9ph 21 47 174' 25' 160' 30' 10' Sandstone 10-12 9pm 21 48 110' 15' 100' 20' 6' Sandstone 15hale 159ph 21 49 60' 5' 12:60' 30' 8' Sandstone 5'2 9pm 21 50' 8 Sandstone 15hale 5'2 9pm		2/	36		40'	3'	25'		8'	Shole + Sondstone	59pm	
21 39 105' 36' 94; 96' 25' 6' Sandstone; shale 2'sgmn 21 40 58' 20' 50; 55 30' 6' Sandstone; shale 49mn 21 41 80' 7 45; 80 50' 8' Shale; sandstone 12 9pm 21 42		21	37		130'	40'	120'	<i>3</i> o′	8'	shale - sandstone	1292	HACH DONE
21 40 58' 20' 50:5 30' 6' Sandstone iskele 492m 21 41 80' ? 45:80 50' 8' Shale i sandstone 1/2 9pm 21 42 21 43. 21 44 100' 15' 60 5.90 125' 4' Shale i sandstone 5'2 9pm 21 45 54' 2' 25:150' 60' 7' Sandstone 15 14 9pm 21 46 300' 5' 170' 50' 6' Sandstone 2.3 9ph 21 47 174' 25' 160' 30' 10' Sandstone 10-12 9pm 21 48 110' 15' 100' 20' 6' Sandstone 15 16 16 15 9ph 21 49 60' 5' 12:160' 30' 8' Sandstone - shale 5'2 9pm 21 50 8 26 6' 6' 60' ? no log —		21	38		80'	15,	පිර '	25'	5'	sandstone	39pm	
21 41 80' ? 45.80 50' 8' Shale i sandstone 1/2 gpm 21 42 21 43. 21 44 100' 15' 6.85.80 125' 4' Shale i sandstone 5 1/2 gpm 21 45 54' 2' 25 150' 60' 7' sandstone 15 hole 7 gpm 21 46 300' 5' 170' 50' 6' sandstone 2.3 gph 21 47 174' 25' 160' 30' 10' Sandstone 10-12 gpm 21 48 110' 15' 100' 20' 6' Sandstone 15 hole 15 gph 21 49 60' 5' 12 160' 30' 8' Sandstone - shale 5' 1/2 gpm 21 50 8 1/5 10' 10' 10' 20' 6' Sandstone 5 1/2 gpm		21	39		105'	36'	94:96'	25'	6'	sandstone: shale	2/29000	
21 42 100' 15' 60 125' 4' Shale sandstone 5' / 2 / 2 / 150' 60' 7' sandstone shale 7 / 2 / 2 / 2 / 2 / 50' 6' sandstone 2 / 3 / 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2 /		21	40		58'	20'	50:5%	30′	6'	Sandstone iskale	49900	
21 43. 21 44 100' 15' 60 55.70 125' 4' Shale i sandstone 5' 2 grm 21 45 54' 2' 25 150' 60' 7' sandstone 5' 2 grm 21 46 300' 5' 170' 50' 6' sandstone 2.3 gph 21 47 174' 25' 160' 30' 10' sandstone 10-12 gpm 21 48 110' 15' 100' 20' 6' sandstone 1 shale 15 gph 21 49 60' 5' 12 160' 30' 8' sandstone 5' 2 gpm 21 50 8 26 6' 6' 60' ? no log —		21	41		80'	?	45:80	50	ළ '	shale isondstone	1/2 9/111	
21 44 100' 15' 60 . 75 90 125' 4' Shale + sandstone 5'29pm 21 45 54' 2' 25 150' 60' 7' sandstone + shale 79pm 21 46 300' 5' 170' 50' 6' sandstone 2-3 9ph 21 47 174' 25' 160' 30' 10' Sandstone 10-129pm 21 48 110' 15' 100' 20' 6' Sandstone 15hale 159ph 21 49 60' 5' 12 160' 30' 8' Sandstone - shale 5'2 9pm 21 50 8 26 6' 6' 60' ? no log —		21 .	42				k ,	· · · · · · · · · · · · · · · · · · ·				
21 45 54' 2' 25 150' 60' 7' sandstone shele 79pm 21 46 300' 5' 170' 50' 6' sandstone 2-3 9ph 21 47 174' 25' 160' 30' 10' Sandstone 10-12 9pm 21 48 110' 15' 100' 20' 6' sandstone 15 sph 21 49 60' 5' 12 160' 30' 8' sandstone 5'2 9pm 21 50 8 26 6' 6' 60' ? no log —		21	43	<u> </u>								
21 46 300' 5' 170' 50' 6' sandstone 2-3 gph 21 47 174' 25' 160' 30' 10' Sandstone 10-12 gpm 21 48 110' 15' 100' 20' 6' Sandstone 15 hale 15 gph 21 49 60' 5' 12 160' 30' 8' Sandstone 5'x gpm 21 50\frac{8}{3} \frac{15}{26} \frac{10'}{6'} \frac{10}{6} \frac{10'}{6'} \frac{10}{20'} 10		21	44		100'	15'	. 85-90	125'	4'	shale , sondtone	5 /2 grm	
21 47 174' 25' 160' 30' 10' Sandstone 10-129pm 21 48 110' 15' 100' 20' 6' Sandstone 1 shale 159ph 21 49 60' 5' 12:60' 30' 8' Sandstone - shale 5'k 9pm 21 50 8 26 6' 6' 7 no log —		2/	45		54	2'	25 150	60'	7'	sandstone shale	7 9000	
21 48 110' 15' 100' 20' 6' Sandstone 1 shale 159ph 21 49 60' 5' 12:60' 30' 8' Sandstone - shale 5'x gpm 21 50 8 26 6' 6' 60' ? no log —		21	46		300'	5'	170'	50'	6'	sandstone	2-3 gph	
21 49 60° 5′ 12:60° 30′ 8′ Sandstone-state 5′2 gpm 21 50° 26 6′ 6′ 60° ? no log —		21	47		174'	25'	160'	30'	10'	Sandstone	10-12 gpm	
21 50B 26 6' 60' ? nolog -		2.1	48	,	110'	15'	100'	20'	6'	Sandstone 1 shale	159ph	1
21 50B 26 6' 60' ? nolog' -		21	49		60	5'	12 160	30'	8'	sandatone-stale	5 % gpm	
		21	50 B	1		10'			?	nolog		
21 51 180 ! 100 ! 6 4pm Sulphur smell	1	2/	5/	,	180	?	100'	10'	?	" "	6 9pm	Sulphur smell .
* Water bearing Zone - W.3.2										The state of the s		* Water bearing Zone W.B.Z.

VATERSHED	SECTION	WELL No.	WELL DUG	DEPTH DRILL	5.W.L.	DEPTH To ** W.B.Z.	WELL HEAD ELEVATION	1	DESCRIPTION OF MATERIAL	REPORTED YIELD	REMARKS
Sands	21	52		170'.		162'	25'	6'	Sondatone s shale	1901	·
	21	53		30'	رح	16'	25'		_	3-4 gph	
•	21 ·	54		110	3'	94'	25'	8'	sandstone rshale	29pm	POOR quality di>1000 ppm
	21	55		174	?	52 1171	15'	8'	sandstone -shale	30 - 50 92	
	21	56		280'	30'	178'	20'	52'	sandstone	495%	not used
	21	57		120'	15'	115'	20'	4/2'	sandstone	79900	HACH DONE CI 71000 PPM.
	21	58		240'	?	?	50'	8'	Sandstone - skale	29 ph	
	21	59		. z92	15'	280 -	15'	4'	sonddone - shale	10-12900	
	21 .	60		298	35'	280	60'	41/2.	shale	3 9pm	HACH DONE childe 1950 pm
	21	61	•	125	30'	120	30'	6'	sandstone - shale	19pm.	
	21	62		418	40'	. 151	60'	5'6"	Stoley sandstone	29917	
•	21	63		196'	?	154'	60'	3'	sontaine we layers	1	
	21	64	\$2'	·	7'	12'	40'	?	shale	- 1	
	21	65'		105'	?	97'	?	. 6'	shaley sandstone	39pm	
	21	66		105	5'	96'	.7	5'	shale	1/2 9 pm	SITE 17 1400301
	21	67		150'	40'	140'		6'	sandstone	149000	
	21	68	,	115'	15'	85'105		3'	sonostone i llay	1.59000	
1											* Water bearing Zone - W.B.Z.

DEC. 1977

GABRIOLA ISLAND WELL INVENTORY, TABLE NO. 1 - HYDROGEOLOGICAL DATA

							,				
WATERSHED	SECTION	WELL No.	WELL DUG	DEPTH DRILL	5.W.L.	DEPTH TO # W.B.Z.	WELL HEAD ELEVATION	1	DESCRIPTION OF MATERIAL	REPORTED YIELD	REMARKS
Silva Bay	5	35		110	20'	80'	65	5	Sanddone · shale	49000	
i	5	36			<u> </u>						
1	5	37		120'	7.	?	?	7'	shale	18970	
	5	38		90'	12'	45:90	?	20'	sanddone ishale	15 gpm	
	5	39		125'	30'	73 1118	?	6'	sandstone: shale	69700	HACH ANALYSIS DOVE
	5	40		50'	3'	25 :40	?	12'	Sandatione	29pm	
	5	41	. '	70'	2′	90:60	, ?	ي و	Conglomerale	25 gpm	
	5	42		85'	30'	80'	? .	7.	Sandobone	349pm	
	5	43						·			
	5	14-	18'	7	7	. 7	?	7.			ETTE D 1400316
	5	45		200'	30'	43-95-130	110'	21/2'	Shale isandstone	10 gpm	
	5	46		115	•	40'-109'	· ·	2'	Santatione : shale		
	5	47		124'		95+115'	? .	9'	Conglomerate	1/2 gpm	
	5	48		130	35'	95175	?	4'	1. 10	5gm	
	5	49	-	109	40'	101	?	3'		5 gpm	
İ	4	6	'	100			25	 		:	SME 1) 1400296
	4	19	 	90'				8'	Simulatione state	İ	SIE 19 14002715
	4	20		95'		50'-85'95	1	-5'	shale I sondone		* Water bearing Zone - W.3.Z.
·	1./1		. '			1			See that a man and a single real man and demonstrate to the second section of the section of the sectio	1 2/1	A graduation control of the control

			•	P	
GARRIOLA	TELANTO	WELL TANKENTORY	TARIF No. 1	-	HYDROGEOLOGICAL DATA
GABAIDEA	エンニーハマン		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		

VATERSHED	SECTION	WELL No.	WELL DUG	DEPTH DRILL	S.W.L.	DEPTH TO # W.S.Z.	WELL HEAD ELEVATION	CASING LENGTH	DESCRIPTION I OF MATERIAL	REPORTED YIELD	<u> Pemarks</u>
Vocate Degre	1	14		144	? .	?	25 ′	8'	Sanctione	5gom	
BAY	1	·18'		202	63	193	70	10	Sandstone	wd601	
6	1	19		83'	57'	'63 '	60	3.5	Simulatione; shale	1.5 gpm	SITE ID 1400298 HACH AMALYOU
	1	20		110	3'	20 0 100	65'	4.	Sandstone	59pm	
·	,	.40		175	40	140' 169	?	6'	Sandtone	3.5 gm	
	,	42		/35	40'	110 :125.	?	3'	Sondotone i State	2 /2 gpm	HACH DOVE
L	/	61		160		105:1144'		з′	sandstoner shale	1/4 gpm	
	/	66		160	65'	140:153	?	6'	shale s'sunddone	129000	
	4.	1.	28'		14.	?	?	?	TILL	good singly	- Litled in
	4-	2		147	32'	101:126	35'	3'	Sanddoner shake	2.3 gpm	
	4	3	,	60'	23'	33 / 52 ' 55 / 58 '	30'	7	Sandstone Eshale	2 /29pm	7
	4	4		60'	17	33'	35'	4/2.	Shale	2 gpm	
• •	4	5		100'	55'	?	80'	?	Sandstone wishale	4900	
	4	7.		120	9'	?	40'	3'	Sandstone.	1/2 gpm	
***	7.	8		20'	16'	62:82	50'	3/2'	Sandstone	+109pm	
	4	9		60'	10-15	58'	35'	?	"	3 <i>g</i> pm	
	4	10		135'	15'	D\$130	40'	5'	Somdetine; shale	2 gpm	
					a subtract for historia				contract of the second	1 1800 11 11 11 11 11 11 11	* Weter bearing Zone - W.3.Z.
	,		,		,	,			•		

* DEC. 1977

					•	
GABRIOLA	ISLAND	WELL INVENTORY.	TABLE NO. 1	•	HYDROGEOLOGICAL J	ΔTA
					· · · · · · · · · · · · · · · · · · ·	

											
WATERSHED	Section	WELL No.	WELL DUG	DEPTH DRILL	5.W.L.	DEPTH TO # W.B.Z.	WELL HEAD ELEVATION	1	DESCRIPTION OF MATERIAL	REPORTED YIELD	TIEMARKS_
NerthDegren	4.	li .		130	70'	70 /123	30'	4'	sorbdone i chale	12 gpm	
CAY	4	12		150	50'	30:75:13	0 80'	4'	Son Stone . Stale	2/2980	
	4	18		150'	50'	125950	?	?	Sandatona shale	1/2 gpm	
	4	2/		90'	20'	82'	?	7'	Sontative state	41/2 gpm	7
!	4	22		90'	?	?	?	7	nolog	1-29900	HACH DONE CI >1000
i	4	23		160'	30'	151'	?	5'	Sandstone ashale	20 t gam	
:	4	24		80'		55 F70'	?	4/2'	Sandstone : shale	10/29pm	
	4	25		/35'	15'	901120:	?	10	Sondstone as/shale	39pm	
	4	26		60'	ı	60'.	?	10'	, , , , , , , , , , , , , , , , , , , ,	15gm	
	4	27		145'	40'	105:135'	?	写,	Shale · sandstone	15 dem	7
,	5	5		108'	م برور	10E 34:103	100'	?	Saldone w/ctross	3/2 gpm	HACH DONE
	5	36		52'	16	26 :42	?	6'	Sandstone, State	1	
	5	43		180'	120	153 1174	? .	4'	Sanddone	3/2 gpm	
	6	1	8'		2'	?	?	7	.70/09	?	
1	6	8		110'	12'	35:101	2	4'	sandstone ; dale	3/4900	
										·	
			1.								
					المردون المعادية المع		and the second s				* Water bearing Zone - W.B.Z.
		-									

								.			DEC. 1877
المستريد					GAERIC	OLA ISL	AND WELL	INVENT	ORY, TABLE No.1	· HYDROG	EOLOGICAL DATA
WATERSHED	Section	WELL No.	WELL	DEPTH DRILL	3. W. L.	DEPTH TO # W.B.Z.	WELL HEAD ELEVATION	CASING LENGTH	DESCRIPTION OF MATERIAL	REPORTED YIELD	<u>REMARKS</u>
West Dagre	7 ,-	6		23/			70 '		:		DEV AGE
7	,	フ	4'		2'	z'	30'		Located in dry	GOD	
	,	8	30		15	?	50'	.7	Bedrock	900CL SURRY	
	,	10		60'	烂	58+60'			Sonstone & shale	10 gpm	HACKDONE OL=650 FAM
	1	//		103	40'	163 '	35	·	7		HACITAGE CL- 450 ppm
	1	12	4	7	7	?	15'	?	GRAVEL	GO SHOOY	
	1	15	•	60'	?			7'	shale	19pm	NOT BEING USED
	. /	2.3		55'	20'	48'	15'	34'	Sandstone : Shake	209pm	33'cfo.B.
. •	1	26		110'	30′	75+95',	40'	3'	Sandstone	2/2900	1 NOT BEING WED
	/	33		180	2"	?	75'	25	Sandine ishale	.30bm	SULPHUR REFERT
	1	34		40	12'	?	20	12'	?	6 gpm	
	1	35		80'	10'	70'	60'	2'	Sandstone	4-9pm	
	1	39		70'	20'	61.66	, ?	17'	Sonletone	11/29711	
	1	41		125	15'	20'1118'	?	51	Sondstone - Shale	Bahm	SAE D 1400308
	/	44-		75'	-8'	55'	?	3'	Sonddone	3/2 gm	
	. ,	46		70'	1Z'	60'	. ?	3'	Sorbline-shale	25.9pm	
	,	47	,	75	10	63	?	37'	shale	Egm	
		1	1		1			1			* Water bearing Zone - W.B.Z.

S.W.L. DEPTH TO ** W.B.Z. DESCRIPTION REPORTED WELL HEAD CASING REMARKS WELL DEPTH WATERSHED SECTION WELL YIELD OF MATERIAL LENGTH ELEVATION DRILL No. DUG 1/2 97177 ? NOT IN USE 138 56 8 gpm 5! Sandstone 30' 35:155' 165' 65 * Water bearing Zone. - W.B.Z.

·DEC. 1977

GABRIOLA ISLAND WELL INVENTORY, TABLE NO. 1 - HYDROGEOLOGICAL DATA

S ...

WELL DEPTH DEPTH DESCRIPTION WELL HEAD CASING REPORTED WATERSHED SECTION WELL 5.W.L. REMARKS TO 12 YIELD LENGTH OF MATERIAL No. DRILL DUG W.S.Z. ELEVATION False NACCOLS good Bedrock? 18' 8 110 7 9002 9. (8) 115 TILL-Sonddone 2 SLPPLY 9000 14' 105' 3 3 10/00 SUPPLY good 10' 14' bedrock? 4 100 QUALITY goods. SUFFLY 11 11 10' 70' 5 14 9 shale 140 130 15Aph 38' 30 28' 12' 13 ? 25' bedrock. post <u>7</u>3′ 80' 25' Sandstone 16 39pm <u>30'</u> <u>88</u> ' ළා' Sordetone E gpm 17 36' 3/2gm . HACH BURLYSIS 2 21 100 135 Sandetones clay 150 120' 1 gpm Stale relay 122 22 200 2%' 15 35 Sanddone · State 59pm 24 80 75180 6' 110' to down 118 50 Sondetine 25 20 NOTBENS USED NOT REMA USED (CRANTE PERCETED . 150 6' 1/2 dem 27 130 80 / 130 Cong. & grante 6' Corp. 1 Sandstone 1 -40 2gpm 28 -68 70.80 150 65' 1/2 gph 15" 7 7 29 105 75 ; , Thick fonation of believe clay endularing 65' 100 Zgpm Sondetine 250 30 * Water bearing Jone - WA.Z.

DEC. 1977 GABRÍOLA ISLAND WELL INVENTORY, TABLE NO. 1 - HYDROGEOLOGICAL DATA WELL DEPTH CASING DESCRIPTION REPORTED WELL 5.W.L. WELL HEAD WATERSHED SECTION REMARKS To * LENGTH YIELD No. DRILL OF MATERIAL DUG W.B.Z. ELEVATION Fabre 12 gpm 70' Sondstone <u>50</u>' 3/ 110 4 Namous 3/4 dbm 80 Sondtone , stale 32 55 <u>3</u>3′ 35' 1/29pm 50 1220 70' 220 7 36 <u>3</u> 25:160 ? 1/2 gpm 60' day + shale nkyes 37 175 20' 60-70 granite again reported granite ? 2 9pm 38 90 -80'-90 6/2 9pm 165 10 ? soudine ! stale 43 150 160 3 ? 7/2 gom 45 100 12 Sandstone + blue clay 150:170 Stale : Harstone. 1/2 gpm 48 7 175 95 30 Olay - shale in layers. 40178 8 gpm 90' 49 30 2 20 day-shale 129917 120 28 250 ? 50 3' Sandstone 25 40 :55 7 51 7 gpm. 75 45.80 7 8' Schaldenes shale 3/4gm 125 0 52 Conglornerate shale 135 4140 7 50 150 z'5 gpm 53 clay and shale. 7 2' 210 54 230 89ph 4' shale sclay 165' 39ph 200 55 145,181 7 Shale & clay 490m 57 180 orale clay 40' Higgm. /&O! 58 190 85 1178 * Water bearing Zone - W.3.Z.

		· ·			•
GARRIOLA	TSLAND	WELL INVENTORY.	TABLE NO. 1	-	HYDROGEOLOGICAL DATA
07.07.70.		,			· · · · · · · · · · · · · · · · · · ·

DEPTH TO * WELL DEPTH CASING DESCRIPTION REPORTED VATERSHED SECTION WELL 5.W.L WELL HEAD FEMARKS YIELD LENGTH W.B.Z. OF MATERIAL No. DUG DRILL ELEVATION Folse 129pm 4' shale I day ? 175 190 59 Narrous 145':175 10 Thate oday 3 gpm 200 34 60 ? 3' shole sday 59pm 62 170 85 161 HACH DONE COND OVER 8000 ? 7 63 135 10 log 12 aprin 4' ? 70 day , shale 64 175 200 good supply 30' Shale ? Z 11 10 good ? nolog. 2 .7 2 14 80' Stale: sanddone 5gpm 3 57' 25 2 62 24' 54 'وِ 45' Shale 50 10 gpm 10 Z 4 ٠ ٥ . 35' 15 25 134 2 5 shale 29pm 40 2/2 gpm 140 13'5" Sandstone 2 34' 56 Conglomerate 117 77:95 8gpm 2 100 2/1 175 HACK-DONE 24" 16' 109ph 2 8 40 <18' 65' Shake 70' 16' 2 9 65' shale w layer 55 gph 30' 57763 shale sandstone layered sandstone - conglonorate 125' 39pm 2 120--50' 115' 10 65'185 80' 100' grante reported? 2' Sanditore 19pm 155 HACA DONE // 2 21' 70 980 55' shale 10 dbw 90' 36 Z 12 * Water bearing Zone - W.B.Z.

_				•
GABRIOLA	ISLAND	WELL INVENTORY,	TABLE NO. 1	- HYDROGEOLOGICAL DATA

WATERSHED	SECTION	WELL No.	WELL DUG	DEPTH DRILL	5.W.L.	DEPTH To * W.B.Z.	WELL HEAD ELEVATION	CASING LENGTH	DESCRIPTION OF MATERIAL	REPORTED YIELD	REMARKS
False Narrows	Z	13		50'	4'	27:40	55'	22 ′	shale	2/2 gpm	
		14		105'	10'	35195	/25	.7'	clay ishale	29pm.	
		15		/33′	40'	70:126'	145'	4'	shale sonditive	3900	
		16		<i>9</i> 0′	8'	35'580'		6'	shale o day	9 9pm	
		17		80'	15'	50' : 71'	?	6	Sandstone & day	1/2 gpm	. 4
:		18		90'	?	83'	?	6'	day shale	20 gpm	
		19		90'	15'	82'	?	31'	shale f day	6 gpm	
		20		751	18'	67'	?	16'	shale i'day	12. gpm	
		21 .		105'	14'	45 : 95'	?	6'	shale & sandstone	3.59977	
		22		125'	6"	23':117	?	20'	clay ishale	29900	
	·	23		80'	18'	40 B	?	26'	shale day	109pm	
		24		Bo	සර්	& '	?	191	clay and shale	39ph	
		26		80'	40'	30':65'	?	14'	clay! shale	6 9pm	
1		27		145	35'	65; 135	?	4'	Sandstone ! clay	5/2 gpm	1
		28		135	95	125	?	5	clay and saidstine	15 99111.	
		29		85	50'	75'	?	3 ′	Sandstone (clay	سراه 3	
:		25		115'	6'	10, 105'		21'	clay s shale	2 9pm	
								00 00, 5151 \$4,000 15.00F			* Water bearing Zone W.O.Z.

				•
CATTOLOGIA	T	Man Ture many		1/4555555555555555555555555555555555555
CABRIOLA	15ZAND	WELL INVENTORY.	TABLE NO. 1	HYDROGEOLOGICAL DATA

									ter en en en en en en en en en en en en en		
WATERSHED	SECTION	WELL No.	WELL	DEPTH DRILL	5.W.L.	1 7 3	WELL HEAD ELEVATION		DESCRIPTION OF MATERIAL	REPORTED	REMARKS
		1,10.	DUG	DRILL	<u> </u>	W.S.Z.	ELEVATION		OF MAILTIME	HELD	
False Narrows	2	30		115'	20'	30' ; 110'	?	15'	clay ishale	2295000.	
		3/	•	110	30	65' 100'	?	17'	clay i shale	5 gpm.	
	4	32		105'	10'	25' 85'	?	10'	ciay ishale	3 9pm.	
		33		95'	10'	12' 85'	?	//′	shake o clay	159pm.	
-		34		160	70'		?	7'	clay ishale	19/2 9000	,
	.	35		105'	3'	80':90'	?	8'	Sandstone	15 gpm	
		36		85'	10'	50,73'79'	?	5'	Sandstone	29000	
		37		100'	10'	50'95'	?	4'	state isondatione	10 gpm	
-	1	38		95'	3'	28' P'	?	27	shale r day	16 gpm	
		39		100'	20'	30'	?	24'	day skale	159000	
		40		110'	20'	9295'98'	?	82.	Sondatione	Bapan	Limestone reportied! 22'overlanden
		41		75'	13'6"	68'	?	20'	Shale	2900	
		42		58'	12'	58'	?	60'	grand	109000	Despos . B. (well comp. m gravel)
		43		150'	20'	551.75	?		shale I day	2/29pm	
		44		240'	60'	230'		16'	elay e shake	1/2 9000	
	. 1	45		145	18'	95' 135'		6'	clay state	59pm	
		46	,	150	30'	105'	?	//'	elay shale	4-geon	
		47	1	90'		35'80'	?	2'	SHALE	8 gran	* Water bearing Zone - W.B.Z.

WATERSHED	SECTION	WELL No.	WELL DUG	DEPTH DRILL	5.W.L.	DEPTH TO * W.B.Z.	WELL HEAD ELEVATION	i i	DESCRIPTION OF MATERIAL	REPORTED YIELD	REMARKS
FabeNAGOU	z 2·	48		170	35	<i>8</i> 5′	?	20'	SHALE	Egph	
	2	49		50'	10'	43'	?	15'	SHALE	3/2 gpm	
	2	50		135	5'	70', 12A'	7.	9'	SHALEY SHIVE	39pm.	
	2	51		135	?-	125,	7	.19'	Saddme s Ade	29pm	
	2°	52		170'	120'	160'	?	6	Souldone I shale	Egpan	
	3	/	5'	-	?	?	70'	?	Shale	good	·
	3	2	6'				35	?	; ·	good. Surly	
	3	3		65'	16'	25,58	20'	2	stale	409ph	
``	3	4		56'	7	?	75'	14'	sandine: dele	3 9000	
	3	5		80'	39	70'	25'	9'	clay, shoke	74 gpm	
	3	6		70'	10'	30'	75'	19'	Souldone	2/2900	
	. 3	7		40'	3'	31' 40'	65	16'	shale-day	2.9pm.	
	3	8		40°	3'	20 940	70'	18'	clay o'shale	359pm	
	3	9		40'	8'	23',40'	115'	18'	cay estate	15 gpm	
	3	10		40'	2'	20' 33'	155	. 18	ciay: shale	4/2900	
	3	//		116'	30	105	200'	82'	shale o clay	29pm	81 oborbunden recorded
	3	12	,	150	30'	110',40'	230'	85'	Shale o clay	2/29000	85' "
-	3	/3		110'		80'	?	15'	clay and shale	12 9000	* Water bearing Zone - W.S.Z.
								•			

DEC: 1977

GABRIOLA ISLAND WELL INVENTORY, TABLE NO. 1 - HYDROGEOLOGICAL DATA

DEPTH To * WELL DEPTH CASING DESCRIPTION REPORTED S.W.L. WELL HEAD WATER IED SECTION WELL PREMARKS YIELD LENGTH No. DRILL OF MATERIAL DUG W.B.Z. ELEVATION Fase 50' 14' 2/290m 10' CLAY + HALE 65' . 65' 3 14 Abrows 32' 6 1/2 gpm 8 16' 7 15 60 CLAY & SHALE 3 30 ' <u>10</u>' っ 90' 16' , 82 ' CLAY I PHALE 10 9pm 16 3 56'72' 17' ? 17 ? 80' CLAY - SHORE 3 9pm 3 30' 76' 13 18 85 ? CLAY ! SHAKE 5 gm 3 48,05,25 19 ? 31' 4' CLAY - SHALE 49000 125 3 ? 10 40'118' CLAY , SHALE 125 20 gpm 20 3 3/4 gpm (49' O.R. reported) SITE ID 1400309 ? 21 45 102' 48' CLAY - SMALE 2 130 2/29000 155' SME & CLAY 22 16. 65' ? 167' 3 70'50' 20' 20 gpm 8' フ SMALE F.CLAY 23 3 180 25 95'106' 30' 4/2 9000 115' SHOULE ! CLAY 24 3 17'98' 6' Shall conditione 105 13' 25 7 12 9,900 3 110' 95' 36 26 35' CHAVE & CLAY 1.5 gpm ? 3 3/ CLAY , SHALE 69pm 27 15' 90 82' 16' 3 14" 159pm CLAY SHALE 7 28 110 12' 3 50 10 gpm 20' 17' SHALE! CLAY ? 90' *'*୫୦' 3 29 CLAY & SHALE 50' ? 23' 2 gpm 155 110 140 30 * Water bearing Zone - W.O.Z. 16' 7 CLAY: SHAKE 12gpm 90 12' 3 31

	· ·	·									
WATEL HED	SECTION	WELL No.	WELL DUG	DEPTH DRILL	5.W.L.	DEPTH TO * W.B.Z.	WELL HEAD ELEVATION	1	DESCRIPTION OF MATERIAL	REPORTED YIELD	REMARKS
Fake Normus	3	32		140'	20'	45'	?	21'	shale clay	19pm	
	3	<i>3</i> 3_		95'	20'	55'	?	19'	CLAY ! SKALE	5 dbun	
	3 .	34	·	225'	48'	105 200	?	3'	SHALE! SATORONE	1/2 dam	
	9	1	SPRING		+		310	-	?	good	
•	10	1	7'		3'		320'		bedrock	?	
	. 10	2_		50	25′	45'?	300'	14 1/2'	shale of soundstones	1/2 gpm	
	10	3		145	30'		325'	16'	Sandatone , compl.	14.9pm	
	.10	4		. //2'	?	100/12	260'	3'	shale : congl.	4/20pm	
	10	ج. ح		110	40'	75'105'	?	8'	sombtone ! shele	5/4 gpm	
	28	1	8'		?		36	?	shale iday	Fair	- 0
	28	Z		2200'	4-						TEST HOLE FOR COAL DRILLED & 1930
	28	3		172	?	70 172	25	14'	snote	960 gpd.	
	28	4		160'	15'	50,140	50'	28'	state : Queday	1/2 gpm	
	28	5		65	20'	55'	30	17'	shale & clay	3 9pm	1
·	28	6		72'	12'	40'62'	30'	11%	skale olay	2 /2 gpm	
	28	7		85'	20'		10'	16'	skole i clay	1/2 gpm	
	28	8	,	200'	30'	125'180'	50'	10	1	1/2900	HACH DOWE
	28	9		70'	17'	17'60'10	50'	16	Sondotore schale		

VATERLHED	SECTION	WELL No.	WELL DUG	DEPTH DRILL	5.W.L.	DEPTH TO ** W.B.Z.	WELL HEAD ELEVATION	1	DESCRIPTION OF MATERIAL	REPORTED YIELD	Pemarks
False Narrows	28	10		70	10'	60'	50	15'	CLAY?	109000	
		11		70'	20'	20'60'	50'	10'	CLAY! SAME	2/2900	
	-	12		90'	10'	85'	50'	13'	10 "	8 9pm	
		13		60'	15'	35' . 50	50′	18'	SHALE	25 grm	
·		14		70'	25	20',	?	10'	CLAY · SHALE	5.5 gam	
		15		80	24'	68'60'	?	20'	CLAY + BIALE	59pm	
:		16		60'	15	20.80	?	22'	CLAY I RAPLE	39000	
		17		. 100	6.	100	? 25?	15'	CLAY & DHALE	11 down	
		18		100	.7'	24'60'80'	25'?	12'	SHINE ! CLAY	54 15 gpm	
		19		100'	1.5'	42.75	25'?	15'	11 11	36 05gpm	7
		20		100'	7-	22,70,00	25'?	18'	" .,	50 9pm	
		21		95'	20'	27'. 85 go'	?	20'	SHAVE ! CLAY	6 gpm	
		22		105	20'	42'96'	?	26'	STAKE + CLAY	1/2 9000	
		23		200'	25'	193'	?	13	SAARE O CLAY	1/2 9 2000	
		24		100'	12'	40'85'	?	20'	SAGNE! CLAY	3 /2 gpm	
		25		120	16'		?	20	SHAVE	29000	
<u> </u>		26	,	90'	27'	70'	?	14'	SAME	1/2 gpm	
1:		27		80'			?	16 1/2'	SHALE	2/4gm.	* Water bearing Zone - W.B.Z.

WATERSHED	SECTION	WELL No.	WELL DUG	DEPTH DRILL	5.W.L.	DEPTH TO # W.B.Z.	WELL HEAD ELEVATION	CASING LENGTH	DESCRIPTION OF MATERIAL .	REPORTED YIELD	REMARKS
HOGAN LAKE	//	1		?	7	?	?	?	Salvone	900L SURRLY	no information available
9	11	<i>Z</i> .		100'	25'	85'	?	3'	Shile; sanddone	3/23	
	12	8		75'		30 ? 70'	. ?	7'	send Aone ishale	5 തുത	HAND PUMP.
	12	16		140	6'	12:60	?	4'	Skele - sondstona	50 down	
:	12	17		130	25'	40160	. ?	3'	Sandstone & Shale	40 gpm	
	12	18		130'	.7	45',60' 90'\$130'	7	9'	Sandatine schale	20 gpm	
•	12	19		130'	12'	98: 130	?	3'	Sondstone ishale	50 gpm	
	12	20		174'	20'	168'	7	9'	Sandstone ishall	259pm	
	12	30		190'	25'	181'	?	4'	Sandstone schale	1 9pm	SAE DE 1400ZEB
	12	37		105'	30′	95'	7	3'	skale in layers	20 pm	
1	12	38		165'	30'	156'	?	4'	Sandetone	12 gpm	
	/2	41		105'	40'	89197'	7.	3'	Sandtone	2.9pm	
:	12	42		165	15'	40' 160':155'	7	6'.	Sondatone	12 gpm	
	12	43		100	30'	85'	7	6'	Soddore istale	2gpm	
:	12	52		100'	30'	90'	7	5'	State isaidtone	1090m	
	12.	<i>5</i> 3.		245	90'	232'	?	4	Sandstone istale	1 gpnn	
	13	2	,	110'	15'	20:90	250	.8'	Sandstone ! shale	20 grm	
										I STANDARDS	* Water bearing Zone W.B.Z.

DEC. 1977 DEPTH CASING WELL DEPTH WELL HEAD WELL 5.W.L. TERSHED SECTION REMARKS 70 1 LENGTH OF MATERIAL YIELD No. DEILL DUG ELEVATION! W.B.Z. 45 960 20 9700 loom Leke Sandstone 13 3 250 75 Shale scanditione 10 9pt 7 7 12' 13 180 76" 9' Sandstone. 8 15 gpm 60 14' 13 11' Shaley sandstone 100' 14900 22! 17 8' shale : Greday North 89pm 27 228 130 240 Cumberland 6 130:198 Watersen . 12 30 49pm 32 210 0 Sonttone Conglomente 8 9777 65 6130 South Descripo 12 140' 85' 1152' BAY 300' 5' Shale 29ph っ 5 245 12 4/2 mm (II)75 2' Sondstone 12 .61 320 6 HACH DONE Shale i sandstone 24' 9 115 12 6/2900 ? Sandstone ! shale 161 135 12 10 + 24 2' 15' Sandstone 60 329pm *55*′ 12 11 12 Sordodono: Ack 22' 7 ABONDONED 226 12 12 22'.545' 55' Sonistane , shale 9 9000 HACA DONE 60' 2' 23' 12 13 45' 80' Sandatone & thele 19' LINCH DONE 17' 11 dem 90 14 12 * Water bearing Zonc - W.Z.I.

WATERSHED	SECTION	WELL No.	WELL DUG	DEPTH DRILL	5.W.L.	DEPTH TO # W.B.Z.	WELL HEAD ELEVATION	CASING LENGTH	DESCRIPTION OF MATERIAL	REPORTED YIELD	REMARKS
South Dexon	00 1Z	. 15		90	2'	26' 30' 40'65 ₈ 5'	23 '	5′	Sondstone i shale	24. Jm	
	12	23		100'	25'	30'90'	?	12/2.	date : sextetone	20/2 gm	
	12	24		300'	?	150:280	?	6'	soldone & Sale	1/2 gm	
	12	25		155'	30	145	?	3'	sandstone! shale	2.5 gm	
	12 :	27		275'	?	200'	?	4'	sandctore istale	.05 gpm	
	12	28		210'	?	?	?	5'	sandstone	?	
	12	3/		190'	25'	15:184	?	4'	Sandstone	10gpm	
	12	<i>3</i> 3 ·	SPRINE		+?		?	?	?		¹¹ /4003/3
	/2_	34		200'	75'	201:193	?	4'	Soldone	24 gpm	
	12	35		190'	<i>8</i> 0'	178'	2	5'	Shale	1/2 900	, E
	12	39		260	162	205 : 260	7	10'	Sandatone doy	14 gpin	
	12	44		105	?	95'	?	7'	?	1/2 gpm	
	12	45		105'	30'	96'	7	/3′	Side	79Pm	
	12	46		39'	3'	2/	7	12	Shale · day inloyer		
5	. 12	51		-265'	90	90 1255		5'	Sandstone-shale	2/2 gpm	
	12	54		300'	15'	7		5'	clay , shale in layers	19Fm	
	. 12	55	,	77	17'	37,55		8'	stale	89pm	
									The second secon		*_ Water bearing Zone W.B.Z.

									والمراجع والمراجع والمراجع والمراجع والمراجع والمراجع والمراجع والمراجع والمراجع والمراجع والمراجع والمراجع		
WATERSHED	Section	·WELL No.	WELL	DEPTH DRILL	5.W.L.	DEPTH TO # W.B.Z.	WELL HEAD ELEVATION	CASING LENGTH	DESCRIPTION OF MATERIAL	REPORTED YIELD	REMARKS
South Descan: BAY	25			60'	22'	58°	20'	z '	Sondstone ! conflorate	E 10 9pm	HACHDONE
		· Z		102'	23 ′	79 -100	50	8'	Sindstone	10 gm	HACH DONE
		3		105'	+	96'	20	4'	Sandstone	10 gpm	HACH DONE
		4		266	13'	.'	20'	4'	Sandstone	5gpm?	
		. 5		142	<i>8</i> 0'	139'	<i>&</i>	3'	Sondatione & Shale	4-9pm	
	•	6		\$55	7	?	20 '	?	no log	7	
		7		236'	20'	120'	20'	4	Shale: clay	39pm	HACH DONE
		8		95'	5'	85'	?	8'	Shale of conglomerate	16 gpm	
		.9		/30	75	120'	?	5'	Sanddone	15 gpm	
		10		150	11'	142	7,	// '	Sandons	8gpm	HAGEN DONE (Northanbedood Chamel)
		11		190'	40	185'	? .	4'	Sonditore - congl.	Zegpm	
i .		12		65'	0	12'	2.	4	Sandstine	10 gpm	
:	20	2	12				14		TILL	POOR Supply	
		5		85	FLAN	78'	10	2'8"	SHALE, CONG. SAMITONE	10 9900	2.5
:		/5		85	FLTUI	35-60 70-80	14	/3	SANDSTONE	30 EPM	
1		16		170	25	160	又	7	BLUESHALE	1 GPM	
		17	,	140	12	59, 132		"	BLUE SHAKE	1/2 open	
		21		190	80	170,190		6	SEALE 1 CONSTRUCTOR	1 1/2 gpm	* Water bearing Zone - W.B.Z.

TABLE 2 - QUANTITATIVE ESTIMATES OF PRESENT GROUNDWATER USE

VERSUS AVAILABLE STORAGE

GROU	NDWATER REGION	AREA OF REGION IN ACRES	PRELIMINARY ESTIMATES OF GROUND SUPPLIES IN STORAGE AND RECOVER BY MINING - EXPRESSED AS % EST. BEDROCK VOL. IN ACFT. ASSUMING DEPTH OF 200' - FOR	ABLE IN REGION	ESTIMATED YIELD IN GPM USAGE 500 GPD PER WELL	ESTIMATED GROUND- WATER USAGE IN GALLONS BASED ON 500 GPD/PER 100 DAY PUMPING	
			0.01% IN AC.FT. (1)		·	(2)	:
1.	Sands	864.19	17.28	175	60.76	8.7x10 ⁶	
2.	Lock Bay	2188.93	43.78	200	63.44	10x10 ⁶	
3.	Descanso Bay	1420.93	28.42	71	24.65	3.5x10 ⁶	
4.	Gabriola	3148.93	62.98	25	8.68	1.2x10 ⁶	
5,	Silva Bay	563.01	11.26	51	17.70	2.5x10 ⁶	
6.	North Descanso Bay	553.15	11.06	32	11.11	1.6x10 ⁶	
7.	West Degnen Bay	422.46	8.45	19	6.60	9.5x10 ⁵	
8.	False Narrows	1414.21	28.28	178	61.80	8.9x10 ⁶	
9.	Hoggan Lake	1977.73	39.55	22	7.64	1.1x10 ⁶	
10.	Northumberland Channel	204.93	4.10	2	.69	1x10 ⁵	
11.	South Descanso Bay	339.20	6.78	49	17.01	2.4x10 ⁶	

ESTIMATED AVAILABLE RECHARGE
TO GROUNDWATER FROM PRECIPITATION IN U.S. GALLONS BASED
ON 1" OF ANNUAL PRECIPITATION
AVAILABLE FOR GROUNDWATER STORAGE

ESTIMATED GROUNDWATER
USAGE VERSUS AVAILABLE
RECHARGE EXPRESSED AS
A PERCENTAGE BASED ON
COLUMNS

ESTIMATED GROUNDWATER USAGE VERSUS GROUNDWATER IN STORAGE EXPRESSED AS A PERCENTAGE.

(3)	(2) & (3)	(2) & (1)
2.35x10 ⁷	37	154.0
5.9x10 ⁷	16.9	70.0
3.9x10 ⁷	9.0	. 37.8
8.5x10 ⁷	1.4	5.8
1.5x10 ⁷	16.7	68.1
1.5x10 ⁷	10.7	44.4
		*
1.1x10 ⁷	8.6	34.5
3.3×10 ⁷	23.4	95.6
1.1×10 ⁷	10.0	8.5
5.5x10 ⁶	1.8	7.5
9.2x10 ⁶	26.1	.108.6

GABRIOLA ISLAND	WELL INVENTORY,	TABLE No. 1	· HYDROGEOLOGICAL DAT	A

S.W.L. DEPTH WELL DEPTH WATERSHED SECTION WELL CASING DESCRIPTION WELL HEAD REPORTED To **
W.B.Z. REMARKS No. DUG DRILL LENGTH ELEVATION OF MATERIAL YIELD (200/290 Sands 86 21 295 7' Shale + sandstone =209ph 135 87 34 gpm 2/ 120 50 4' shale + sandatone 21 88 35 :110 125 15' 7 5 shale & sondstone 39pm 89 21 110 30 195 7' 10 gpm 21 90 120' 80:115 10' 109pm 21 91 25' 166' ? 8' 170 20+gpm 21 92 30 125' <u> 130</u> 6' sandsone 30 Tgpm SITE. I.D. # 1400320 40.70 21 93 85' 6' stale 1 sandstone Conglomerate 80'-85' 109pm 94 21 110 10' 100' 89pm 21 55 195 95 110 4' Clay and shale. 10 gpm 21 96 8' 50-75-100 110 cray and shale 4 9pm 21 97 7' 125 115' Sandstone + shale 29pm 21 98 ۵. 5' 130 120 shale 109pm 29 125' 21 15' 90 ! 115 Sandstone 9 29pm 100' 15 6' 21 100 60185 2 sandstone ishale 159pm 21 65' 10% 180 125:170 4'8" shaley sondstone 5 9pm 25' 10' 215' 21 /03 205' sandstone shale 79pm 21 104 368' 368: 51 sandstone Water bearing Zone - W.B.Z. 19pm

WATERSHED	SECTION	WELL No.	DUG-	DEPTH DRILL	5.W.L.	DEPTH TO *: W.B.Z.	WELL HEAD ELEVATION	CASING LENGTH	DESCRIPTION OF MATERIAL	REPORTED	REMARKS
Sands	2:/	69		135'	6'	125'	?	6'	Sandstone-shale	1/2 9 pm	
	2/	70	·	10,5	2'	95'	?	3'	Sandstone	8.9pm	· .
	2/	7/		125'	7'	115'	?	7'	Sandstone	5gpm	
	2/	72_		100'	30'	70! 95'	?	5'	shale roandstone	1/2 9000	
	2/	73		100	6'	20:94'	2	6'	Shale - sandstone	12 gpm	· ·
	2/	74		170'	9'	157 163	?	5'	shale; sandstone	1/2 gpm	
	2./	75		145'	25'	136'	7	8'	/: · · · ·	3.990	
	21	76		.100'	5'	15:190	?	7'	layered shale	6.9pm	
-	2.1	77		110'	2'	15:106	?	7'	clayeshale	1/2 gpm	
	21	78		330	- ·		?	14'	sandstone.		•
	21	79		150	5'	6:150	7	6'	Santtone	19pm.	
	21	80		45'	+	16:30	?	8'	Sandstone	30 Fm7	APPEAD TO BE EXCELLENT WELL SHOULD BE SAMPLED FOR QUALITY
	21	81		100	37'	78'	? .	5'	Sandstone	1 ½ gpm	\
	21	8Z		200.	50'	1 193'	?	: 7'	Sandstone , shale	129000	
	21	83		115'	30'	95 105	?	7	sandstone -shale	10 9pm	
	2/	84-		130'	25	15. ! 122'	?	11'	Shale	2429pm	
	2/	85	,.	265	-	245 1256	?	7'	sandstone 1 dale	12 gpm	
											* Water bearing Zone - W.3.

. DEC. 1977

GABRIOLA ISLAND WELL INVENTORY, TABLE NO. 1 - HYDROGEOLOGICAL DATA DESCRIPTION REPORTED WELL HEAD CASING DEPTH PEMARKS WELL DEPTH 5.W.L. WELL VATERSHED SECTION 70 % ELEVATION LENGTH YIELD OF MATERIAL W.B.Z. DRILL No. DUG HARA DESCHWSO 13 GAY SANDSTONE 6 160 20 10 166 24 BAY EROWN AND 155 12 GAY 25 BLUE SHALE 8 160 65110 SHALE AND 12 GPH SANDSTONE 25 9 120 70 20,90 SANDSTONE AND 5 GPM SIALE IN LAYERS 12 125 115 SHALE AND 12611 27 SANDSTONIE 8:18,120 5 15 145 SANDSTONE AND SHALE IN LAYERS 3/2 GAM 4 19 55 65 20 * Water bearing Zone - W.B.Z.

_		•		•	
GABRIOLA	ISLAND	WELL INVENTORY,	TABLE NO. 1 -	HYDROGEOLOGICAL	_DATA

WELL DEPTH DEPTH DESCRIPTION CASING REPORTED WELL HEAD WELL ERSHED SECTION REMARKS LENGTH YIELD No. DUG DaiLL ELEVATION OF MATERIAL W.B.Z. HACH ANALYSIS DONE 112' 110" 3/5 gpm 61:81 SITE ID 1400292 sanddone of shele 50 SCFT WATER 110 CABRICLA 2 115' a' Sandatone : shale 7 97177 4 124 34' 122 3 42 43, 72, 76 13 5" SITE# 14.007.91 80 Conditione 125 749pm 75,9pm COSERVATION WELL - CONFLETE P.T. Them. Sandstone withde 275 +10 120 .5 40 1021 Sandstone 6 59pm 65 9 gpm 22:81 14 Sandetone 90 6 125 Sandone shale 11' 80 :115° 12 9PM Sandstone ; shale 55' z' 140 58 /110 397177 10 60:70 14' Sandstone 6 9pm 80' 11 HACH ANALYSIS DONE 1400289 30 165 61 143' 16 2 /5 9pm 74 Sundione ; shale 3 HACH ANALYZEDONE 5 80 195 145' 2/29pm 102' Sondstone 8' 55 9' 12/29pm 44' Sandstone (BERLATION) NELL 72-4 -29' 10' Sanddone 39pm 275 16 210 Sandstone 95' 3' 3 9pm 75' 130 17 good 5' 130 7// 12' 17 * Water bearing Zone - W.B.Z.

WATERSHED	SECTION	WELL No.	WELL DUG	DEPTH DRILL	5.W.L.	DEPTH TO ** W.S.Z.	WELL HEAD ELEVATION	CASING LENGTH	DESCRIPTION OF MATERIAL	REPORTED YIELD	PEMARKS_
CABROLA	17.	. 3		30	5		173	?	Sandstone schole	4-9pm	
	30	1		56	34'	45'		13 '	State & sonddone	2.5 9pm	#1400306 + 141CH ANALYSS
	30	2		100		9,50,65	?	6'	Sandtone dale	16 9pm	
	30	3		100	6"	16, 65,100	?	٠. ٢	Sandtone	20 977	
	30	4		150'	37'	70 110-19	, ,	?	Sandctone	79pm	٧
	30	5		150'	20'	25,80	?	9'	Sandstone & shale	4.9pm	
. ,	8			99'	?	?		4'	Sandstone i skale	59pm	
•											
									•	•	
								•			
,											
· ·				· ·							
		:		·				-			,
		t ·—					·		·		
										·	
			,						, .		
							•				* Water bearing Zone - W.D.Z.

						-	•	
GAE	RĴOLA	ISLAND	WELL INVENTORY,	TABLE	No. 1	-	HYDROGEOLOGICAL	DATA

. DE0. 1977

ATERSHED	SECTION	WELL No.	WELL DUG	DEPTH.	5.W.L.	DEPTH TO ** W.B.Z.	WELL HEAD ELEVATION	CASING LENGTH	DESCRIPTION. OF MATERIAL	REPORTED YIELD	<u> Fiemarks</u>
Silva Bay	5	/		2∞′	<i>5</i> 0 '	200'	<i>8</i> 0'	?	Bedrock.	20 mil	SAED 1400290
(3)	5	2		78'	32'	27,577		? .	Sandstone	799777	
	5	3_		77'	25	?	50'	?	Sandtone I shale	59pm	
	5	4		67'	16	39-48-65		÷	Stale : sondstone	59pm 1 4 1 59m	
									/		
	5	۶	9		Low	?	70'	. ?	Sandstone	~>	good siggly & quality reported.
	5	7		122'	28'	16:75	30'	7	Sandstone	29pm	
	5	8	·	120'	?	?	95'	7'	Sandstone ! shale	189pm	
•	5	9		120'	42'	74 9 118	30′	?	Sandelone	2.3 gpm	HACH DONE
	5	10		70'	3z'				Sardatone	59pm	НАСН " el. 900 ppm . —
	5.	il		104	78'	?	70'.	?	Sandstone	5 gpm	bad spoly?
	5	12		40'	16'	27'	17'	4'	Sandstone	5gpm	·sact?
	5	13		60'	8'	56:60	20'	12'	Sandstone.	دسنه	
	5	14		68'	14'	51:64	35'	13'4"	Sandstone.	39pm	Hach analysis done
	5	15		70'	32'	54'	75'	?	Sandstone	2.6 grm	SITE ID 1400295 Hack done
-	5	16		63'	31'	55:63'	රිර	?	Sondtone i shale	1.2900	Had done
	5	17	,	77'	44	72'	55	12'	Sandstone	8 gm	
											* Water bearing Zone - 11.0.2.

· · · · · · · · · · · · · · · · · · ·											
NATERSHED	SECTION	WELL No.	WELL	DEPTH DRILL	5.W.L.	DEPTH TO * W.B.Z.	WELL HEAD ELEVATION	CASING LENGTH	DESCRIPTION OF MATERIAL	REPORTED YIELD	REMARKS
Silva Bay	5	18	16		7	?	25 '	?	TILL	?	good sipply reported
silva say	5	. 19		75	25'	25:70'	90'	4'	Sandstone I shale	69pm	
-	5	20	<u> </u>	60'	24'		20'	?	Sandstone	4 gpm	
	5	21		182'		180' 91, 134, 173,	55	?	Sandstone	4 gpm	
	5	22		66	25'	64'	80'	56"	Sandatone	39pm	¥
	5	23		61'		12'1'59'	75'	4'2"	Sandstone	5/29pm	
	5	24		148'	 	28! 138		?	Sandstone shale	29pm	
	5	25		60	30'	55 :	100'	5'	Stale	2.5 gpm	HACH ANALYSIS DONE
	5 .	20		60'	9'	.53'	110'	7	Sandstone	199777	٠ .
	5	27	1	100'	15'		75'	2'	Sandstone	1/3 gom	
	5	28		70'	33	64'	30	7'	Shale	4-9pm	Had and pusdone Cl 1050 April
	5	29	-	,	35'	17 165		7	Sandstone	5 gpm	
	5	30	1.	74	40'	17.03	50'	11'	Sandtone	59pm	HACH ANALYTIS DONE
		,		110	6			10	Sandstone		
	5	3/	-	65	 	55	25'		Shale and Sunddone	4.9pm	HACH ANALYSIS DONE
	5	32		85	30	75 : 85	85	5/2'			
	5	33		80	30'	50 4	80	5'	Sandstone & day	1/2900	
	5	34	,	60'	8'	23 160	30'	9'	Conglomenate	2/29pm	
							and the second section of the second		The state of the s		* Water bearing Zone W.B.Z.

— →						•	
GARRIOLA	TELANT	WELL INVENTORY,	TARIF	No 1	- HYDROG	FOLOGICAL	-DATA
GADAIOLA	エンニハハマン	**************************************	//\~~				

VATERSHED	Section	WELL No.	DUG	DEPTH DRILL	5.W.L.	DEPTH TO * W.B.Z.	WELL HEAD ELEVATION		DESCRIPTION OF MATERIAL	REPORTED YIELD	PEMARKS
Sands	22	/	11.		z '		50'		TILL		
	22	2	•	65°	4	26 655		16'	shale & sandstone	79pm	
	22	3	15'		8'		37		sandstone		fook suffly
•	22	4		117'	57'		200'	10'	sholey sondstone	1/2 9pm	
	22	5_		35'	13'	24'	11'	9'4"	sandstone o dale	!	1400302
	22	۷	14'		10'	.?	37	?	Sandstone	?	Thor supply
•	22_	7	27'		20'	?	37'	?	TILL	?	TILL
	2Z .	8									
	22	9		124	20'	112!	69'	20'	Sandstone	9-0 9ph SUPPLYS 3 HOUSE	
	22	10							•		
	22	il									
	22	12	15		SUCFACE	?	30′	?	Sondstone	good surrey	1400304
	22	13		120'	4	110'	3/ .	?	Sandatone	0.89pm	nor beine used
	22	14	15'		12'	10'	24'	?	Sandstone	~>	good surrey
	22	15	-17'-		2	?	26'	?	11 11	>.	good supply
	22	16		2/5		44'	15'	7	Sandstone	899/7	POOR SUPPLY - SULPHUR
	22	17.	14'		11.	·	34	7	Sandstone	GEODERLY	
,B ⁻			 		1		1				* Water bearing Zone - W.

DEPTH WELL DEPTY CASING DESCRIPTION REPORTED WELL HEAD WATERSHED SECTION WELL 5.W.L. REMARKS 70 * LENGTH YIELD No. DRILL OF MATERIAL DUG W.B.Z. ELEVATION good supply 32' Sandstone ٠, ٦ 10' 17' 1400312 Sands 22 18 19 22 212' 4'9" Sandstone 21' 22 20 125' 34' shale 19000 22 140 10' 21 sandstone 1904 22 22 209' 105 poor supply 45' adequate supply 8' sandstone 23 22 150 3' 1/2900 90° 45' shaley sandstone 4'z" 22 24 87' ₃′ 56 10' 52' shaley sandstone 49pm 20 22 25 45' sandetone 9'5" 19000 200 26 142.185 22 not being sel 130 10' 120 9126 150' Sandstone & trale 99pm 27 22 31 Sandstone . Sale 93' 30 75' 30' 19pm 28 22 29 121 sandstone 70 20165 49000 22 50' 4' 30 137 137' 12' 45' 1400303 22 31 87' 15' 10900 Hach andysis done 78' 22 100 4' 129 35' 49pm Salt water (HACH) 20' 125' 22 32 10,60 259pm 180 Sondone & shale 70' 22 33 19' Layered shale 25' 50,70 190' 49pm 22 80 34 · * Water bearing Zone - W.B.Z.

				•
		I.C. T. Manager and	7	· HYDROGEOLOGICAL DATA
(-APARIOIA	(S/AND	WELL LAVENIORY.	TABLE NO. 1	* MYDROGEOLOGICAL DATA
0/1041/02/1		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		

DEPTH To * WELL DEPTH CASING DESCRIPTION REPORTED 5.W.L. WATERSHED SECTION WELL WELL HEAD REMARKS LENGTH OF MATERIAL YIELD No. DUG DRILL ELSYATION W.B.Z. 5' 120 160 Sandstone SURFACE 165 3 9Pm Sands 200 22 35 30 65 12/2 Sondatione I shale 36 250 20 gpm 22 72 307' 50' Flows @ . 49pm Sonditone whale 22 312' 3 9PM 37 HACH AMALYSI DONE SITE \$ 1400308 8' ? ? 17' 45' TILL 22 38 Or Surry 7 45 ? 5' 39 20' .22 7744 40 22 5 175 138 ? 160 sorttone & shale 22 41 29711 5' 120' 42 112' sandstone & shale 69900 22 13' well not in use 43 18 7 TILL 22 44 22 ? 5' 22 144' 45 69pm 130 8 54' 22 46 120 22' sandstone 115' 159900 32' 47 sandstone 90' 54' 81' 22 5gpm 8' ? **>** . 48 ? ? 22 SIE D 1400318 49 22 3/ 9pm 5' shale ... 155 145 50 22 5' State & sandstone 1/29pm 140' 51 132' 51 22 * Water bearing Zone - W.B.Z.

WELL DEPTH DEPTH TO & DESCRIPTION WELL CASING WATERSHED SECTION WELL HEAD REPORTED REMARKS No. DUG DRILL LENGTH YIELD ELEVATION: OF MATERIAL W.B.Z. 95' 30' 85' Sands *5*Z 22 20 SHALE 1- gom 22 53 145 48' 134' Shale .17 10 gram 90' 55 8' 22 10:80 shale 15/29pm 13" Sandstone 265 57 22 287 2 pm 3 . ? *3*0′ 30' 220 ? 24 7 24 4 10' 50' 19pk. 5' HACH ANALYSIS - HIGH CHEARDE 24 5 280 15° 215 16' 7 4' sanddone I dale 24 40 gpd 51 159 shale 901. 24 135 0.089pm 10 6' 7' 45 24 Sandatone 11 159pm 6' 24. 13 115 15' Sandstone & state 2+9pm 20' 51 24 14 ? Sandstone 220 185' 1/2 apm 25' 24 16 3/3' *3*23' Sandstone shale 21 29ph 24 :110 7 Sandstone & shake 1/2 gpm 17 -123-120 2 2/2 gpm 125 sandstone 18 2 5' 24 * Water bearing Zone - W.B.Z. 11.

REPORTED CASING DESCRIPTION DEPTH REMARKS WELL DEPTH WELL HEAD S.W.L WELL WATERSHED SECTION TO # ELEVATION LENGTH YIELD OF MATERIAL DRILL W.B.Z. No. DUG acco BEDRUCK 340 12 14 LOCK BAY SANDSTONE 17 1400286 9 GPM 340 AND SHALE (2) 35 37 17 SANDSTONE US TEST WELL 72-1 10 CIPH 1400064 10' AND SHALE 3 12.84 *5*25 CLAY 8 3 GAM AND SHALE 95 130 <u>300</u> ± 5/2 GPM 1400285 80 5+11-71 = 85 12 15: SANDSTONE 6 CPM 13.75 25-45 3,25 AND SHALE 2 50 SANDSTONE 2.0 GF17 3 6 AND SHALE 5 10 65 2³/4 GP17 8 SANDSTONL .110 20 53102 4 SANDSTONE 20 /2 GM 13 AND CLAY 50-65 5 70 20 POOR 30 BEDROCK 12 14 18 1/2 GPM 325 95 SAWDSTONE 1/2 601 3 10 230 8 AND SHALE 100 30-100 SANDSTONE 20 GPH 4 65 930.60 230 AND SHALE 10-15 61111100311 - MACH 15 30 67,110 30 SHALE 5a 112 WAS 10 OPM-HAS GONE DRY DRY SHALE 56 110 KV CIPIY 14 50 SHALE 56 60 6 CLFIY 14 0111 150 270 5 MINO SHALLE 160 . * Water bearing Zone - W.S.Z

•	_	WELL INVENTORY,	_		11.120000000000000	AL ZZATA
_	•		TABIE	NO.I.	MADKORFORGE	
0	Tal 44/77	WELL LNVENIONES	/ // // //			
(FAERIOLA	メンムハマン	//				

							A112 112			REPORTED	#EMARKS
VATERSHED	SECTION	WELL		DEPTH	5.W.L.	DEPTH TO *	WELL HEAD ELEVATION	CASING LENGTH	DESCRIPTION OF MATERIAL	YIELD	HEMARKS
7.7,72,110.7.2		<i>No.</i>	DUG	DRILL		W.B.Z.	ELEVATION				
OCK BAY	18	.9		55	1.2	30	275	15	SANDSTONE,	5-6 GPM	
OCK DITT		9		80	6	30.70	275	9	CLAY AND SHALE	10 GM	
				85			280	10		8-10 GAY	140 1145
		10	<u> </u>			20 250		8	SANDSTONE + CONGLONERATE	2/2011	
	-	.//		90	8	30,75,90		1		11/2 CIPM	ij
	<u>.</u>	12		90_	8	75	270	4-	SANDSTONE CLAY AND SHALE		
		13	/	27	8	19.27	50	12	IN IAYERS CLIAY AND SHALE	20 GPM	·
		14		32	10	20,32	30	10	IN IAYERS CLAY AND SHALE	30 GPM	
		15		.90	13	30,76	75	17	IN LAYERS	1GPM	
	 		1			25	50	14	BLUE CLAY AND SHALE	10 CPM	,
		16	-	50	6	35,43			•	15-20 0	ing .
		17	_	25	10	20,25	30	10	SANDSTONE SHALE AND		
		18		36	6	24	30_	12	SANDSTUNE BLUE SHALE	6. GPM	
		19	T .	35	12		30	14	PAND - CLAY	6 CP1	HACH
									SANDSTONE	2/2 60	· · · · · · · · · · · · · · · · · · ·
		20		75	120	65,75	325_	6	SAMMISICAL		· ·
;		21		40	32	, 20	60	. <i>IC</i>	1	7 6/17	/
:				50	12	35,50	30_	19	CLAY & SHALE	1/201	2/
<u> </u>		22						12	BLLE CLAY	4/2011	nt
:		23	_	40	10	30,35	30_				
		24		40	6	25-30	25	13	C1124 10 SHIN	E 1.23 1.2 (11	* Water bearing Zone - W.B.Z.
											The second secon

DEC. 1977 GABRIOLA ISLAND WELL INVENTORY, TABLE NO. 1 . HYDROGEOLOGICAL DATA DESCRIPTION DEFTH CASING REFORTED WELL DEPTH PEMPRKS WELL HEAD WELL 5.W.L. WATERSHED SECTION 70 × YIELD LENGTH OF MATERIAL ELEVATION No. DUG DRILL W.B.Z. 50 GM 25. CLAY & SHALE 35 24.35 25 18 LCCK BAY SANDSTONE 12 GPIY 69.70 75 24 26 18 CLAY & SHALE 12 CIPM 30 10 27 40 LMYERED 2 GPM SHALE & CLAY 40130 28 130 30 BILLE SHALE 2/2GPM 12 58 10 29 65 LAYERED SHALE SANDSTONE 125 5 GP/Y 31 125 90 LAYERED BLUE CLAY 1/3 GPM 160 32 151 BLUE CLAY & 3 GPIY BIVE SHALL 33 155 14 70,147 BULLE CLAY 4 4 CPH SANDSTONE 54 60 200 250 BLUE CLAY'S BLUE SHALE 25 GPM 55 15,54 15 60 BLUE CLHY4 ./7 BLUE SHALE 20 GP/1 36 22,49 60 BLUE SHALE 12 GP/1 16. YBLUE CLAY 37 22.49 55 BLUE SHALE 7/2 7 BLUF CLAY 12 GPM 38 30 /30 1.21 5000 BLUE SHALE 115 39 125 BLUE SHALE 6611 85 40. 94 16 * Water bearing Zone - W.B.Z.

						•	
GABRIOLA	TSLAND WE	LL INVENTORY.	TABLE	No. 1	-	HYDROGEOLOGICAL	DATA

			T	7	T	Depty			DESCRIPTION	REPORTED	7-11-5-10
WATERL.1ED	SECTION	WELL No.	DUG	DRILL DEPTH	S.W.L.	DEPTH TO * W.B.Z.	WELL HEAD ELEVATION		1 -	YIELD	<u>REMARKS</u>
	 	170.	DUG	DRILL		W. B. Z.	444				
LOCK BAY	18	42		155	,	147	ļ	5'	BLUE SHALE	2 GPM	
LUCK OIT	10							7	SANDSTONE AND SHALE IN LAYERS	10/2 GPM	k
	1	4.3		100		75,90		 	SANDSTONE AND		
	1	14		80	15	30,65 75,78		5	SIFIERS	26 12 GPM	
<u> </u>	+		-								
	<u> </u>	45_		130	15	16,119		9	BLUE SHALE SINDSTONE AND	5 GPM	2
	1.	46		105	4	4,95		3/2	SHALE IN IAYERS	5/2 GM	
	 		+								
	<u> </u>	47		75	17_	65	<u> </u>	28	BLUE SHALE	12 GP/Y	
	,	48		70	8	10,60		20	IN LAYERS	15 GPM	
	1	73	+	1					SHALE AND CLAY		
·	·	19		.45	15	38,45		14		AC GPH	
				1,7		1,517		4	SHALE AND SANDSTENE IN LAYERS	12 GPM	
		50	+	125	50	115,125		17	1/34/-735	1000	
· · · · · · · · · · · · · · · · · · ·		51		235	75	35,219	,	14	BLUE SHALE	4. GP14	
	+	1	1						BLUE CLAY	1.500	100 770
-		52		75	12	30,45		1.3	AND SHALE	116171	1400379
		7		00		77.71	,		SANDSTONE AND BLUE CLAY	3 GPM	
!		53		80	- 30	58,74	-	6	PIVI) BLUE CLITY	J C//-/	
		54	Ì	120	15	90.110	,	8	SANDSTONE	8 GF14	• • • • • • • • • • • • • • • • • • • •
		10/	+	1.00	+,~	10,10		+	SHALE AND		
		55		95	- 40	60		1. 3	SON'DSTONELLAYER	1/2000	/ `
}	+	+	-		_			•	· BLOWN STUDSTEL	્ ક	
		56		90	30	45		12	BULE CLAY ?	3611	1
	1			1,7	T_{α}			9	On the CTO !	7 GPM	,
		57		40	12	15,30			SANDSTONE	1/0//	
4		58	,	' 95	50	85		11	GREY SINONSICE	8 12 0017	1
1	_	100			-		 	-	Maria de la Companya		.* Water bearing Zone - W.B.Z.

			T WELL	L DEPTH	T	DEPTH	WELL HEAD	CASING	DESCRIPTION	REPORTED	PEMARKS_
NATERSHED	SECTION	WELL No.	DUG	DRILL	5.W.L.	W.B.Z.	ELEVATION	1 1	OF MATERIAL	YIELD	
	 		+	+	1 2	,		-111		10 GPM	
LOCK BAY	/ 18	59		<u> </u>	4?	 '	1	11/-			
	19	1 /		120	2/	70.112	200	10'9"	SANDSTONE	2.1 GPM	1
	1	10			1	,		,	SHALE AND SANDSTONE		DRY HOLE HACH
	 '	10	+	192	-	+		 	HACO	-1/2 000	
·		5		74	37	63	200	6	BLACK SHALE	2/2 GAY	
		9	T .	100	5	45		12	BILLE SHALE	6 GPH	1
			+						SANDSTONE	3 GPM	•
	<u> </u>	10		130_	1/5	70,120	-	12	AND SHALE	3 (7/-1/	
· ·		111		25		22		9	SANDSTONE	10 GPH	
	+		1					10	BIUE SHALE	3 GPM	
	22	40		105	12	50,95		10		(75	
1		14		325	10.8	3.	120	10	SANDSTONE	24 GP14	1400063 TEST WELL 72-5
	 	-						. 4	SINDSTONE 4	8 GPM	
		49		125	<u> </u>	4,120	-	1.54	DARK GREY		
•		54		155	85	145		5	SHNISTONE	1/4 GAY	
	+					140				8 GPM	
; <u></u>		56	-	300		260,285	<u></u>	. 10	BLUE CLAY	18 CT11	
- -	23	١,		25		15	46		SANDSTONE	NOR	
	122	+		120		1/5	1,0	1	0,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
		2		100	10	60,75	100	4	CLAY & SHALE	2 GP14	
: .	1								SANDSTONE 4 SINILE IN LAYERS	15 GPM	
		3		125	10	- 50,110,11.	4-	5_	SHALE AND .	15 01/11	
:	7	7		285	- 95			16	SONDSTONE	16PH	
			-	.					BLUE CLAY 4	Jacon 1	
· ·	3/	/		40	1/2	35,40	0 30	.2.2	BUE SHALE	<u> </u>	* Water bearing Zone - W.B.Z.
!						a			No.		PV U. C. or an appropriate to the second sec

GABRIOLA ISLAND WELL INVENTORY, TABLE NO. 1 - HYDROGEOLOGICAL DATA

DEPTH DESCRIPTION REPORTED REMARKS CASING WELL DEPTH WELL HEAD 5.W.L. WELL WATERSHED SECTION TO # YIEAD OF MATERIAL LENGTH ELEVATION DRILL No. W.B.Z. DUG 7 GPM SHALE 50 22 45 LOCK BAY 31 21'6" 5 GPM SHALE 3 23 27.41.55 65 11/2 .10 10 GPM 10 SHALE 4 50 176" 6 GPM SHALE 10 60 12 5 10 GPM 28.51 15 SHALE. 55 14 6 12/2 6PM 21 SHALE 26.49 15 23 7 53 18 CLAY & SHALE 5 GAY 10 8 50 20.45 CLAY & SHALE 16 GPM 9 22.40 30 10 45 10 10 70 OVER FLOIVS WINTER 15 22 // BLUE CLAY & 13 GPM 13 30 BLUE SHALE 30 25 12 CLAY AND SHALE 66 GPLY 10 27,34 13 10 14 40 HACH . 01 = 30 ppin CLAY AND SHALE 25 GRIY 14 26.33 25 40 12 10 25 15 70 BLUE CLAY 12 AND SHALE 6 6111 18.35 30 40 16 CLAY 1 SHALE 20 GPY 25 40 28 16 7 61717 30 18 35 * Water bearing Zone - W.B.Z.

`					GABRI	OLA ISA	AND WELL	. INVENT	TORY, TABLE NO.1	- HÝDROGI	EOLOGICAL DATA DEC. 1977
WATERSHED	SECTION	WELL No.	WELL DUG	DEPTH DRILL	5.W.L.	DEPTH TO # W.B.Z.	WELL HEAD ELEVATION	CASING LENGTH	DESCRIPTION OF MATERIAL .	REPORTED YIELD	REMARKS
CCK BAY	31	19		40	12	20,32	35	15	CLAY & SHALE	25 GPM	
<u> </u>		20		45	12	40	30	13	BLUE SHALE	10 GPM	
		21		65	8.	30,55	48	12	CLAY & SHALE	312 CPM	
·		22		40	8	25,35	35	14	SANISTONE TO BUYE CUTY IN JAYERS	11 GPM	HACH
		23		75			30	12	BLUE CLAY & SHALE		DEEPENED FROM 40'-7.5' IN 1971
		24		60	8	50	20	15	CLAY 9 SHALE	2/2 GM	
		25		50	7	24	20	20	SHALE	30 GP17	HACH
	:	26		40	4	25,32	30	15	CLAY & SHALE	30 600	
. •		27		40	10	32	15	15	CLAY & SHALE	6 GPM	7 0
		28		40	10	27.31.40	15	15	CLAY & SHALE	246814	
		29		95	(?) 7.5	17.38		15	SHALE AND SANDSTONE	20 6811	
		30		40	12	25,40	10.	. 18	CLAY	6/2 GPM	
		31		40	1	25,35	15	15	SANDSTONE FIND SHALE	4 GPM	
		32		75	8	17,26	15	15		2 GPM	HACH
		 						26			
	<u> </u>	33		90	12	35,40		1	CLAY & SHALE BLUE SHINE & S.S. IN LAYERS	201 660	HANH
		34	 	40	 	28,30		14_			
		35		7.5		26,65	30	10	BLUE SHALE	1 J. (J. 17)	* Water bearing Zone - W.B.Z.

GABRIOLA ISLAND WELL INVENTORY, TABLE NO. 1 - HYDROGEOLOGICAL DATA

DESCRIPTION REPORTED DEPTH WELL HEAD CASING REMARKS WELL DEPTH 5.W.L. WELL WATERSHED SECTION 70 × LENGTH OF MATERIAL YIELD ELEVATION DRILL No. DUG W.B.Z. 8 GPM CLAY & SHALE 15 12 60 50,60 36 LOCK BAY 31 125 22 37 26 LIMESTONE AND c/ 50 pm HACH 14 GPM 30 SHALF 25 15.30,75 60 75 38 CLAY + SHALE 10 GPM IN LAYERS 20.40 14 39 40 50 15 CLAY 9 SHALE 4.5 GPM 40 10 25,35 40 3 GPM 41. SHALE 52 24.48 CLAY & SHALE 15/2 IN IAYERS 40 26 30 35 42 5 GPM SHALE 47 6 44 43 BLUE SHALE 11 GPM 44 42 50 SHALE & CLAY 10 GPM IN INYERS 44,50 45 25 50 12 GPM BLUE CLAY 32 20 46 40 BLIJE CLAY Y 2 GPM 14 BILLE SHALE 47 40.50 50 25 9 614 15. 30,35 SHALE 48 40 10 19 BLUE SHALE 20 GPM 50 1830.45 49 10 BLUE CLAYY STALE IN LAYERS 15 GAY 15 30 -5. 20 50 SIPIE & CLAY 25 6/14 IN INYEPS 40 12 30,35 15 5% JIME Y CLAY 20: IN IDYFRS 8 6/11 *3*5 22 52 12 * Water bearing Zone - W.B.Z.

VATERSHED	SECTION	WELL		DEPTH	5.W.L.	DEPTH To *	WELL HEAD	CASING LENGTH	DESCRIPTION OF MATERIAL	REPORTED YIELD	PEMARKS
		<i>No.</i>	DUG	DRILL		W.8.Z.	ELEVATION	LENGTH		772.22	
ick BAY	3/	5.3		60	15	55 <u>.</u>		3	VERY HAPO STONE	7 GPM	
CCCC ST.		54		90	12	65,8090		5_	BLUE CLAY 4 BLUE SHALE	2 GPM	
		55		150	60	144		5	CLUE CLAY & SHALE IN LAHERS	,5 GP/	
		56		70	6	62		7	SHALE & SAND STONE IN LAYERS	1.5 GPM	V
	·	57		60	15	37,54		20	BIUE SHALE	9 GPM	V .
		58		40	15	2332		14.	BLUE CLAY & BLUE SHALE	17 GPM	
		59		80	20	53,74	•.	16	BLUE SHALE	1/2 GPM	
	· ·	60		50	24	44		22	BIUF SHALE	11 GPM	
		61		45	12	37		16	BLUE SHALE	12GPM	. 4
		62		80	15	42.64.7.	3	2/	BLUE SHALE	5 GAY	
		63		75		43.69		16	BLUE SHALE	15 GP14	
		64		100	15	27,94		24	BLUE SHALE	3/2 CAPP	
				75	10	47.68		27	BLUE SHALE	5 GARY	
	 	65	-			T .					
		66		55	20	41,49	ļ	14	BLUE SHALE	25 GF14	
		67		80	14	57.80		12	BLUE SHALE T	1 GP14	
		68		25							1401146
		:-9	,	45	7	25,37		20	BUE SHALE	20011	
i		1	1	1	1	1					* Water bearing Zone - W.B.Z.

Commings	TOLAND	WELL INVENTORY.	TABLE	No.1 -	HYDROGEOLOGICAL DATA

		WELL	WELL	DEPTH	5.W.L.	DEPTH TO #	WELL HEAD		DESCRIPTION	REPORTED	REMARKS
TERSHED	ECTION	No.	DUG	DRILL		W.B.Z.	ELEVATION.	LENGTH	OF MATERIAL	YIELD	
CK BAY	3/	70		45	6	22,39		216"	SHALE	5/2 697	
CK DAY	<i></i>	71		45		33,37		21	BLUE CLAY AND BLUE CLAY IN LAYERS	7 GPM	
		72		60	1	20,45 30		18	SHALE 4 CLAY IN TAYERS	16 GPM	
		7.3		45	8	2538		2.3	BULE SHALE	12 GPM	
	•	. 74		50	R	45		18	BLUE SHALE	15 GPM	
		75		45	5	25		24	BLUE SHALE	46914	
		76		50	8	20,40		16	CLAY & SHALE IN LAYERS	21 6917	
		77		75		75		15		2 GAM	
-		78		70	20	50,60.70		5	HARD SANDSTONE	5 GPM	3
		79		55	14	35.45		17	CLAY AND SHALE IN LAYERS	12 GPM	
		80		65	20	55		28	CHALE & CLAY	1/2 6117	
•		8/		. 95	10	80		41/2	SANDSTONE	5 GPM	
			 	75		65		27	BLUE SHALE	2/26/17	
		82			5	20,80		13	SANDSTONE AND STALE IN LAYERS	10 GMY	
,	-	83		90	9	45,52		12	BLUE SHALE	15 691	
		34	•	60		105		6	BLUE SHALE	8 GP14	
·	 	85	-	1/5	3			. 10	SANDSTONE	1/2 6174	
		86		91	- 0	50,80	· 1				* Water bearing Zone - W.B.Z.

VATERSHED	SECTION	WELL No.	WELL DUG	DEPTH. DRÍLL	5.W.L.	DEFTH TO * W.B.Z.	WELL HEAD ELEVATION		DESCRIPTION OF MATERIAL	REPORTED YIELD	REMARKS
LCCK BAY	31	87	,	55	19	45		13.	CLAY Y SHALE IN LAYERS	6 GPM	
200,0077		28		60	15	.39		16'4"	SHALE	1 GPM	
		89		90	25	38		2110"	SHALE	3/4 6/14	
		90		65	12	55		2/2"	SHALE	10 GPM	
*											*
. <u></u>											
								, .			
		•									
. •											
* ·		. :			1						
			 			<u>'</u>	-				
				-	· · · · · ·						
		1									
		<u> </u>	-		 						
	-		 		 		 				
	-	-	 				 	_			
	·	<u> </u>		-	-		<u> </u>				* Water bearing Zone - W.B.Z.

GABRIOLA ISLAND WELL INVENTORY, TABLE NO. 1 - HYDROGEOLOGICAL DATA

ATERSHED.	SECTION	WELL	WELL		5.W.L.	DEPTH TO *	WELL HEAD	CASING	DESCRIPTION	REPORTED	REMARKS
		No.	DUG	DRILL		W.B.Z.	ELEVATION	LENGTH	OF MATERIAL		
BAY	12	/	8		4		280		SANDSTONE	SUMY	
3).	/~	 		60	30	55	275	2		10 GAY	HACH PINALYSIS
		.3		50		20-40	<i>ź75</i>	30"	SHALE AND SANDSTONE	12 GP14	
		7	-	90		75,82	325	4/2	CONGLEMERATE	20 GPM	
			1.	125	6	50	032	10	SHOUSTONE AND SHOUE IN LAYERS	50 GPM	
		2/	 	T	0	80,125		5	SANDSTONE SUE		DRY WELL
,		22	-	200	9	68		10	VERY MAKE SANDSTONE	1/2 GPM	
· .		26		100	 	1		5	BLUE SANDSTONE	1 GPM	
		29		85	13_	74			BLUE CLAY	10 GP14	
		36	 	100	6	15,030	7 <u> </u>	7	AND SHALE HARD		
	ļ	40	-	/35	5	121		10	SANDSTONE MARD	12 GP14	
		47		125	10	115		9	SYNDSTONE GREY	12 GPM	
		48		175	40	80,165		4	SANDSTONE	1 GPM	
		49		135	20	125		6	BLLE SHALE	JO GAY	
· · · · · · · · · · · · · · · · · · ·		50	1	92	15	75	-	6	SHALE AND SANDSTONE IN LAYERS	10 arty	
	-	100	+	1.	,	10.55	250	5/2	OLCE SHILE FIND ENNIGHTENE IN LAYEKS	30 6M	
<u>.,, ., </u>	13	+/	-	60	6	7				20 00	
	-	4		90		65,85		1.2.	SHALE		
,		5_		40	10	22,33	250	1.2.	SHINDSTONE	30 am	* Water bearing Zone - W.B.Z.

•											
WATERSHED	SECTION	WELL No.	DUG	DEPTH DRILL	5.W.L.	DEPTH TO * W.B.Z.	WELL HEAD ELEVATION	LENGTH		REPORTED YIELD	REMARKS
DESCANSO BAY	13	6		60	15	15. 52.60		8	VERY UNION D-IND- BLUE SHINE	14/2 GPM	
0,77	, <u> </u>	9		90	15	82		6	BIUE SHALE	1.5 GPM	
		10		40.	10	30,32		7	SHALE NIVD SANDSTONE IN LAYERS	20 6114	ì
		. / 1		90	2	18	<u> </u>	21	OVERBURDEN ? BLUE SANDSTONE	3 GPM	
ì	·	12		80	9	17		3	GRAVEL	25 GNY	
1		/3		20	12	40,60,80	<u>}</u>	2/2	SHALE AND SANDSICNE IN LAYERS	20 GPM	
		14		65	20	50		4	SANDSTONE GREY SANDSTONE	10 GPM	
		1.5		90	12	25		8	GREY SHNDSTONE FIND HARD BLUE SHALE IN LAYERS	12 GPM	
		16		125	16	65,110		4	SANDSTONE	20GPH	74
		18		165	10	155		14	SHALEY SANDSTONE	21/2 6194	
		19		85	3	16		7	BROWN SAN'DSTONE SHALE AND CLAY	15 GNY	
	18	30		50	12	43		10	IN LAYERS	30 GPM	
		41		165	8	15.5		10	BLUE SHALE	8 6014	
:	19	2		30	15		320		BEDROCK	GCCD SUPPLY	
		3	-	7.9	-51.		300		SANDSTONE	·	1400066
: 	1	4		70	38		275	5'6"	SAND STONE	1/2 GIVY	
:	1	6		1 70	4		350	. /2 '	HARA SAKIDSTOKE	5/2 GMY	
1	-	+==	_	1	1				The second secon		* Water bearing Zone - W.B.Z.
			1								

ಶ್ರೇ 1977

		•	
		WELL INVENTORY, TABLE NO. 1: - HYDROGEOLOGICA	/ 23 A 77A
		TABLE MO 1 - HYDROGEOLOGICA	ムーンハイハ
CIMPIALA	アペノ ヘヘノフ	WEIL INVENTORY, TROLL NO. 3.	

S.W.L. DEPTH DESCRIPTION WELL HEAD CASING REFORTED HEMARKS WELL DEPTH WELL YIELD VATERSHED SECTION 70 % LENGTH OF MATERIAL ELEVATION Saje pried , elt 35-40029 W.E.Z. DRILL No. DUG 1400067 72 GPM TEST HOLE 70-3 SONDSTONE とうじわいい 305 250 65.37 19 BAY 5/2 GAM 2 SHALE 25 45,75 80 GCOO SUPPLY 26 TILL 16 20 20 GUCID SLIPPLY 1400300 SANDSTONE 173 3 SPRING GREY 12 GPM SANDSTONE 238 50 4 SHALE AND DRY HOLE 11/2 240 SANDSTONE 6 205 CLINE SHALE DRY HOLE 4/2 VAND SPNIDSTONE 230 75 DRY HOLE 3 SANOSTONE. 225 8 212 SHALE AND 4- GPH SANOSTONE 230 220 9 250 MED 3/2GPY 1400299 SANDSTONE 250 5 18,38 45 10 4 15 GAY SANDSTONE 15,60 230 70 230 12 12 VID GMY MOCH ANALYSIS 18 SHALE 250 70 81 35. 13 3/1 6011 SANDSTONE 10.60 250 14 70 * Water bearing Zone - W.B.Z.

. DEC. 1977 GABRIOLA ISLAND WELL INVENTORY, TABLE NO. 1 - HYDROGEOLOGICAL DATA WELL HEAD CASING DESCRIPTION REPORTED DEPTH TO # WELL DEPTH. REMARKS WELL 5.W.L. NATERSHED SECTION YIELD LENGTH OF MATERIAL ELEVATION 16. DRILL W.B.Z. 20:10 DESCANSO 20 BAY 1/46014 13 25 40,90 SANDSTONE 18 105 .35 GPM SANOSTONE 124,145 20 19 14.5 SHALE AND 48" SANDSTONE 10 GPM 537 140 20 18 GREY SHALE 12 GPM 23 135 30-40 125 CREY SPUDSTONE BLUE SHALE 4 12 GAY 185 24 195 BLUE CLAY AND SHALE IN IAYERS 2 GAY 8 12 195 205 25 SHALE MAID SONDSTONE VINCOSTONE VINCE W LAYELS 70001 130 42 80 21 100 12GPIY 43 100 15 30.65 4 80 26114 6 BLUE SHALE 101 216 220 60 (?) 35 6PM 4'5" SHALE 24 50 12,50 10 DRY HOLE 1410" SANDS TONE 14 157 2 5 (114 1/2 90NOSTONE 2.5 4. 195 31 * Water bearing Zone - W.B.Z.